

C11005

Diagnostic information - Headlight control unit (central)

Control module faulty

NOTE

- ♦ The lights should always be switched off before removing and installing the headlights.
- ♦ Carry out repair work on the headlight or wiring only with the component removed and separated from the voltage supply.

Diagnostic conditions

- Headlights switched on
- Ignition on

Fault setting condition(s)

- **Control module** Headlights faulty

Fault effects

- ♦ System switches off
- ♦ Display in instrument cluster

Diagnosis information - Headlight control unit (central)

Control module , not coded

Control module , incorrectly coded

NOTE

- ♦ The lights should always be switched off before removing and installing the headlights.
- ♦ Carry out repair work on the headlight or wiring only with the component removed and separated from the voltage supply.

Diagnostic conditions

- Ignition on

Possible fault causes

- ♦ Headlight control unit (central) not coded
- ♦ Headlight control unit (central) incorrectly coded
- ♦ Headlight control unit (central) Faulty

Diagnostic information - headlight control unit (central)

Compression angle sensor (only without level control unit (PASM))

CAUTION

Danger of eye injuries due to bright light!

- ◆ Do not look directly into the light beam.

NOTE

- ◆ On vehicles with level control/PASM, the signal for the vehicle position is generated via the leveling system/PASM control unit. This has four angle sensors for compression.
- ◆ The signal values are then sent to the headlight control unit (central) via CAN
- ◆ Calibration takes place in the **leveling system control unit (PASM)**
- ◆ Calibration takes place in the headlight control unit (central) only without **level control unit (PASM)**

Diagnostic conditions

- ◆ Ignition on

Fault setting condition(s)

- ◆ **Angle sensor** calibration incorrect or not carried out
- ◆ **>Commissioning<** function under Maintenance/repairs not performed

Fault effects

- ◆ No function of headlight beam adjustment