

991 + 981 , MY 2012 =>

Diagnosis information - Headlights right side

10000.....	1
10001.....	2
10003.....	3
20000.....	4
20000.....	5
20001.....	6
20001.....	7
20002.....	8
20002.....	9
20003.....	10
20003.....	11
20005.....	12
20005.....	13
20006.....	14
20006.....	15
20007.....	16
20007.....	17
20011.....	18
20011.....	19
20020.....	20
20020.....	21
20021.....	22
20021.....	23
30000.....	24
30000.....	25
30001.....	26
30001.....	27
30002.....	28
30002.....	29
30003.....	30
30003.....	31
30004.....	32
30004.....	33
30004.....	34
30005.....	35
30005.....	36
30005.....	37
30006.....	38
30006.....	39

30011.....	40
30011.....	41
30020.....	42
30020.....	43
30021.....	44
30021.....	45
30300.....	46
30300.....	47
30301.....	48
320050.....	49
40000.....	50
40001.....	51
40002.....	52
40003.....	53
40004.....	54
40005.....	55
40006.....	56
40011.....	57
40020.....	58
40021.....	59
40300.....	60
40301.....	61
40400.....	62
50000.....	63
50002.....	64
50002.....	65
50002.....	66
50003.....	67
50100.....	68
50101.....	69
50200.....	70
60000.....	71
80510E.....	73
C058.....	74

Diagnostic information - Headlights

Control module Power supply

WARNING

HBA Xenon: Electric shock and burns from high voltage.

- ◆ The lights should always be switched off before removing and installing the headlights.
- ◆ Only operate the gas-discharge lamp when installed in the headlight.
- ◆ Carry out repair work on the headlight or wiring only with the component removed and separated from the voltage supply.

Diagnostic conditions

- Headlights switched on
- Ignition on

Fault setting condition(s)

- **Control module** Headlights **Power supply**
- Signal Terminal 15
- Signal Terminal 56b

Fault effects

- ◆ System switches off, Headlights **OFF**
- ◆ Display in instrument cluster

Diagnostic information - Headlights

Control module Power supply

WARNING

HBA Xenon: Electric shock and burns from high voltage.

- ◆ The lights should always be switched off before removing and installing the headlights.
- ◆ Only operate the gas-discharge lamp when installed in the headlight.
- ◆ Carry out repair work on the headlight or wiring only with the component removed and separated from the voltage supply.

Diagnostic conditions

- Headlights switched on
- Ignition on

Fault setting condition(s)

- **Control module** Headlights **Power supply**
- Signal Terminal 15
- Signal Terminal 56b

Fault effects

- ◆ System switches off, Headlights **OFF**
- ◆ Display in instrument cluster

Diagnostic information - Headlight control unit

Control unit, coded incorrectly

CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas-discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight control unit coded incorrectly
- Ignition on

Possible fault causes

- ◆ Line connection from **headlight** control unit to headlight housing connector faulty
- ◆ Wiring at headlight control unit connector Pin 5 and Pin 6 interchanged
- ◆ Headlight control unit faulty

HBA stepper motor



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ Line connection or contacts to HBA servo motor faulty
- ◆ HBA stepper motor overheated
- ◆ HBA stepper motor mechanically blocked
- ◆ HBA stepper motor faulty
- ◆ **Headlight** control unit coded incorrectly

Stepper motor HBA switched off



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ HBA stepper motor version is not supported by control unit
- ◆ HBA stepper motor switched off due to overtemperature
- ◆ Supply voltage too low
- ◆ Headlight control unit wrong software version

HBA stepper motor



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ Line connection or contacts to HBA servo motor faulty
- ◆ HBA stepper motor overheated
- ◆ HBA stepper motor mechanically blocked
- ◆ HBA stepper motor faulty
- ◆ **Headlight** control unit coded incorrectly

Stepper motor HBA switched off



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ HBA stepper motor version is not supported by control unit
- ◆ HBA stepper motor switched off due to overtemperature
- ◆ Supply voltage too low
- ◆ Headlight control unit wrong software version

HBA stepper motor



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ Line connection or contacts to HBA servo motor faulty
- ◆ HBA stepper motor overheated
- ◆ HBA stepper motor mechanically blocked
- ◆ HBA stepper motor faulty
- ◆ **Headlight** control unit coded incorrectly

Stepper motor HBA switched off



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ HBA stepper motor version is not supported by control unit
- ◆ HBA stepper motor switched off due to overtemperature
- ◆ Supply voltage too low
- ◆ Headlight control unit wrong software version

HBA stepper motor



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ Line connection or contacts to HBA servo motor faulty
- ◆ HBA stepper motor overheated
- ◆ HBA stepper motor mechanically blocked
- ◆ HBA stepper motor faulty
- ◆ **Headlight** control unit coded incorrectly

Stepper motor HBA switched off



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ HBA stepper motor version is not supported by control unit
- ◆ HBA stepper motor switched off due to overtemperature
- ◆ Supply voltage too low
- ◆ Headlight control unit wrong software version

HBA stepper motor



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ Line connection or contacts to HBA servo motor faulty
- ◆ HBA stepper motor overheated
- ◆ HBA stepper motor mechanically blocked
- ◆ HBA stepper motor faulty
- ◆ **Headlight** control unit coded incorrectly

Stepper motor HBA switched off



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ HBA stepper motor version is not supported by control unit
- ◆ HBA stepper motor switched off due to overtemperature
- ◆ Supply voltage too low
- ◆ Headlight control unit wrong software version

HBA stepper motor



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ Line connection or contacts to HBA servo motor faulty
- ◆ HBA stepper motor overheated
- ◆ HBA stepper motor mechanically blocked
- ◆ HBA stepper motor faulty
- ◆ **Headlight** control unit coded incorrectly

Stepper motor HBA switched off



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ HBA stepper motor version is not supported by control unit
- ◆ HBA stepper motor switched off due to overtemperature
- ◆ Supply voltage too low
- ◆ Headlight control unit wrong software version

HBA stepper motor



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ Line connection or contacts to HBA servo motor faulty
- ◆ HBA stepper motor overheated
- ◆ HBA stepper motor mechanically blocked
- ◆ HBA stepper motor faulty
- ◆ **Headlight** control unit coded incorrectly

Stepper motor HBA switched off



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ HBA stepper motor version is not supported by control unit
- ◆ HBA stepper motor switched off due to overtemperature
- ◆ Supply voltage too low
- ◆ Headlight control unit wrong software version

HBA stepper motor



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ Line connection or contacts to HBA servo motor faulty
- ◆ HBA stepper motor overheated
- ◆ HBA stepper motor mechanically blocked
- ◆ HBA stepper motor faulty
- ◆ **Headlight** control unit coded incorrectly

Stepper motor HBA switched off



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ HBA stepper motor version is not supported by control unit
- ◆ HBA stepper motor switched off due to overtemperature
- ◆ Supply voltage too low
- ◆ Headlight control unit wrong software version

HBA stepper motor



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ Line connection or contacts to HBA servo motor faulty
- ◆ HBA stepper motor overheated
- ◆ HBA stepper motor mechanically blocked
- ◆ HBA stepper motor faulty
- ◆ **Headlight** control unit coded incorrectly

Stepper motor HBA switched off



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ HBA stepper motor version is not supported by control unit
- ◆ HBA stepper motor switched off due to overtemperature
- ◆ Supply voltage too low
- ◆ Headlight control unit wrong software version

HBA stepper motor



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ Line connection or contacts to HBA servo motor faulty
- ◆ HBA stepper motor overheated
- ◆ HBA stepper motor mechanically blocked
- ◆ HBA stepper motor faulty
- ◆ **Headlight** control unit coded incorrectly

Stepper motor HBA switched off



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or the wiring when the part is removed and disconnected from the power supply.

Diagnostic conditions

- Headlight (xenon) control unit internal function test
- Ignition on

Possible fault causes

- ◆ HBA stepper motor version is not supported by control unit
- ◆ HBA stepper motor switched off due to overtemperature
- ◆ Supply voltage too low
- ◆ Headlight control unit wrong software version

Diagnostic information - Headlight control unit

Stepper motor for dyn. cornering light switched off

CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas-discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or wiring when the part is removed and disconnected from the power supply.

INFORMATION

The stepper motor/servo motor for the dynamic cornering light and its mechanical components and wiring cannot be replaced individually.
The headlight housing must be replaced if repairs are needed.

Diagnostic conditions

- Internal function test on headlight (Xenon) control unit
- Ignition on

Possible fault causes

- ◆ Mechanism of stepper motor for dyn. cornering light sluggish or blocked
- ◆ Dynamic cornering light wiring faulty
- ◆ Stepper motor for dynamic cornering light faulty
- ◆ Headlight control unit faulty

Diagnostic information - Headlight control unit

Stepper motor for dyn. cornering light, position sensor

CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas-discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or wiring when the part is removed and disconnected from the power supply.

INFORMATION

The stepper motor/servo motor for the dynamic cornering light and its mechanical components and wiring cannot be replaced individually.
The headlight housing must be replaced if repairs are needed.

Diagnostic conditions

- Internal function test on headlight (Xenon) control unit
- Ignition on

Possible fault causes

- ◆ Mechanism of stepper motor for dyn. cornering light sluggish or blocked
- ◆ Dynamic cornering light wiring faulty
- ◆ Stepper motor for dynamic cornering light faulty
- ◆ Headlight control unit faulty

Diagnostic information - Headlight control unit

Stepper motor for dyn. cornering light switched off

CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas-discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or wiring when the part is removed and disconnected from the power supply.

INFORMATION

The stepper motor/servo motor for the dynamic cornering light and its mechanical components and wiring cannot be replaced individually.
The headlight housing must be replaced if repairs are needed.

Diagnostic conditions

- Internal function test on headlight (Xenon) control unit
- Ignition on

Possible fault causes

- ◆ Mechanism of stepper motor for dyn. cornering light sluggish or blocked
- ◆ Dynamic cornering light wiring faulty
- ◆ Stepper motor for dynamic cornering light faulty
- ◆ Headlight control unit faulty

Diagnostic information - Headlight control unit

Stepper motor for dyn. cornering light, position sensor



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas-discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or wiring when the part is removed and disconnected from the power supply.



INFORMATION

The stepper motor/servo motor for the dynamic cornering light and its mechanical components and wiring cannot be replaced individually.
The headlight housing must be replaced if repairs are needed.

Diagnostic conditions

- Internal function test on headlight (Xenon) control unit
- Ignition on

Possible fault causes

- ◆ Mechanism of stepper motor for dyn. cornering light sluggish or blocked
- ◆ Dynamic cornering light wiring faulty
- ◆ Stepper motor for dynamic cornering light faulty
- ◆ Headlight control unit faulty

Diagnostic information - Headlight control unit

Stepper motor for dyn. cornering light switched off

CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas-discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or wiring when the part is removed and disconnected from the power supply.

INFORMATION

The stepper motor/servo motor for the dynamic cornering light and its mechanical components and wiring cannot be replaced individually.
The headlight housing must be replaced if repairs are needed.

Diagnostic conditions

- Internal function test on headlight (Xenon) control unit
- Ignition on

Possible fault causes

- ◆ Mechanism of stepper motor for dyn. cornering light sluggish or blocked
- ◆ Dynamic cornering light wiring faulty
- ◆ Stepper motor for dynamic cornering light faulty
- ◆ Headlight control unit faulty

Diagnostic information - Headlight control unit

Stepper motor for dyn. cornering light, position sensor

CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas-discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or wiring when the part is removed and disconnected from the power supply.

INFORMATION

The stepper motor/servo motor for the dynamic cornering light and its mechanical components and wiring cannot be replaced individually.
The headlight housing must be replaced if repairs are needed.

Diagnostic conditions

- Internal function test on headlight (Xenon) control unit
- Ignition on

Possible fault causes

- ◆ Mechanism of stepper motor for dyn. cornering light sluggish or blocked
- ◆ Dynamic cornering light wiring faulty
- ◆ Stepper motor for dynamic cornering light faulty
- ◆ Headlight control unit faulty

Diagnostic information - Headlight control unit

Stepper motor for dyn. cornering light switched off

CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas-discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or wiring when the part is removed and disconnected from the power supply.

INFORMATION

The stepper motor/servo motor for the dynamic cornering light and its mechanical components and wiring cannot be replaced individually.
The headlight housing must be replaced if repairs are needed.

Diagnostic conditions

- Internal function test on headlight (Xenon) control unit
- Ignition on

Possible fault causes

- ◆ Mechanism of stepper motor for dyn. cornering light sluggish or blocked
- ◆ Dynamic cornering light wiring faulty
- ◆ Stepper motor for dynamic cornering light faulty
- ◆ Headlight control unit faulty

Diagnostic information - Headlight control unit

Stepper motor for dyn. cornering light, position sensor

CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas-discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or wiring when the part is removed and disconnected from the power supply.

INFORMATION

The stepper motor/servo motor for the dynamic cornering light and its mechanical components and wiring cannot be replaced individually.
The headlight housing must be replaced if repairs are needed.

Diagnostic conditions

- Internal function test on headlight (Xenon) control unit
- Ignition on

Possible fault causes

- ◆ Mechanism of stepper motor for dyn. cornering light sluggish or blocked
- ◆ Dynamic cornering light wiring faulty
- ◆ Stepper motor for dynamic cornering light faulty
- ◆ Headlight control unit faulty

Diagnostic information - Headlight control unit

Stepper motor, dyn. cornering light, version conflict

CAUTION

Danger of injury from high voltage!

- ♦ The light must always be switched off when removing and installing the headlights.
- ♦ The gas-discharge lamp may only be operated when installed in the headlight.
- ♦ Only carry out repairs to the headlight or wiring when the part is removed and disconnected from the power supply.

INFORMATION

- ♦ Software for the stepper motor does not match software for the control unit; software versions are not compatible.
- ♦ The stepper motor/servo motor for the dynamic cornering light and its mechanical components and wiring cannot be replaced individually.
The headlight housing must be replaced if repairs are needed.

Diagnostic conditions

- Internal function test on headlight (Xenon) control unit
- Ignition on

Possible fault causes

- ♦ Software version of stepper motor is not supported by control unit
- ♦ Stepper motor for dynamic cornering light faulty
- ♦ Headlight control unit has wrong software version
- ♦ Headlight control unit faulty

Diagnostic information - Headlight control unit

Stepper motor for dyn. cornering light switched off

CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas-discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or wiring when the part is removed and disconnected from the power supply.

INFORMATION

The stepper motor/servo motor for the dynamic cornering light and its mechanical components and wiring cannot be replaced individually.
The headlight housing must be replaced if repairs are needed.

Diagnostic conditions

- Internal function test on headlight (Xenon) control unit
- Ignition on

Possible fault causes

- ◆ Mechanism of stepper motor for dyn. cornering light sluggish or blocked
- ◆ Dynamic cornering light wiring faulty
- ◆ Stepper motor for dynamic cornering light faulty
- ◆ Headlight control unit faulty

Diagnostic information - Headlight control unit

Stepper motor for dyn. cornering light, position sensor



CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas-discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or wiring when the part is removed and disconnected from the power supply.



INFORMATION

The stepper motor/servo motor for the dynamic cornering light and its mechanical components and wiring cannot be replaced individually.
The headlight housing must be replaced if repairs are needed.

Diagnostic conditions

- Internal function test on headlight (Xenon) control unit
- Ignition on

Possible fault causes

- ◆ Mechanism of stepper motor for dyn. cornering light sluggish or blocked
- ◆ Dynamic cornering light wiring faulty
- ◆ Stepper motor for dynamic cornering light faulty
- ◆ Headlight control unit faulty

Diagnostic information - Headlight control unit

Stepper motor, dyn. cornering light, version conflict

CAUTION

Danger of injury from high voltage!

- ♦ The light must always be switched off when removing and installing the headlights.
- ♦ The gas-discharge lamp may only be operated when installed in the headlight.
- ♦ Only carry out repairs to the headlight or wiring when the part is removed and disconnected from the power supply.

INFORMATION

- ♦ Software for the stepper motor does not match software for the control unit; software versions are not compatible.
- ♦ The stepper motor/servo motor for the dynamic cornering light and its mechanical components and wiring cannot be replaced individually.
The headlight housing must be replaced if repairs are needed.

Diagnostic conditions

- Internal function test on headlight (Xenon) control unit
- Ignition on

Possible fault causes

- ♦ Software version of stepper motor is not supported by control unit
- ♦ Stepper motor for dynamic cornering light faulty
- ♦ Headlight control unit has wrong software version
- ♦ Headlight control unit faulty

Diagnostic information - Headlight control unit

Stepper motor for dyn. cornering light switched off

CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas-discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or wiring when the part is removed and disconnected from the power supply.

INFORMATION

The stepper motor/servo motor for the dynamic cornering light and its mechanical components and wiring cannot be replaced individually.
The headlight housing must be replaced if repairs are needed.

Diagnostic conditions

- Internal function test on headlight (Xenon) control unit
- Ignition on

Possible fault causes

- ◆ Mechanism of stepper motor for dyn. cornering light sluggish or blocked
- ◆ Dynamic cornering light wiring faulty
- ◆ Stepper motor for dynamic cornering light faulty
- ◆ Headlight control unit faulty

Diagnostic information - Headlight control unit

Stepper motor for dyn. cornering light, position sensor

CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas-discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or wiring when the part is removed and disconnected from the power supply.

INFORMATION

The stepper motor/servo motor for the dynamic cornering light and its mechanical components and wiring cannot be replaced individually.

The headlight housing must be replaced if repairs are needed.

Diagnostic conditions

- Internal function test on headlight (Xenon) control unit
- Ignition on

Possible fault causes

- ◆ Mechanism of stepper motor for dyn. cornering light sluggish or blocked
- ◆ Dynamic cornering light wiring faulty
- ◆ Stepper motor for dynamic cornering light faulty
- ◆ Headlight control unit faulty

Diagnostic information - Headlight control unit

Stepper motor for dyn. cornering light switched off

CAUTION

Danger of injury from high voltage!

- ◆ The light must always be switched off when removing and installing the headlights.
- ◆ The gas-discharge lamp may only be operated when installed in the headlight.
- ◆ Only carry out repairs to the headlight or wiring when the part is removed and disconnected from the power supply.

INFORMATION

The stepper motor/servo motor for the dynamic cornering light and its mechanical components and wiring cannot be replaced individually.
The headlight housing must be replaced if repairs are needed.

Diagnostic conditions

- Internal function test on headlight (Xenon) control unit
- Ignition on

Possible fault causes

- ◆ Mechanism of stepper motor for dyn. cornering light sluggish or blocked
- ◆ Dynamic cornering light wiring faulty
- ◆ Stepper motor for dynamic cornering light faulty
- ◆ Headlight control unit faulty