

	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

**** ON A/C FSN ALL**

TASK 24-00-00-810-818-A

System Reset Guidelines

1. Possible Causes:

2. Job Set-up Information



A. Referenced Information

REFERENCE	DESIGNATION
Ref. AMM 10-11-00-555-014	Removal of the Aircraft Protection Equipment
Ref. AMM 31-39-00-040-805	Deactivation of the Emergency Locator Transmitter - Distress Tracking (ELT-DT) for Manitenance
Ref. AMM 31-39-00-440-805	Reactivation of the Emergency Locator Transmitter - Distress Tracking (ELT-DT) After Maintenance

3. Fault Confirmation

SUBTASK 24-00-00-710-059-A

A. Test

(1) Not applicable

4. Fault Isolation

SUBTASK 24-00-00-810-069-A

A. System Reset Procedure

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW/MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- (1) The aim of this task is to provide guidelines for system reset and table further to fault indication due to transient or intermittent failure.
 - (a) If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed according to the following guidelines:
 - for the affected computers listed in the reset table: a reset is authorized only for the listed ECAM alerts or system malfunctions
 - for all other computers: there is no restriction.
 - (b) If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- 1 if an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed
 - 2 if no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed according to the following guidelines:
 - for the affected computers listed in the reset table: a reset is authorized only for the listed ECAM alerts or system malfunctions
 - for all other computers: there is no restriction.
- (2) To do system reset:
- (a) Set the related normal cockpit control to OFF, or open the related circuit breaker as specified in the reset procedure.
 - (b) Wait 3 seconds if a normal cockpit control is used, or 5 seconds if a circuit breaker is used (unless a different time is indicated).
 - (c) Set the related normal cockpit control to ON, or close the related circuit breaker.
 - (d) Wait 3 seconds for the end of the reset.

SUBTASK 24-00-00-868-24T-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- B. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
 If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR PACK 1 OVHT	ACSC	Refer to ECAM procedure.

SUBTASK 24-00-00-868-27Q-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- C. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR PACK 2 OVHT	ACSC	Refer to ECAM procedure.

SUBTASK 24-00-00-868-24U-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- D. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR PACK 1 OVHT	Pack Controller 1(2)	Refer to ECAM procedure.

SUBTASK 24-00-00-868-27R-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- E. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:

- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
- If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR PACK 2 OVHT	Pack Controller 1(2)	Refer to ECAM procedure.

SUBTASK 24-00-00-868-25A-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- F. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	VENT AVNCS CTL FAULT	iAEVS	Not permitted.

SUBTASK 24-00-00-868-089-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- G. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
-

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	VENT AVNCS SYS FAULT	AEVC	Open the C/B 3HQ. After 5 seconds, close the C/B 3HQ.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
122VU	AIR COND/AVNCS/VENT/MONG	3HQ	Y17

SUBTASK 24-00-00-868-24V-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- H. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	VENT BKUP VALVE FAULT	iAEVS	Not permitted.

SUBTASK 24-00-00-868-24W-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

J.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:

- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
- If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	VENT BLOWER FAN FAULT	iAEVS	Not permitted.

SUBTASK 24-00-00-868-25B-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- K. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	VENT BLOWER FAULT	AEVC	Refer to ECAM procedure.

SUBTASK 24-00-00-868-24X-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- L. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
- If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	VENT EXTRACT FAULT	AEVC	Refer to ECAM procedure.

SUBTASK 24-00-00-868-24Y-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- M. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	VENT INBD VALVE FAULT	iAEVS	Not Permitted.

SUBTASK 24-00-00-868-24Z-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- N. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

--	--	--	--

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	VENT OVBD VALVE FAULT	iAEVS	Not Permitted.

SUBTASK 24-00-00-868-250-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- P. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	VENT PRESS SENSOR FAULT	iAEVS	Not permitted.

SUBTASK 24-00-00-868-251-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- Q. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	VENT SKIN VALVE FAULT	AEVC	Refer to ECAM procedure.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

SUBTASK 24-00-00-868-252-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- R. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	VENT GND COOL FAULT	AEVC	Refer to ECAM procedure.

SUBTASK 24-00-00-868-253-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- S. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	CAB PR EXCES RESIDUAL PR	CPC	Not Permitted.

SUBTASK 24-00-00-868-254-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- T. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	CAB PR EXCESS CAB ALT	CPC	Not Permitted.

SUBTASK 24-00-00-868-255-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- U. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	CAB PR LDG ELEV FAULT	CPC	Refer to ECAM procedure.

SUBTASK 24-00-00-868-256-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- V. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	CAB PR LO DIFF PR	CPC	Not Permitted.

SUBTASK 24-00-00-868-257-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- W. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
TBD	CAB PR OFV NOT OPEN	CPC	Not Permitted.

SUBTASK 24-00-00-868-258-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- X. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
- If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	CAB PR OUTFLOW VALVE NOT OPEN	CPC	Not Permitted.

SUBTASK 24-00-00-868-259-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- Y. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	CAB PR SAFETY VALVE OPEN	CPC	Not Permitted.

SUBTASK 24-00-00-868-079-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AA. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 -

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	CAB PR SYS 1 FAULT	CPC	For CPC 1: - Open the C/B 1HL, - After 5 seconds, close the C/B 1HL. For CPC 2: - Open the C/B 2HL, - After 5 seconds, close the C/B 2HL.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
49VU	AIR COND/CAB/PRESS/CTL1	1HL	D09
122VU	AIR COND/CAB PRESS/CTL/2	2HL	Y22

SUBTASK 24-00-00-868-27P-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AB. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	CAB PR SYS 2 FAULT	CPC	For CPC 1: - Open the C/B 1HL, - After 5 seconds, close the C/B 1HL. For CPC 2: - Open the C/B 2HL,

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

		- After 5 seconds, close the C/B 2HL.
--	--	---------------------------------------

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
49VU	AIR COND/CAB/PRESS/CTL1	1HL	D09
122VU	AIR COND/CAB PRESS/CTL/2	2HL	Y22

SUBTASK 24-00-00-868-25C-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AC. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	CAB PR SYS 1+2 FAULT	CPC	Not Permitted.

SUBTASK 24-00-00-868-25D-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AD. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR AFT CRG VENT FAULT	ACSC / ZC	Not Permitted.

SUBTASK 24-00-00-868-25E-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AE. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
 If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR FWD CRG VENT FAULT	ACSC / ZC	Not Permitted.

SUBTASK 24-00-00-868-25F-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AF. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
 If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND AFT CARGO DUCT OVHT	Cargo Heat controller (CHC)	Refer to ECAM procedure.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

**** ON A/C FSN 378-379, 611-611, 651-700, 725-725
POST SB 21-1215 for A/C 731-731**

SUBTASK 24-00-00-868-25G-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AG. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND AFT CRG HEAT FAULT	Cargo Heat controller (CHC)	Open C/B 31HN. After 3 seconds, close C/B 31HN.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
49VU	AIR COND/AFT CARGO/VENT & HTG /CTL & MONG	31HN	C07

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-25H-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AH. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
-

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
- If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND AFT CRG ISOL VALVE	Cargo Heat controller (CHC)	Not Permitted.

SUBTASK 24-00-00-868-25I-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AJ. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND FWD CARGO DUCT OVHT	Cargo Heat controller (CHC)	Refer to ECAM procedure.

SUBTASK 24-00-00-868-25K-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AK. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND FWD CRG ISOL VALVE	Cargo Heat controller (CHC)	Not Permitted.

SUBTASK 24-00-00-868-25L-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AL. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	FUEL INERTING SYS FAULT	CCU	Not Permitted.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
-------	-------------	-----	----------

**** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 251-300, 351-352, 356-356, 358-358, 401-401, 403-405, 408-408, 415-416, 418-418, 420-420, 423-423, 427-428, 430-433, 435-450, 851-876, 882-908, 911-925, 930-951, 953-955**



EMB SB 21-1047 for A/C 001-009
EMB SB 21-1175 for A/C 435-436

49VU	AIR COND/AFT CARGO/VENT/CTL & MONG	31HN	C07
------	------------------------------------	------	-----

**** ON A/C FSN 751-800**

49VU	AIR COND/AFT CARGO/VENT/CTL	31HN	C07
------	-----------------------------	------	-----

**** ON A/C FSN 378-379, 611-611, 651-700, 725-725**
POST SB 21-1215 for A/C 731-731

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

49VU	AIR COND/AFT CARGO/VENT & HTG /CTL & MONG	31HN	C07
------	--	------	-----

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-25M-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AM. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR COND CTL 1 FAULT	ACSC	Not Permitted.

SUBTASK 24-00-00-868-25N-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AN. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR COND CTL 1-A FAULT	ACSC	Not Permitted.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

SUBTASK 24-00-00-868-25O-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AP. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR COND CTL 1-B FAULT	ACSC	Not Permitted.

SUBTASK 24-00-00-868-25P-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AQ. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR COND CTL 2 FAULT	ACSC	Not Permitted.

SUBTASK 24-00-00-868-25Q-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AR. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR COND CTL 2-A FAULT	ACSC	Not Permitted.

SUBTASK 24-00-00-868-25R-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AS. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR COND CTL 2-B FAULT	ACSC	Not Permitted.

SUBTASK 24-00-00-868-25S-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- AT. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR PACK 1 FAULT	Pack Controller 1(2)	Not Permitted.

SUBTASK 24-00-00-868-25T-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AU. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR PACK 1 FAULT	ACSC	Not Permitted.

SUBTASK 24-00-00-868-25U-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AV. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:

- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
- If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR PACK 1 FAULT // AIR SYS CTL FAULT	Pack Controller 1(2)	Not Permitted.

SUBTASK 24-00-00-868-25V-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AW. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR PACK 1 FAULT // AIR SYS CTL FAULT	ACSC	Not Permitted.

SUBTASK 24-00-00-868-25W-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AX. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
- If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR PACK 1 OFF	Pack Controller 1(2)	Not Permitted.

SUBTASK 24-00-00-868-25X-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- AY. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR PACK 1 OFF	ACSC	Not Permitted.

**** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999**

SUBTASK 24-00-00-868-088-C

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BA. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR PACK 1 REGUL FAULT AIR PACK 2 REGUL FAULT	AIR COND SYSTEM (ACSC (Air-Conditioning System Controller))	# PACK 1&2.....OFF. - Check that both Pack Flow Control Valves are closed on the BLEED SD page. # Open C/Bs 55HH and 53HH. # Open C/Bs 51HH and 49HH. # Open C/Bs 50HH, 54HH and 56HH. # Open C/B 52HH. # Wait 10 seconds. - Close C/Bs 50HH, 54HH, and 56HH. # Close C/Bs 51HH and 49HH. # Close C/Bs 55HH and 53HH. # Close C/B 52HH. # PACK 1&2.....ON. NOTE: During the reset, a small increase of the engine thrust may be observed (N1 or EPR, as applicable). If the parking brake is set, vibrations can occur.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
49VU	AIR COND/TEMP CTL/SYS 1 CHAN B /28VDC	52HH	D08
122VU	AIR COND/TEMP CTL SYS 2/CHAN A /115VAC	53HH	W22
122VU	AIR COND/TEMP CTL SYS 2/CHAN A /28VDC	55HH	W21
122VU	AIR COND/TEMP CTL SYS 1/CHAN A /115VAC	49HH	X22
122VU	AIR COND/TEMP CTL SYS 1/CHAN A /28VDC	51HH	X21
122VU	AIR COND/TEMP CTL SYS 2/CHAN B /28VDC	56HH	Y21
	AIR COND/TEMP CTL SYS 2/CHAN B		

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

122VU	/115VAC	54HH	Y20
122VU	AIR COND/TEMP CTL SYS 1/CHAN B /115VAC	50HH	Y18

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-25Y-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BB. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR PACK 1+2 FAULT	ACSC	Not Permitted.

SUBTASK 24-00-00-868-25Z-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BC. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR PACK 2 FAULT	ACSC	Not Permitted.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

SUBTASK 24-00-00-868-260-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BD. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR PACK 2 FAULT // AIR SYS CTL FAULT	ACSC	Not Permitted.

SUBTASK 24-00-00-868-261-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BE. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR PACK 2 OFF	ACSC	Not Permitted.

SUBTASK 24-00-00-868-262-A

CAUTION:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BF. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND	Pack Controller 1(2)	Not Permitted.

SUBTASK 24-00-00-868-263-A

CAUTION: **DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:**

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BG. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND	ACSC	Not Permitted.

SUBTASK 24-00-00-868-264-A

CAUTION: **DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:**

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BH. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND AFT CAB DUCT OVHT	Pack Controller 1(2)	Refer to ECAM procedure.

SUBTASK 24-00-00-868-265-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BJ. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND AFT CAB DUCT OVHT	ACSC	Refer to ECAM procedure.

SUBTASK 24-00-00-868-266-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BK. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
 If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND CKPT DUCT OVHT	Pack Controller 1(2)	Refer to ECAM procedure.

SUBTASK 24-00-00-868-267-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BL. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
 If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND CKPT DUCT OVHT	ACSC	Refer to ECAM procedure.

SUBTASK 24-00-00-868-268-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

BM.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:

- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
- If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND FWD CAB DUCT OVHT	Pack Controller 1(2)	Refer to ECAM procedure.

SUBTASK 24-00-00-868-269-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BN. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND FWD CAB DUCT OVHT	ACSC	Refer to ECAM procedure.

SUBTASK 24-00-00-868-26A-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BP. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:

- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
- If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND HOT AIR FAULT	Pack Controller 1(2)	Not Permitted.

SUBTASK 24-00-00-868-26B-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BQ. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND HOT AIR FAULT	ACSC	Not Permitted.

SUBTASK 24-00-00-868-26C-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BR. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
-

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
- If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND L+R CAB FAN FAULT	P/B	Refer to ECAM procedure.

SUBTASK 24-00-00-868-26D-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BS. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND LAV+GALLEY FAN FAULT		Not Permitted.

SUBTASK 24-00-00-868-26E-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BT. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

--	--	--	--

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND TEMP CTL 1 FAULT	Pack Controller 1(2)	Not Permitted.

SUBTASK 24-00-00-868-26F-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BU. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND TEMP CTL 1 FAULT	ACSC	Not Permitted.

SUBTASK 24-00-00-868-26G-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BV. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND TEMP CTL 2 FAULT		Not Permitted.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

	Pack Controller 1(2)	
--	-------------------------	--

SUBTASK 24-00-00-868-26H-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BW. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND TEMP CTL 2 FAULT	ACSC	Not Permitted.

SUBTASK 24-00-00-868-26I-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BX. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND TEMP REGUL 1 FAULT	Pack Controller 1(2)	Not Permitted.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

SUBTASK 24-00-00-868-26J-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- BY. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND TEMP REGUL 1 FAULT	ACSC	Not Permitted.

SUBTASK 24-00-00-868-26K-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CA. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND TEMP REGUL 2 FAULT	Pack Controller 1(2)	Not Permitted.

SUBTASK 24-00-00-868-26L-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CB. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND TEMP REGUL 2 FAULT	ACSC	Not Permitted.

SUBTASK 24-00-00-868-26M-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CC. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND ZONE REGUL FAULT	Pack Controller 1(2)	Not Permitted.

SUBTASK 24-00-00-868-26N-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CD. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
 If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND ZONE REGUL FAULT	ACSC	Not Permitted.

SUBTASK 24-00-00-868-26O-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CE. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
 If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR PACK 1 FLOW REDUCED	ACSC	Not Permitted.

SUBTASK 24-00-00-868-26P-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CF. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:

- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
- If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	AIR PACK 2 FLOW REDUCED	ACSC	Not Permitted.

SUBTASK 24-00-00-868-120-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CG. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21	COND TRIM AIR SYS FAULT	AIR COND SYSTEM (ACSC (Air-Conditioning System Controller))	# PACK 1&2.....OFF. Check that both Pack Flow Control Valves are closed on the BLEED SD page. # Open C/Bs 55HH and 53HH. # Open C/Bs 51HH and 49HH. # Open C/Bs, 50HH, 54HH and 56HH. # Open C/B 52HH. # Wait 10 seconds. # Close C/Bs 50HH, 54HH, 56HH. # Close C/Bs 51HH and 49HH. # Close C/Bs 55HH and 53HH. # Close C/B 52HH. # PACK 1&2.....ON. <u>NOTE:</u>

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			During the reset, a small increase of the engine thrust may be observed (N1 or EPR, as applicable). If the parking brake is set, vibrations can occur.
--	--	--	--

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
** ON A/C FSN 015-050, 106-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 611-611, 615-650, 725-725, 729-730, 751-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999			
49VU	AIR COND/TEMP CTL/SYS 1 CHAN B /28VDC	52HH	D08
122VU	AIR COND/TEMP CTL SYS 2/CHAN A /115VAC	53HH	W22
122VU	AIR COND/TEMP CTL SYS 2/CHAN A /28VDC	55HH	W21
122VU	AIR COND/TEMP CTL SYS 1/CHAN A /115VAC	49HH	X22
122VU	AIR COND/TEMP CTL SYS 1/CHAN A /28VDC	51HH	X21
122VU	AIR COND/TEMP CTL SYS 2/CHAN B /28VDC	56HH	Y21
122VU	AIR COND/TEMP CTL SYS 2/CHAN B /115VAC	54HH	Y20
122VU	AIR COND/TEMP CTL SYS 1/CHAN B /115VAC	50HH	Y18

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-118-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

CH.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
21 36	AIR PACK 1 REGUL FAULT AIR PACK 2 REGUL FAULT AIR ENG 1 BLEED ABNORM PR AIR ENG2 BLEED ABNORM PR	AIR COND SYSTEM (ACSC (Air-Conditioning System Controller)) Engine bleed supply system	This reset procedure is applicable when AIR ENG 1(2) BLEED ABNORM PR and AIR PACK 2(1) REGUL FAULT have been triggered. If PACK 2(1) is set to ON: - PACK 2(1)..... OFF. - Wait 60 seconds. - PACK 2(1)..... ON. If PACK 2(1) is set to OFF: - PACK 2(1)..... ON. <u>NOTE:</u> This will clear the AIR PACK 2(1) REGUL FAULT ECAM alert.

SUBTASK 24-00-00-868-055-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

CJ. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

--	--	--	--

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT FCU 1 FAULT	FCU	For the FCU 1: - Open the C/B 9CA1, - After 5 seconds, close the C/B 9CA1. If the fault does not continue: - Do a check of the target and barometer references shown, and correct them if necessary (reset successful). If the fault continues: - Open the C/Bs 9CA1., - After 7 minutes, close the C /Bs 9CA1 in less than 5 seconds in side 1, - A minimum of 30 seconds are necessary for the FCU 1 to complete the safety test, - If the fault does not continue: * Do a check of the target and barometer references shown, and correct them if necessary (reset successful). - If the fault continues: * End of procedure (reset unsuccessful).

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-709, 712-712, 717-718, 725-725, 729-750, 801-850, 901-908, 911-951, 953-965, 967-999			
49VU	AUTO FLT/FCU/1	9CA1	B05
** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900			
49VU	AUTO FLT/FCU/1	9CA1	H11

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-281-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CK. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT FCU 2 FAULT	FCU	For the FCU 2: - Open the C/B 9CA2, - After 5 seconds, close the C/B 9CA2. If the fault does not continue: - Do a check of the target and barometer references shown, and correct them if necessary (reset successful). If the fault continues: - Open the C/Bs 9CA2., - After 7 minutes, close the C /Bs 9CA2 in less than 5 seconds in side 2, - A minimum of 30 seconds are necessary for the FCU 2 to complete the safety test, - If the fault does not continue: * Do a check of the target and barometer references shown, and correct them if necessary (reset successful). - If the fault continues: * End of procedure (reset unsuccessful).

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
121VU	AUTO FLT/FCU/2	9CA2	M21

SUBTASK 24-00-00-868-056-A

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CL. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT FCU 1+2 FAULT	FCU	Open the C/Bs 9CA1 and 9CA2. After 5 seconds close the C/Bs 9CA1 and 9CA2. If the fault does not continue: - Do a check of the target and barometer references shown, and correct them if necessary (reset successful). If the fault continues: - Open the C/Bs 9CA1 and 9CA2, - After 7 minutes, close the C /Bs 9CA1 and 9CA2 in less than 5 seconds between side 1 and side 2, - A minimum of 30 seconds are necessary for the FCU 1 and the FCU 2 to complete the safety test, - Do a check of the target and barometer references shown, and correct them if necessary (reset successful), - FCU targets are synchronized on current aircraft values and displayed as selected targets, - Re-enter the barometer altimeter setting value, if necessary.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-709, 712-712, 717-718, 725-725, 729-750, 801-850, 901-908, 911-951, 953-965, 967-999			
49VU	AUTO FLT/FCU/1	9CA1	B05
** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900			
49VU	AUTO FLT/FCU/1	9CA1	H11
** ON A/C FSN ALL			
121VU	AUTO FLT/FCU/2	9CA2	M21

SUBTASK 24-00-00-868-057-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CM. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AFS-MCDU-One MCDU locked or blank	MCDU	For the MCDU 1: - Open the C/B 11CA1, - After 10 seconds, close the C /B 11CA1. For the MCDU 2: - Open the C/B 11CA2, - After 10 seconds, close the C /B 11CA2. For the MCDU 3: - Open the C/B 11CA3,

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

		- After 10 seconds, close the C /B 11CA3.
--	--	---

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-709, 712-712, 717-718, 725-725, 729-750, 801-850, 901-908, 911-951, 953-965, 967-999			
49VU	AUTO FLT/MCDU/1	11CA1	B01
** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900			
49VU	AUTO FLT/MCDU/1	11CA1	H07
** ON A/C FSN ALL			
121VU	AUTO FLT/MCDU/2	11CA2	N20

SUBTASK 24-00-00-868-058-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CN. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AFS-FMGC malfunction	FMGC	If no engine running: - Apply external power or APU generator power, - For FMGC 1: * After 2 minutes, set the FD1 P/B SW to OFF, * Open the C/B 10CA1,

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

		* After 10 seconds, close the C/B 10CA1. - Always wait 1 minute after the reset or 1minute after the "PLEASE WAIT" message disappears from MCDU, before engaging or reengaging the FD and the AP of the reset FMGC. If engine running: - For FMGC 1: * Set the FD1 P/B SW to OFF, * Open the C/B 10CA1, * After 10 seconds, close the C/B 10CA1. - Always wait 1 minute after the reset or 1minute after the "PLEASE WAIT" message disappears from MCDU, before engaging or reengaging the FD and the AP of the reset FMGC. - If the FMGC reset is unsuccessful: * Consider FMGC reset with engines not running. <u>NOTE:</u> The FMGC reset is more effective with engines not running.
--	--	--

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-709, 712-712, 717-718, 725-725, 729-750, 801-850, 901-908, 911-951, 953-965, 967-999			
49VU	AUTO FLT/FMGC/1	10CA1	B02
** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900			
49VU	AUTO FLT/FMGC/1	10CA1	H08
** ON A/C FSN ALL			
SUBTASK 24-00-00-868-282-A			

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CP. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AFS-MCDU-All MCDUs locked or blank	FMGC	If no engine running: - Apply external power or APU generator power, - For FMGC 2: * After 2 minutes, set the FD2 P/B SW to OFF, * Open the C/B 10CA2, * After 10 seconds, close the C/B 10CA2. - Always wait 1 minute after the reset or 1minute after the "PLEASE WAIT" message disappears from MCDU, before engaging or reengaging the FD and the AP of the reset FMGC. If engine running: - For FMGC 2: * Set the the FD2 P/B SW to OFF, * Open the C/B 10CA2, * After 10 seconds, close the C/B 10CA2. - Always wait 1 minute after the reset or 1minute after the "PLEASE WAIT" message disappears from MCDU, before engaging or reengaging the FD and the AP of the reset FMGC.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			- If the FMGC reset is unsuccessful: * Consider FMGC reset with engines not running. <u>NOTE:</u> The FMGC reset is more effective with engines not running.
--	--	--	--

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
121VU	AUTO FLT/FMGC/2	10CA2	M17

SUBTASK 24-00-00-868-103-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CQ. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT A/THR OFF	FCU	If no engine is in operation: - On the FCU, push the A/THR pushbutton switch to engage the A/THR again (this step cancels the ECAM message). - On the thrust levers, push the A/THR instinctive-disconnect pushbutton-switch to disconnect the A/THR. If a minimum of one engine is in operation: - Apply the external power or the APU generator power.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			- Set the ENG MASTER control switches to the OFF position. - On the FCU, push the A/THR pushbutton switch to engage the A/THR again (this step cancels the ECAM message). - On the thrust levers, push the A/THR instinctive-disconnect pushbutton-switch to disconnect the A/THR.
--	--	--	--

SUBTASK 24-00-00-868-104-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CR. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AFS-FAC-"CAT 3 DUAL" message is shown on the "INOP SYS" section of the SD without other ECAM message related to the FAC.	FAC	If the "CAT 3 DUAL" message is shown on the "INOP SYS" section of the SD without other ECAM message (s): - Change the AP in command. If not satisfactory: - Release the FAC 1 pushbutton switch (the OFF legend comes on). - Wait for three seconds. - Push the FAC 1 pushbutton switch (the OFF legend goes off). Wait for the "AUTO FLT FAC 1 FAULT" message to go out of view: -

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			Release the FAC 2 pushbutton switch (the OFF legend comes on). - Wait for three seconds. - Push the FAC 2 pushbutton switch (the OFF legend goes off). <u>NOTE:</u> If the "CAT 3 DUAL" message (on the "INOP SYS" section of the SD) is related to an "ADR" or "IR" ECAM message, the FAC or the FMGC do not see the ADR or the IR as defective. Thus, a change of the AP or a reset of the FAC will not clear the "CAT 3 DUAL" message.
--	--	--	--

SUBTASK 24-00-00-868-26S-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CS. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT AP OFF	FMGC	Not Permitted.

SUBTASK 24-00-00-868-26T-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CT. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT A/THR LIMITED	FMGC	Not Permitted.

**** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-709, 712-712, 717-718, 725-725, 729-750, 801-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999**

SUBTASK 24-00-00-868-26U-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CU. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT FAC 1 FAULT	FAC	Refer to ECAM procedure.

SUBTASK 24-00-00-868-26V-A

CAUTION:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CV. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT FAC 2 FAULT	FAC	Refer to ECAM procedure.

SUBTASK 24-00-00-868-26W-A

CAUTION: **DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:**

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CW. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT FAC 1+2 FAULT	FAC	Refer to ECAM procedure.

SUBTASK 24-00-00-868-26X-A

CAUTION: **DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:**

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
 - THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
 - THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
- IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CX. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
 If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT YAW DAMPER 1	FAC	Refer to ECAM procedure.

SUBTASK 24-00-00-868-26Y-A

- CAUTION:** DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
 - THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
 - THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
- IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- CY. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
 If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT YAW DAMPER 2	FAC	Refer to ECAM procedure.

SUBTASK 24-00-00-868-26Z-A

- CAUTION:** DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
 - THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

**- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.**

- DA. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT YAW DAMPER SYS	FAC	Refer to ECAM procedure.

SUBTASK 24-00-00-868-270-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- DB. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT RUD TRIM1 FAULT	FAC	Not Permitted.

SUBTASK 24-00-00-868-271-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- DC. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT RUD TRIM2 FAULT	FAC	Not Permitted.

SUBTASK 24-00-00-868-272-A

- CAUTION:** DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
 - THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
 - THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
- IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.**

- DD. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT RUD TRIM SYS	FAC	Refer to ECAM procedure.

SUBTASK 24-00-00-868-273-A

- CAUTION:** DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
 - THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
 - THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
- IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.**

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- DE. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT RUD TRV LIM 1	FAC	Not permitted.

SUBTASK 24-00-00-868-274-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- DF. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT RUD TRV LIM 2	FAC	Not permitted.

SUBTASK 24-00-00-868-275-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- DG. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT RUD TRV LIM SYS	FAC	Refer to ECAM procedure.

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-277-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- DH. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT REAC W/S DET FAULT	FAC	Not Permitted.

SUBTASK 24-00-00-868-278-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- DJ. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT TCAS MODE FAULT	FMGC	Not Permitted.

**** ON A/C FSN 001-001, 003-006, 009-009, 011-050, 102-107, 110-110, 113-150, 155-158, 160-162, 164-200, 246-248, 251-300, 351-352, 356-356, 358-372, 379-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-511, 517-521, 523-525, 527-527, 529-529, 531-536, 540-550, 562-567, 571-571, 583-600, 611-611, 615-615, 618-620, 622-650, 717-718, 725-725, 729-803, 805-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999**

POST SB 31-1608 for A/C 002-002, 007-008, 101-101, 108-109, 111-112, 154-154, 159-159, 163-163, 249-249, 378-378, 512-512, 522-522, 561-561, 605-608, 610-610, 616-617, 621-621, 651-651, 701-709, 712-712, 804-804

EMB SB 22-1818 for A/C 811-816

EMB SB 22-1819 for A/C 878-878, 880-880, 901-908, 951-951, 953-965, 967-967

EMB SB 22-1820 for A/C 351-352, 356-356, 358-372, 381-390, 401-425, 427-428, 430-433, 540-541

EMB SB 31-1608 for A/C 001-001, 003-006, 009-009, 011-031, 102-107, 110-110, 113-123, 155-158, 160-162, 164-183, 246-248, 251-253, 351-351, 356-356, 358-360, 362-372, 379-379, 382-385, 387-387, 389-390, 401-401, 406-422, 424-425, 427-428, 432-432, 435-436, 501-501, 503-504, 506-506, 508-508, 510-511, 517-521, 523-525, 527-527, 529-529, 531-536, 540-541, 562-567, 571-571, 583-584, 611-611, 615-615, 618-620, 622-624, 717-718, 725-725, 729-731, 801-803, 805-816

EMB SB 31-1609 for A/C 878-878, 880-880, 901-901, 903-908, 951-951, 953-957, 959-959, 967-967

SUBTASK 24-00-00-868-279-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

DK. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
-

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT FMGC VERSIONS DISAGREE	FMGC	Not Permitted.

**** ON A/C FSN 751-800**

SUBTASK 24-00-00-868-27A-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- DL. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT FMGC 1+2 FAULT	FMGC	Not Permitted.

SUBTASK 24-00-00-868-27B-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- DM. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT FMGC 1 FAULT	FMGC	Not Permitted.

SUBTASK 24-00-00-868-27C-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

DN. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT FMGC 2 FAULT	FMGC	Not Permitted.

**** ON A/C FSN ALL**



EMB SB 31-1608 for A/C 001-001, 003-006, 009-009, 011-031, 102-107, 110-110, 113-123, 155-158, 160-162, 164-183, 246-248, 251-253, 351-351, 356-356, 358-360, 362-372, 379-379, 382-385, 387-387, 389-390, 401-401, 406-422, 424-425, 427-428, 432-432, 435-436, 501-501, 503-504, 506-506, 508-508, 510-511, 517-521, 523-525, 527-527, 529-529, 531-536, 540-541, 562-567, 571-571, 583-584, 611-611, 615-615, 618-620, 622-624, 717-718, 725-725, 729-731, 801-803, 805-816

EMB SB 31-1609 for A/C 878-878, 880-880, 901-901, 903-908, 951-951, 953-957, 959-959, 967-967

SUBTASK 24-00-00-868-27D-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

JCP Title: Resets	© AIRBUS S.A.S. ALL RIGHTS RESERVED. CONFIDENTIAL AND PROPRIETARY DOCUMENT.	Page 61 of 206 PRINT DATE: Aug 16/2026
-------------------	--	---

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- DP. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT FAC 1 DEGRADED	FAC	Refer to ECAM procedure.

SUBTASK 24-00-00-868-27E-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- DQ. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT FAC 2 DEGRADED	FAC	Refer to ECAM procedure.

SUBTASK 24-00-00-868-27F-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- DR. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT FAC1+2 DEGRADED	FAC	Refer to ECAM procedure.

**** ON A/C FSN ALL**



EMB SB 22-1797 for A/C 351-352, 356-356, 358-372, 401-425, 427-428, 430-433, 435-436, 540-541, 811-816

EMB SB 22-1798 for A/C 878-878, 880-880, 901-908, 951-951, 953-965, 967-967

EMB SB 31-1608 for A/C 001-001, 003-006, 009-009, 011-031, 102-107, 110-110, 113-123, 155-158, 160-162, 164-183, 246-248, 251-253, 351-351, 356-356, 358-360, 362-372, 379-379, 382-385, 387-387, 389-390, 401-401, 406-422, 424-425, 427-428, 432-432, 435-436, 501-501, 503-504, 506-506, 508-508, 510-511, 517-521, 523-525, 527-527, 529-529, 531-536, 540-541, 562-567, 571-571, 583-584, 611-611, 615-615, 618-620, 622-624, 717-718, 725-725, 729-731, 801-803, 805-816

EMB SB 31-1609 for A/C 878-878, 880-880, 901-901, 903-908, 951-951, 953-957, 959-959, 967-967

SUBTASK 24-00-00-868-27G-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

DS. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT FAC VERSIONS // DISAGREE	FAC	Not Permitted.

**** ON A/C FSN ALL**

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

SUBTASK 24-00-00-868-27H-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- DT. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT LIMITED	FMGC	Not Permitted.

SUBTASK 24-00-00-868-27I-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- DU. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

TBD

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	T.O // ACCELERATION DEGRADED	FAC	Not Permitted.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

**** ON A/C FSN 731-750, 811-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999**



EMB SB 22-1606 for A/C 811-816

EMB SB 22-1676 for A/C 731-731

SUBTASK 24-00-00-868-117-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

DV. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	A/THR	FMGC	If during the ECAM status check of the after start C/L, A/THR INOP SYS is displayed without additional ECAM alert, apply the procedure that follows: Perform a FMGC 1 reset: # Set FD 1 pb to OFF. - Open C/B 10CA1. - Wait 10 s. - Close C/B 10CA1. - Wait until FMGC 1 reset is complete: * Wait 1 min after the "PLEASE WAIT" message disappears from the MCDU to ensure FMGC 1 reset is complete. # Set FD 1 pb to ON. If FMGC 1 reset does not clear A /THR INOP SYS, perform a FMGC 2 reset: # Set FD 2 pb to OFF. - Open C/B 10CA2. - Wait 10 s.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			- Close C/B 10CA2. - Wait until FMGC 2 reset is complete: * Wait 1 min after the "PLEASE WAIT" message disappears from the MCDU to ensure FMGC 1 reset is complete. # Set FD 2 pb to ON.
--	--	--	---

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
** ON A/C FSN 731-750, 811-850, 901-908, 911-951, 953-965, 967-999			
49VU	AUTO FLT/FMGC/1	10CA1	B02
** ON A/C FSN 851-876, 878-878, 880-880, 882-900			
49VU	AUTO FLT/FMGC/1	10CA1	H08
** ON A/C FSN 731-750, 811-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999			
121VU	AUTO FLT/FMGC/2	10CA2	M17

**** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-709, 712-712, 717-718, 725-725, 729-750, 801-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999**

EMB SB 22-1102 for A/C 001-009, 011-014, 102-105, 605-608, 610-610, 651-651, 701-709, 712-712, 717-718, 731-731

EMB SB 22-1226 for A/C 001-009, 011-014, 101-105, 605-608, 610-610, 651-651, 701-709, 712-712, 717-718, 731-731

SUBTASK 24-00-00-868-149-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- DW. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT YAW DAMPER 1	FAC 1	- Set FAC 1 pushbutton switch to OFF. - Wait for three seconds. - Set FAC 1 pushbutton switch to ON.

SUBTASK 24-00-00-868-150-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

DX. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
22	AUTO FLT YAW DAMPER 2	FAC 2	- Set FAC 2 pushbutton switch to OFF. - Wait for three seconds. - Set FAC 2 pushbutton switch to ON.

**** ON A/C FSN 001-009, 011-014, 701-709, 712-712, 717-718, 731-750**

SUBTASK 24-00-00-868-090-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- DY. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
2373	COM CIDS 1+2 FAULT	CIDS	Do this procedure in the sequence shown: - Open C/B 150RH. - Open C/B 151RH. - After 10 seconds, close C/B 151RH. - Close C/B 150RH. - After CIDS reset, approximately 4 minutes are necessary before recovering normal operation.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
49VU	COM/CIDS/DIR 1 AND 2/ESS	150RH	G02
121VU	COM NAV/CIDS/DIR 1 AND 2/NORM	151RH	M05

**** ON A/C FSN 101-105, 605-608, 610-610, 651-700**

SUBTASK 24-00-00-868-090-B

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- DY. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
-

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
2373	COM CIDS 1+2 FAULT	CIDS	Do this procedure in the sequence shown: - Open C/B 150RH. - Open C/B 151RH. - Open C/B 157RH. - Open C/B 156RH. - After 10 seconds, close C/B 151RH. - Close C/B 156RH. - Close C/B 150RH. - Close C/B 157RH. - After CIDS reset, approximately 4 minutes are necessary before recovering normal operation.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
49VU	COM/CIDS/DIR ESS/2	157RH	G02
49VU	COM/CIDS/DIR ESS/1	150RH	G01
121VU	COM NAV/CIDS/DIR NORM/2	156RH	M06
121VU	COM NAV/CIDS/DIR NORM/1	151RH	M05

**** ON A/C FSN
POST SB 23-1B10 for A/C 378-379**

SUBTASK 24-00-00-868-090-H
DY. TBD

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
TBD			

**** ON A/C FSN 015-050, 106-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-400, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 611-611, 615-650, 725-725, 729-730, 901-907, 951-951, 953-965, 967-999**

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

PRE SB 23-1B10 for A/C 015-031, 108-123, 154-183, 246-249, 251-251, 351-352, 356-356, 358-372, 378-379, 381-390, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-541, 561-567, 571-571, 583-584, 611-611, 615-624, 725-725, 729-730

SUBTASK 24-00-00-868-22X-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- EA. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
2373	COM CIDS 1+2 FAULT	CIDS	Do this procedure in the sequence shown: - Open C/B 147RH. - Open C/B 146RH. - Open C/B 150RH and C/B 157RH. - Open C/B 151RH and C/B 156RH. - After 10 seconds, close C/B 150RH. - Close C/B 157RH. - After 10 seconds, close C/B 151RH. - Close C/B 156RH. - Close C/B 147RH. - Close C/B 146RH. - After CIDS reset, approximately 4 minutes are necessary before recovering normal operation.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
-------	-------------	-----	----------

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

**** ON A/C FSN 015-050, 106-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-400, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 611-611, 615-650, 725-725, 729-730, 901-907, 951-951, 953-965, 967-999**

49VU	COM/CIDS/DIR ESS/2	157RH	G02
49VU	COM/CIDS/DIR ESS/1	150RH	G01
121VU	COM NAV/CIDS/DIR NORM/2	156RH	M06
121VU	COM NAV/CIDS/DIR NORM/1	151RH	M05

**** ON A/C FSN 378-379**

121VU	COM/CIDS/DIR 2/BAT	146RH	P14
121VU	COM/CIDS/DIR 1/BAT	147RH	P13

**** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 801-850, 878-878**

PRE SB 23-1830 for A/C 878-878

PRE SB 23-1B10 for A/C 401-425, 427-428, 430-433, 435-436, 801-816

SUBTASK 24-00-00-868-22X-B

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

EA. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
2373	COM CIDS 1+2 FAULT	CIDS	Do this procedure in the sequence shown: - Open C/B 150RH and C/B 157RH. - Open C/B 151RH and C/B 156RH. - After 10 seconds, close C/B 150RH.

	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			- Close the C/B 157RH. - After 10 seconds, close C/B 151RH. - Close C/B 156RH. - After CIDS reset, approximately 4 minutes are necessary before recovering normal operation.
--	--	--	---

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
-------	-------------	-----	----------

**** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 801-850**

49VU	COM DIR ESS/2	157RH	G02
49VU	COM/CIDS/DIR ESS/1	150RH	G01

**** ON A/C FSN 878-878**

49VU	COM NAV/CIDS/DIR2 ESS	157RH	G02
49VU	COM NAV/CIDS/DIR1 ESS	150RH	G01

**** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 801-850**

121VU	COM NAV/CIDS/DIR NORM/2	156RH	M07
121VU	COM NAV/CIDS/DIR NORM/1	151RH	M06

**** ON A/C FSN 878-878**

121VU	COM NAV/CIDS/DIR2 NORM	156RH	M06
121VU	COM NAV/CIDS/DIR1 NORM	151RH	M05

**** ON A/C FSN
POST SB 23-1B10 for A/C 378-379**

SUBTASK 24-00-00-868-22X-D
EA. TBD

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
TBD			

**** ON A/C FSN 015-050, 154-200, 246-250, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 725-725, 729-730, 751-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999**

SUBTASK 24-00-00-868-233-A

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

EB. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
2373	COM CIDS 1+2 FAULT	CIDS	Do this procedure in the sequence shown: - Open C/B 150RH and C/B 157RH. - Open C/B 151RH and C/B 156RH. - After 10 seconds, close C/B 150RH. - Close C/B 157RH. - After 10 seconds, close C/B 151RH. - Close C/B 156RH. - After CIDS reset, approximately 4 minutes are necessary before recovering normal operation.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
49VU	COM/CIDS/DIR ESS/2	157RH	G02

**** ON A/C FSN 015-050, 154-200, 246-250, 351-352, 356-356, 358-372, 378-379, 381-400, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 725-725, 729-730, 901-908, 911-951, 953-965, 967-999**

**** ON A/C FSN 015-050, 154-200, 246-250, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 725-725, 729-730, 801-850, 901-908, 911-951, 953-965, 967-999**

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

49VU	COM/CIDS/DIR ESS/1	150RH	G01
------	--------------------	-------	-----

**** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 801-850**

49VU	COM DIR ESS/2	157RH	G02
------	---------------	-------	-----

**** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900**

49VU	COM NAV/CIDS/DIR2 ESS	157RH	G02
------	-----------------------	-------	-----

49VU	COM NAV/CIDS/DIR1 ESS	150RH	G01
------	-----------------------	-------	-----

**** ON A/C FSN 015-050, 154-200, 246-250, 351-352, 356-356, 358-372, 378-379, 381-400, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 725-725, 729-730, 901-908, 911-951, 953-965, 967-999**

121VU	COM NAV/CIDS/DIR NORM/2	156RH	M06
-------	-------------------------	-------	-----

121VU	COM NAV/CIDS/DIR NORM/1	151RH	M05
-------	-------------------------	-------	-----

**** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 801-850**

121VU	COM NAV/CIDS/DIR NORM/2	156RH	M07
-------	-------------------------	-------	-----

121VU	COM NAV/CIDS/DIR NORM/1	151RH	M06
-------	-------------------------	-------	-----

**** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900**

121VU	COM NAV/CIDS/DIR2 NORM	156RH	M06
-------	------------------------	-------	-----

121VU	COM NAV/CIDS/DIR1 NORM	151RH	M05
-------	------------------------	-------	-----

**** ON A/C FSN 751-800, 851-876, 880-880, 882-900, 908-908, 911-950**

POST SB 23-1830 for A/C 878-878

POST SB 23-1B10 for A/C 015-031, 108-123, 154-183, 246-249, 251-251, 351-352, 356-356, 358-372, 378-379, 381-390, 401-425, 427-428, 430-433, 435-436, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-541, 561-567, 571-571, 583-584, 611-611, 615-624, 725-725, 729-730, 801-816



EMB SB 23-1830 for A/C 852-852, 854-861, 880-880, 908-908, 911-914, 916-916, 918-918, 921-922

SUBTASK 24-00-00-868-23F-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

EC. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
2373	COM CIDS 1+2 FAULT	CIDS	Do this procedure in the sequence shown: - Open C/B 150RH and C/B 157RH. - Open C/B 151RH and C/B 156RH. - After 10 seconds, close C/B 151RH. - Close C/B 156RH. - Close C/B 150RH. - Close C/B 157RH. - After CIDS reset, approximately 4 minutes are necessary before recovering normal operation.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
** ON A/C FSN 015-050, 108-150, 154-200, 246-251, 351-352, 356-356, 358-372, 378-379, 381-400, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 611-611, 615-650, 725-725, 729-730, 908-908, 911-950			
49VU	COM/CIDS/DIR ESS/2	157RH	G02
** ON A/C FSN 015-050, 108-150, 154-200, 246-251, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 611-611, 615-650, 725-725, 729-730, 801-850, 908-908, 911-950			
49VU	COM/CIDS/DIR ESS/1	150RH	G01
** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 801-850			
49VU	COM DIR ESS/2	157RH	G02
** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900			
49VU	COM NAV/CIDS/DIR2 ESS	157RH	G02
49VU	COM NAV/CIDS/DIR1 ESS	150RH	G01

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

**** ON A/C FSN 015-050, 108-150, 154-200, 246-251, 351-352, 356-356, 358-372, 378-379, 381-400, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 611-611, 615-650, 725-725, 729-730, 908-908, 911-950**

121VU	COM NAV/CIDS/DIR NORM/2	156RH	M06
121VU	COM NAV/CIDS/DIR NORM/1	151RH	M05

**** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 801-850**

121VU	COM NAV/CIDS/DIR NORM/2	156RH	M07
121VU	COM NAV/CIDS/DIR NORM/1	151RH	M06

**** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900**

121VU	COM NAV/CIDS/DIR2 NORM	156RH	M06
121VU	COM NAV/CIDS/DIR1 NORM	151RH	M05

**** ON A/C FSN 378-379**

PRE SB 23-1B10 for A/C 378-379

SUBTASK 24-00-00-868-23F-B

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

EC. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
2373	COM CIDS 1+2 FAULT	CIDS	Do this procedure in the sequence shown: - Open C/B 147RH. - Open C/B 146RH. - Open C/B 150RH and C/B 157RH. - Open C/B 151RH and C/B 156RH.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			- After 10 seconds, close C/B 151RH. - Close C/B 156RH. - Close C/B 150RH. - Close C/B 157RH. - Close C/B 147RH. - Close C/B 146RH. - After CIDS reset, approximately 4 minutes are necessary before recovering normal operation.
--	--	--	---

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
** ON A/C FSN 378-379			
49VU	COM/CIDS/DIR ESS/2	157RH	G02
49VU	COM/CIDS/DIR ESS/1	150RH	G01
121VU	COM NAV/CIDS/DIR NORM/2	156RH	M06
121VU	COM NAV/CIDS/DIR NORM/1	151RH	M05
121VU	COM/CIDS/DIR 2/BAT	146RH	P14
121VU	COM/CIDS/DIR 1/BAT	147RH	P13

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-090-C
DELETED

SUBTASK 24-00-00-868-090-D
DELETED

SUBTASK 24-00-00-868-091-A
DELETED

**** ON A/C FSN 101-105, 605-608, 610-610, 651-700**

SUBTASK 24-00-00-868-091-B

CAUTION: **DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:**

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

ED. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
2373	COM-CIDS-Evac horn starts spuriously	CIDS	Do this procedure in the sequence shown: - Press the EVAC/HORN SHUT OFF SW. - Set the EVAC CAPT & PURS /CAPT SW to the CAPT only position. - Press the EVAC command button (if indicated as active) - After 3 seconds, if unsuccessful: - Open C/B 150RH. - Open C/B 151RH. - Open C/B 157RH. - Open C/B 156RH. - After 10 seconds, close C/B 151 RH. - Close C/B 156RH. - Close C/B 150RH. - Close C/B 157RH. - After CIDS reset, approximately 4 minutes are necessary before recovering normal operation.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
49VU	COM/CIDS/DIR ESS/2	157RH	G02
49VU	COM/CIDS/DIR ESS/1	150RH	G01
121VU	COM NAV/CIDS/DIR NORM/2	156RH	M06
121VU	COM NAV/CIDS/DIR NORM/1	151RH	M05

**** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 751-876, 878-878, 880-880, 882-900**

SUBTASK 24-00-00-868-091-C

CAUTION:

JCP Title: Resets	© AIRBUS S.A.S. ALL RIGHTS RESERVED. CONFIDENTIAL AND PROPRIETARY DOCUMENT.	Page 78 of 206 PRINT DATE: Aug 16/2026
-------------------	--	---

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- **THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND**
- **THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR**
- **THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.**

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- ED. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
2373	COM-CIDS-Evac horn starts spuriously	CIDS	Do this procedure in the sequence shown: - Press the EVAC/HORN SHUT OFF SW. - Set the EVAC CAPT & PURS /CAPT SW to the CAPT only position. - Press the EVAC Command button (if indicated as active) - After 3 seconds, if unsuccessful: - Open C/B 150RH. - Open C/B 151RH. - Open C/B 157RH. - Open C/B 156RH. - After 10 seconds, close C/B 150 RH. - Close C/B 157RH. - After 10 seconds, close C/B 151RH. - Close C/B 156RH. - After CIDS reset, approximately 4 minutes are necessary before recovering normal operation.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
-------	-------------	-----	----------

**** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 801-850**

--	--	--	--

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

49VU	COM DIR ESS/2	157RH	G02
49VU	COM/CIDS/DIR ESS/1	150RH	G01

**** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900**

49VU	COM NAV/CIDS/DIR2 ESS	157RH	G02
49VU	COM NAV/CIDS/DIR1 ESS	150RH	G01

**** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 801-850**

121VU	COM NAV/CIDS/DIR NORM/2	156RH	M07
121VU	COM NAV/CIDS/DIR NORM/1	151RH	M06

**** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900**

121VU	COM NAV/CIDS/DIR2 NORM	156RH	M06
121VU	COM NAV/CIDS/DIR1 NORM	151RH	M05

**** ON A/C FSN 015-050, 106-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-400, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 611-611, 615-650, 725-725, 729-730, 901-908, 911-951, 953-965, 967-999**

SUBTASK 24-00-00-868-091-D

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

ED. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
2373	COM-CIDS-Evac horn starts spuriously	CIDS	Do this procedure in the sequence shown: - Press the EVAC/HORN SHUT OFF SW. -

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			Set the EVAC CAPT & PURS /CAPT SW to the CAPT only position. - Press the EVAC Command button (if indicated as active) - After 3 seconds, if unsuccessful: - Open C/B 150RH. - Open C/B 151RH. - Open C/B 157RH. - Open C/B 156RH. - After 10 seconds, close C/B 150 RH. - Close C/B 157RH. - After 10 seconds, close C/B 151RH. - Close C/B 156RH. - After CIDS reset, approximately 4 minutes are necessary before recovering normal operation.
--	--	--	---

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
49VU	COM/CIDS/DIR ESS/2	157RH	G02
49VU	COM/CIDS/DIR ESS/1	150RH	G01
121VU	COM NAV/CIDS/DIR NORM/2	156RH	M06
121VU	COM NAV/CIDS/DIR NORM/1	151RH	M05

**** ON A/C FSN 001-009, 011-014, 701-709, 712-712, 717-718, 731-750**

SUBTASK 24-00-00-868-093-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

EE. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
-

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
2373	COM-CIDS-FAP - no function (frozen)	FAP or Tape repro- ducer /PRAM	For FAP: - Open C/B 170RH. - After 10 seconds, close C/B 170RH. - If unsuccessful, for tape reproducer/PRAM: * Open C/B 2RX, * After 10 seconds, close C/B 2RX.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
-------	-------------	-----	----------

**** ON A/C FSN 001-009, 011-014, 703-709, 712-712, 717-718, 731-750**

121VU	COM NAV/CIDS/FWD ATTND/PNL	170RH	Q14
-------	----------------------------	-------	-----

**** ON A/C FSN 701-702**

121VU	COM NAV/CIDS/FWD ATTND/PNL	170RH	M14
-------	----------------------------	-------	-----

**** ON A/C FSN 001-009, 011-014, 731-750**



EMB SB 25-1BYL for A/C 001-009, 011-014

2000VU	PRAM	2RX	E01
--------	------	-----	-----

**** ON A/C FSN 101-105, 605-608, 610-610, 651-700**

SUBTASK 24-00-00-868-093-B

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

EE. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
23	COM-CIDS-FAP - no function (frozen)	FAP or Tape repro- ducer /PRAM	For FAP: - Open the C/B 170RH, - After 10 seconds, close the C /B 170RH. - If unsuccessful, for tape reproducer/PRAM: * Open the C/B 2RX, * After 10 seconds, close the C/B 2RX.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
121VU	COM /CIDS/FLT ATTND/PNL	170RH	Q14

**** ON A/C FSN 651-700**

2000VU	PRAM	2RX	E01
--------	------	-----	-----

**** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 751-876, 878-878, 880-880, 882-900**

SUBTASK 24-00-00-868-093-C

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- EE. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
23	COM-CIDS-FAP - no function (frozen)	FAP or Tape repro- ducer /PRAM	Open the C/B 171RH, Open the C/B 170RH, After 10 seconds, close the C/B 170RH

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			Close the C/B 171RH. If unsuccessful, for tape reproducer /PRAM: - Open the C/B 2RX, - After 10 seconds, close the C /B 2RX.
--	--	--	---

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
-------	-------------	-----	----------

**** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 801-850**

49VU	COM/CIDS/FLT ATTND PNL/ESS	171RH	H01
------	----------------------------	-------	-----

**** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900**

49VU	COM/CIDS/FLT ATTND PNL/ESS	171RH	G03
------	----------------------------	-------	-----

**** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 801-866, 878-878, 880-880**

121VU	COM NAV/CIDS/FWD ATTND/PNL	170RH	Q14
-------	----------------------------	-------	-----

**** ON A/C FSN 751-800, 867-876, 882-900**

121VU	COM/FAP1/NORM	170RH	Q14
-------	---------------	-------	-----

**** ON A/C FSN 015-050, 106-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-400, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 611-611, 615-650, 725-725, 729-730, 901-908, 911-951, 953-965, 967-999**

SUBTASK 24-00-00-868-093-D

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- EE. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

23	COM-CIDS-FAP - no function (frozen)	FAP or Tape repro- ducer /PRAM	Open the C/B 171RH, Open the C/B 170RH, After 10 seconds, close the C/B 170RH Close the C/B 171RH. If unsuccessful, for tape reproducer /PRAM: - Open the C/B 2RX, - After 10 seconds, close the C /B 2RX.
----	-------------------------------------	--------------------------------	--

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
** ON A/C FSN 015-050, 108-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-400, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 611-611, 615-650, 725-725, 729-730, 901-908, 911-951, 953-965, 967-999			
49VU	COM/CIDS/FLT ATTND PNL/ESS	171RH	H01
** ON A/C FSN 015-050, 108-150, 154-200, 246-300, 351-352, 356-356, 358-372, 381-400, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 611-611, 615-650, 725-725, 729-730, 901-908, 911-951, 953-965, 967-999			
121VU	COM CIDS FWD ATTND PNL	170RH	Q14
** ON A/C FSN 106-107, 378-379			
121VU	COM/FAP1/NORM	170RH	Q14
** ON A/C FSN 566-566			
2000VU	PRAM	2RX	E01

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-092-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

EF. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
 If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

-

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
23	COM-RMP-no function (frozen)	RMP	You must do a reset of all the RMPs, one after the other. On the RMP control panel: - Set the ON/OFF SW to OFF, - After 5 seconds, set the ON /OFF SW to ON.

**** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-401, 403-405, 408-408, 415-416, 418-418, 420-420, 423-423, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-709, 712-712, 717-718, 725-725, 729-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999**

SUBTASK 24-00-00-868-074-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- EG. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
23	COM-SATCOM-malfunction	SDU	Open the C/B 102RV1. After 5 seconds, close the C/B 102RV1. <u>NOTE:</u> The Satellite Data Unit (SDU) should reset in less than 2 minutes.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			You cannot perform a software reset for SATCOM via MCDU.
--	--	--	--

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
** ON A/C FSN 246-250, 378-379, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-610, 615-650, 701-709, 712-712, 717-718, 725-725, 729-730, 751-810			
121VU	SATCOM	102RV1	K01

**** ON A/C FSN 402-402, 406-407, 409-414, 417-417, 419-419, 421-422, 424-425**

SUBTASK 24-00-00-868-074-B

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

EG. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
23	COM-SATCOM-malfunction	SDU	Open the C/B 240RV. After 5 seconds, close the C/B 240RV. <u>NOTE:</u> The Satellite Data Unit (SDU) should reset in less than 2 minutes. You cannot perform a software reset for SATCOM via MCDU.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
121VU	SATCOM	240RV	K01

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

**** ON A/C FSN 359-372, 435-450, 751-800, 851-876, 882-900, 919-950**

SUBTASK 24-00-00-868-075-B

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- EH. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
23	COM-Flickering or total loss of video camera display (on SD) with the VIDEO NOT AVAIL message shown	CDSS	On the center pedestal VIDEO panel, set the VIDEO rotary selector to OFF. On the overhead panel, set the COCKPIT DOOR VIDEO P/B SW to OFF. After 2 minutes, on the overhead panel, set the COCKPIT DOOR VIDEO P/B SW to ON. After 15 seconds, on the center pedestal VIDEO panel, set the VIDEO rotary selector to CKPT ENTRY.

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-105-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- EJ. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
23	COM-HF Datalink/HF	HF TRANSCIVER	- Pull circuit breaker 1RE1. - Wait for two seconds. - Push circuit breaker 1RE1.

PANEL	DESIGNATION	FIN	LOCATION
-------	-------------	-----	----------

**** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-700, 703-709, 712-712, 717-718, 725-725, 729-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999**

49VU	HF1	1RE1	HA14
------	-----	------	------

**** ON A/C FSN 701-702**

49VU	COM HF1	1RE1	HA14
------	---------	------	------

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-1FH-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

EK. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC AC BUS 1 FAULT	ELEC	Not permitted.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

SUBTASK 24-00-00-868-1FI-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- EL. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC AC BUS 2 FAULT	ELEC	Not permitted.

SUBTASK 24-00-00-868-1FJ-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- EM. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC AC ESS BUS ALTN	ELEC	Not permitted.

SUBTASK 24-00-00-868-1FK-A

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- EN. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC AC ESS BUS FAULT	ELEC	In the cockpit, on the ELEC control panel 35VU, release the AC ESS FEED P/BSW.

SUBTASK 24-00-00-868-1FL-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- EP. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC AC ESS BUS SHED	ELEC	Not permitted.

**** ON A/C FSN 015-050, 106-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529,**

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

531-536, 540-550, 561-567, 571-571, 583-600, 611-611, 615-650, 725-725, 729-730, 751-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999

SUBTASK 24-00-00-868-059-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- EQ. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC-AC EXT PWR CTL-No PWR SPLY of A/C electrical circuits from the external power	GAPCU	If at least one power source (IDG 1 or IDG 2, APU GEN or batteries) is connected to the electrical network of the aircraft: In the cockpit, on the ELEC control panel 35VU: - Push and release the EXT PWR P/BSW. If no power source is connected to the electrical network of the aircraft: In the cockpit, on the ELEC control panel 35VU: - Push the BAT 1 P/BSW and the BAT 2 P/BSW (the OFF legend goes off). - Push and release the EXT PWR P/BSW.

SUBTASK 24-00-00-868-1GO-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- ER. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
 If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC APU GEN FAULT	GAPCU	Refer to ECAM procedure.

SUBTASK 24-00-00-868-1GP-A

- CAUTION:** DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
 - THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
 - THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
- IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.**

- ES. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
 If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC APU GEN OVERLOAD	GAPCU	Not permitted.

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-1FO-A

- CAUTION:** DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
 - THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
 - THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- ET. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC BAT 1 FAULT	BCL	Not permitted.

SUBTASK 24-00-00-868-1FP-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- EU. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC BAT 1 OFF	BCL	In the cockpit, on the ELEC control panel 35VU: - Release BAT 1 P/BSW. - Push BAT 1 P/BSW.

SUBTASK 24-00-00-868-1FQ-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

**- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.**

- EV. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC BAT 2 FAULT	BCL	Not permitted.

SUBTASK 24-00-00-868-1FR-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- EW. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC BAT 2 OFF	BCL	In the cockpit, on the ELEC control panel 35VU: - Release BAT 2 P/BSW. - Push BAT 2 P/BSW.

SUBTASK 24-00-00-868-1FS-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- EX. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC BCL 1 FAULT	BCL	Not permitted.

SUBTASK 24-00-00-868-1FT-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- EY. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC BCL 2 FAULT	BCL	Not permitted.

SUBTASK 24-00-00-868-1FU-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- FA. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
 If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC DC BAT BUS FAULT	ELEC	Not permitted.

SUBTASK 24-00-00-868-1FV-A

- CAUTION:** DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
 - THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
 - THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
- IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.**

- FB. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
 If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC DC BUS 1 FAULT	ELEC	Not permitted.

SUBTASK 24-00-00-868-1FW-A

- CAUTION:** DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
 - THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
 - THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
- IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.**

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- FC. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC DC BUS 1+2 FAULT	ELEC	Not permitted.

SUBTASK 24-00-00-868-1FX-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- FD. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC DC BUS 2 FAULT	ELEC	Not permitted.

SUBTASK 24-00-00-868-1FY-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- FE. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC DC EMER CONFIG	ELEC	Not permitted.

SUBTASK 24-00-00-868-1FZ-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- FF. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC DC ESS BUS FAULT	ELEC	Not permitted.

SUBTASK 24-00-00-868-1G0-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- FG. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC DC ESS BUS SHED	ELEC	Not permitted.

SUBTASK 24-00-00-868-1G1-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- FH. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC EMER CONFIG ELEC EMER CONFIG	GCU EMER	Not permitted.

SUBTASK 24-00-00-868-1G2-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- FJ. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
-

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC EMER GEN 1 LINE OFF	GCU EMER	On ELEC control panel 35VU, if the OFF legend of the GEN 1 P/BSW is in to view (OFF legend is on): - Push GEN 1 P/BSW. - The OFF legend of the GEN 1 P/BSW goes out of view (OFF legend goes off).

SUBTASK 24-00-00-868-1G3-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- FK. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC ESS BUSES ON BAT	ELEC	Not permitted.

SUBTASK 24-00-00-868-1G4-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- FL. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC ESS TR FAULT	ELEC	In the avionics compartment, on relay box 103VU: - Push the TR RST P/BSW.

SUBTASK 24-00-00-868-1G5-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- FM. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC GEN 1 FAULT	GCU	Refer to ECAM procedure.

SUBTASK 24-00-00-868-1G6-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- FN. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC GEN 1 OFF	GCU	Not permitted.

SUBTASK 24-00-00-868-1G7-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- FP. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC GEN 1 OVERLOAD	GCU	Not permitted.

SUBTASK 24-00-00-868-1G8-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- FQ. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC GEN 2 FAULT	GCU	Refer to ECAM procedure.

SUBTASK 24-00-00-868-1G9-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- FR. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC GEN 2 OFF	GCU	Not permitted.

SUBTASK 24-00-00-868-1GA-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- FS. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC GEN 2 OVERLOAD	GCU	Not permitted.

SUBTASK 24-00-00-868-1GB-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- FT. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC IDG 1 DISCONNECTED	GCU	Not permitted.

SUBTASK 24-00-00-868-1GC-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- FU. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC IDG 1 FILTER CLOG	GCU	Not permitted.

SUBTASK 24-00-00-868-1GD-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

FV. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC IDG 1 OIL LO LVL	GCU	Not permitted.

SUBTASK 24-00-00-868-1GE-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

FW. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC IDG 1 OIL LO PR	GCU	Not permitted.

SUBTASK 24-00-00-868-1GF-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- FX. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC IDG 1 OIL OVHT	GCU	Not permitted.

SUBTASK 24-00-00-868-1GG-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- FY. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

24	ELEC IDG 2 DISCONNECTED	GCU	Not permitted.
----	-------------------------	-----	----------------

SUBTASK 24-00-00-868-1GH-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- GA. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC IDG 2 FILTER CLOG	GCU	Not permitted.

SUBTASK 24-00-00-868-1GI-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- GB. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC IDG 2 OIL LO LVL	GCU	Not permitted.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

SUBTASK 24-00-00-868-1GJ-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- GC. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC IDG 2 OIL LO PR	GCU	Not permitted.

SUBTASK 24-00-00-868-1GK-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- GD. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC IDG 2 OIL OVHT	GCU	Not permitted.

SUBTASK 24-00-00-868-1GL-A

CAUTION:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- GE. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC STATIC INV FAULT	ELEC	Not permitted.

SUBTASK 24-00-00-868-1GM-A

CAUTION: **DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:**

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- GF. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC TR 1 FAULT	ELEC	In the avionics compartment, on relay box 103VU: - Push the TR RST P/BSW.

SUBTASK 24-00-00-868-1GN-A

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

GG. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
24	ELEC TR 2 FAULT	ELEC	In the avionics compartment, on relay box 103VU: - Push the TR RST P/BSW.

**** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 251-300, 566-566, 605-608, 610-611, 651-709, 712-712, 717-718, 725-725, 729-750, 926-926**
PRE SB 31-1703 for A/C 926-926

EMB SB 23-1157 for A/C 731-731

SUBTASK 24-00-00-868-144-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

GH. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
-----	----------------------------------	-------------------	-----------------

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

25	EQPT/FURN-Inadvertent triggering of the ELT	ELT	Press the ELT TEST/RESET P/B.
----	---	-----	-------------------------------

**** ON A/C FSN 246-250, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-565, 567-567, 571-571, 583-600, 615-650, 751-876, 878-878, 880-880, 882-908, 911-925, 927-951, 953-965, 967-999**

POST SB 31-1703 for A/C 926-926

SUBTASK 24-00-00-868-144-B

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

GH. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
25	EQPT/FURN-Inadvertent triggering of the ELT	ELT	- Set the ELT selector to the TEST/RESET position (or RESET/TEST, depending on the aircraft configuration). - Wait for 3 seconds. - Set the ELT selector to the ARMED position.

**** ON A/C FSN 751-800, 865-876, 882-900, 928-950**

SUBTASK 24-00-00-868-152-B

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- GJ. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
 If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
25	EQPT/FURN-EFB cannot be charged when it is plugged to the cockpit power outlet	Cockpit Static Inverter (CSI)	# Open the C/B 1NA. # After at least 1 second, close the C /B 1NA. # After 15 seconds, make sure that the EFB is charging. <u>NOTE:</u> The reset of the Cockpit Static Inverter (CSI) can be attempted no more than three times.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
121VU	PILOTS OUTLETS/STAT INV	1NA	K25

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-063-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- GK. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
 If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

--	--	--	--

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
26	SMOKE FWD CRG DET FAULT SMOKE LAV+CRG DET FAULT SMOKE AFT CRG DET FAULT SMOKE FWD CRG BTL1 FAULT SMOKE FWD CRG BTL2 FAULT SMOKE AFT CRG BTL1 FAULT SMOKE AFT CRG BTL2 FAULT	CIDS-SDF	Do this procedure in the sequence shown: - Open the C/Bs 18WH and 15WH, - Open the C/Bs 17WH and 14WH, - After 10 seconds, close at the same time the C/Bs 18WH and 15WH, and in less than 2 seconds, close at the same time the C/Bs 17WH and 14WH. - After CIDS reset, approximately 4 minutes are necessary before recovering normal operation.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
** ON A/C FSN 015-050, 108-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 611-611, 615-650, 725-725, 729-730, 751-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999			
49VU	AIR COND/CIDS/SDF/DIR2 ESS	18WH	C06
49VU	AIR COND/CIDS/SDF/DIR1 ESS	15WH	C05
122VU	AIR COND/CIDS/SDF/DIR NORM/2	14WH	T18
122VU	AIR COND/CIDS/SDF/DIR NORM/1	17WH	T17

**** ON A/C FSN 001-009, 011-014, 101-105, 605-608, 610-610, 651-709, 712-712, 717-718, 731-750**

SUBTASK 24-00-00-868-061-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

GL. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
26	SMOKE DET FAULT	SDCU	Open the C/B 11WQ. Open the C/B 12WQ. After 10 seconds, close at the same time the C/B 11WQ and the C/B 12WQ.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
49VU	AIR COND/SDCU/CHAN1	11WQ	C06
122VU	AIR COND/SDCU/CHAN2	12WQ	T18

**** ON A/C FSN 015-050, 106-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 611-611, 615-650, 725-725, 729-730, 751-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999**

SUBTASK 24-00-00-868-061-B

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- GL. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
26	SMOKE DET FAULT	SDCU	

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			Do this procedure in the sequence shown: - Open the C/Bs 18WH and 15WH. - Open the C/Bs 17WH and 14WH. - After 10 seconds, close at the same time the C/Bs 18WH and 15WH, and in less than 2 seconds, close at the same time the C/Bs 17WH and 14WH. - After CIDS reset, approximately 4 minutes are necessary before recovering normal operation.
--	--	--	--

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
** ON A/C FSN 015-050, 108-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 611-611, 615-650, 725-725, 729-730, 751-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999			
49VU	AIR COND/CIDS/SDF/DIR2 ESS	18WH	C06
49VU	AIR COND/CIDS/SDF/DIR1 ESS	15WH	C05
122VU	AIR COND/CIDS/SDF/DIR NORM/2	14WH	T18
122VU	AIR COND/CIDS/SDF/DIR NORM/1	17WH	T17

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-062-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

GM. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
26	SMOKE LAVATORY DET FAULT	With all lavatories declared inoperative on the FAP. CIDS or CIDS-SDF	Do this procedure in the sequence shown: - Open the C/Bs 147RH and 146RH (if installed). - Open the C/Bs 150RH and 157RH, - Open the C/Bs 151RH and 156RH. - After 10 seconds, close the C /Bs 151RH and 156RH. - Close the C/Bs 150RH and 157RH, - Close the C/Bs 147RH and 146RH (if installed). - After CIDS reset, approximately 4 minutes are necessary before recovering normal operation. If unsuccessful, do this procedure in the sequence shown: - Open the C/Bs 18WH and 15WH, - Open the C/Bs 17WH and 14WH, - After 10 seconds, close at the same time the C/Bs 18WH and 15WH, and in less than 2 seconds, close at the same time the C/Bs 17WH and 14WH, - After CIDS reset, approximately 4 minutes are necessary before recovering normal operation.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
49VU	COM/CIDS/DIR 1 AND 2/ESS	150RH	G02

**** ON A/C FSN 001-009, 011-014, 701-709, 712-712, 717-718, 731-750**

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

**** ON A/C FSN 015-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-400, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-700, 725-725, 729-730, 901-908, 911-951, 953-965, 967-999**

49VU	COM/CIDS/DIR ESS/2	157RH	G02
------	--------------------	-------	-----

**** ON A/C FSN 015-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-700, 725-725, 729-730, 801-850, 901-908, 911-951, 953-965, 967-999**

49VU	COM/CIDS/DIR ESS/1	150RH	G01
------	--------------------	-------	-----

**** ON A/C FSN 015-050, 108-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 611-611, 615-650, 725-725, 729-730, 751-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999**

49VU	AIR COND/CIDS/SDF/DIR2 ESS	18WH	C06
49VU	AIR COND/CIDS/SDF/DIR1 ESS	15WH	C05

**** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 801-850**

49VU	COM DIR ESS/2	157RH	G02
------	---------------	-------	-----

**** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900**

49VU	COM NAV/CIDS/DIR2 ESS	157RH	G02
49VU	COM NAV/CIDS/DIR1 ESS	150RH	G01

**** ON A/C FSN 001-009, 011-014, 701-709, 712-712, 717-718, 731-750**

121VU	COM NAV/CIDS/DIR 1 AND 2/NORM	151RH	M05
-------	-------------------------------	-------	-----

**** ON A/C FSN 015-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-400, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-700, 725-725, 729-730, 901-908, 911-951, 953-965, 967-999**

121VU	COM NAV/CIDS/DIR NORM/2	156RH	M06
121VU	COM NAV/CIDS/DIR NORM/1	151RH	M05

**** ON A/C FSN 378-379**

121VU	COM/CIDS/DIR 2/BAT	146RH	P14
121VU	COM/CIDS/DIR 1/BAT	147RH	P13

**** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 801-850**

121VU	COM NAV/CIDS/DIR NORM/2	156RH	M07
-------	-------------------------	-------	-----

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

121VU	COM NAV/CIDS/DIR NORM/1	151RH	M06
-------	-------------------------	-------	-----

**** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900**

121VU	COM NAV/CIDS/DIR2 NORM	156RH	M06
121VU	COM NAV/CIDS/DIR1 NORM	151RH	M05

**** ON A/C FSN 015-050, 108-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 611-611, 615-650, 725-725, 729-730, 751-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999**

122VU	AIR COND/CIDS/SDF/DIR NORM/2	14WH	T18
122VU	AIR COND/CIDS/SDF/DIR NORM/1	17WH	T17

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-27L-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

GN. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
26	APU FIRE	FDU	Not Permitted.

SUBTASK 24-00-00-868-27M-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- GP. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
26	APU FIRE DET FAULT	FDU	Not Permitted.

SUBTASK 24-00-00-868-27N-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- GQ. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
26	APU FIRE LOOP A FAULT	FDU	Not Permitted.

SUBTASK 24-00-00-868-27O-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- GR. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
26	APU FIRE LOOP B FAULT	FDU	Not Permitted.

**** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-709, 712-712, 717-718, 725-725, 729-750, 801-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999**

SUBTASK 24-00-00-868-064-A

WARNING: MAKE SURE THAT THE TRAVEL RANGES OF THE FLIGHT CONTROLS SURFACES ARE CLEAR. MOVEMENT OF FLIGHT CONTROLS CAN CAUSE INJURY TO PERSONS AND/OR DAMAGE TO EQUIPMENT.

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- GS. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
27	F/CTL ELAC 1 PITCH FAULT	ELAC	CAUTION: - Do not reset ELAC in case of dispatch with MMEL item SEC 1 or SEC 2. -

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			Do not attempt more than one reset. - Set ELAC 2 P/B SW to OFF. - Set pitch trim to 5 UP position. - Set ELAC 1 P/B SW to OFF. - After 3 seconds, set ELAC 1 P/B SW to ON. - After 15 seconds, do a check of pitch trim at 0 position. - Do a check of the flight control. - Set ELAC 2 P/B SW to ON. - Set pitch trim to takeoff CG. <u>NOTE:</u> Record the ELAC 1 reset in the logbook (successful or unsuccessful).
--	--	--	--

SUBTASK 24-00-00-868-065-A

WARNING: MAKE SURE THAT THE TRAVEL RANGES OF THE FLIGHT CONTROLS SURFACES ARE CLEAR. MOVEMENT OF FLIGHT CONTROLS CAN CAUSE INJURY TO PERSONS AND/OR DAMAGE TO EQUIPMENT.

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- GT. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
27	F/CTL ELAC 2 PITCH FAULT	ELAC	CAUTION: - Do not reset ELAC in case of dispatch with MMEL item ELAC 1, SEC 1 or SEC 2. - Do not attempt more than one reset.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			- Set ELAC 1 P/B SW to OFF. - Set pitch trim to 5 UP position. - Set ELAC 2 P/B SW to OFF. - After 3 seconds, set ELAC 2 P/B SW to ON. - After 15 seconds, do a check of pitch trim at 0 position. - Do a check of flight control. - Set ELAC 1 P/B SW to ON. - Set pitch trim to takeoff CG. <u>NOTE:</u> Record the ELAC 2 reset in the logbook (successful or unsuccessful).
--	--	--	---

SUBTASK 24-00-00-868-066-A

WARNING: MAKE SURE THAT THE TRAVEL RANGES OF THE FLIGHT CONTROLS SURFACES ARE CLEAR. MOVEMENT OF FLIGHT CONTROLS CAN CAUSE INJURY TO PERSONS AND/OR DAMAGE TO EQUIPMENT.

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- GU. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
27	F/CTL AIL SERVO FAULT	ELAC	CAUTION: - Do not reset ELAC if more than one aileron actuator indication box is displayed in amber on the F/CTL SD page. - Do not reset ELAC in case of dispatch with MMEL item ELAC 1, SEC 1, SEC 2 or SEC 3.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			- Do not attempt more than one reset. - Set ELAC 1 P/B SW to OFF. - Set ELAC 2 P/B SW to OFF. - After 3 seconds, set ELAC 2 P/B SW to ON. - Do a check of flight control. - Set ELAC 2 P/B SW to OFF. - Set ELAC 1 P/B SW to ON. - Do a check of flight control. - Set ELAC 2 P/B SW to ON. - Set pitch trim to takeoff CG. <u>NOTE:</u> Record the ELAC 1 and ELAC 2 reset in the logbook (successful or unsuccessful).
--	--	--	--

SUBTASK 24-00-00-868-067-A

WARNING: MAKE SURE THAT THE TRAVEL RANGES OF THE FLIGHT CONTROLS SURFACES ARE CLEAR. MOVEMENT OF FLIGHT CONTROLS CAN CAUSE INJURY TO PERSONS AND/OR DAMAGE TO EQUIPMENT.

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- GV. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
27	F/CTL SPLR FAULT	SEC	CAUTION: - Do not reset SEC in case of dispatch with MMEL item ELAC 1, SEC 1, SEC 2 or SEC 3.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			- Do not attempt more than one reset. - Set SEC 1 P/B SW to OFF. - After 3 seconds, set SEC 1 P /B SW to ON. - Set SEC 2 P/B SW to OFF. - After 3 seconds, set SEC 2 P /B SW to ON. - Set SEC 3 P/B SW to OFF. - After 3 seconds, set SEC 3 P /B SW to ON. - Do a check of flight control. <u>NOTE:</u> Record the SEC 1, SEC 2 and SEC 3 reset in the logbook (successful or unsuccessful).
--	--	--	--

**** ON A/C FSN 751-800**

SUBTASK 24-00-00-868-064-B

WARNING: MAKE SURE THAT THE TRAVEL RANGES OF THE FLIGHT CONTROLS SURFACES ARE CLEAR. MOVEMENT OF FLIGHT CONTROLS CAN CAUSE INJURY TO PERSONS AND/OR DAMAGE TO EQUIPMENT.

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- GS. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
27	F/CTL ELAC 1 PITCH FAULT	ELAC	CAUTION: - Do not reset ELAC in case of dispatch with MMEL item SEC 1.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			- Do not attempt more than one reset. - Set ELAC 2 P/B SW to OFF. - Set pitch trim to 5 UP position. - Set ELAC 1 P/B SW to OFF. - Wait for 3 seconds. - Set ELAC 1 P/B SW to ON. - After 15 seconds, do a check of pitch trim at 0 position. - Do a check of the flight control. - Set ELAC 2 P/B SW to ON. - Set pitch trim to takeoff CG. <u>NOTE:</u> Record the ELAC 1 reset in the logbook (successful or unsuccessful).
--	--	--	--

SUBTASK 24-00-00-868-065-B

WARNING: MAKE SURE THAT THE TRAVEL RANGES OF THE FLIGHT CONTROLS SURFACES ARE CLEAR. MOVEMENT OF FLIGHT CONTROLS CAN CAUSE INJURY TO PERSONS AND/OR DAMAGE TO EQUIPMENT.

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

GT. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
27	F/CTL ELAC 2 PITCH FAULT	ELAC	CAUTION: - Do not reset ELAC in case of dispatch with MMEL item ELAC 1 or SEC 1. - Do not attempt more than one reset. - Set ELAC 1 P/B SW to OFF.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			- Set pitch trim to 5 UP position. - Set ELAC 2 P/B SW to OFF. - Wait for 3 seconds. - Set ELAC 2 P/B SW to ON. - After 15 seconds, do a check of pitch trim at 0 position. - Do a check of flight control. - Set ELAC 1 P/B SW to ON. - Set pitch trim to takeoff CG. <u>NOTE:</u> Record the ELAC 2 reset in the logbook (successful or unsuccessful).
--	--	--	--

SUBTASK 24-00-00-868-066-B

WARNING: MAKE SURE THAT THE TRAVEL RANGES OF THE FLIGHT CONTROLS SURFACES ARE CLEAR. MOVEMENT OF FLIGHT CONTROLS CAN CAUSE INJURY TO PERSONS AND/OR DAMAGE TO EQUIPMENT.

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- GU. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
27	F/CTL AIL SERVO FAULT	ELAC	CAUTION: - Do not reset ELAC if more than one aileron actuator indication box is displayed in amber on the F/CTL SD page. - Do not reset ELAC in case of dispatch with MMEL item ELAC 1 or SEC 1. - Do not attempt more than one reset.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			- Set ELAC 1 P/B SW to OFF. - Set ELAC 2 P/B SW to OFF. - Wait for 3 seconds. - Set ELAC 2 P/B SW to ON. - Do a check of flight control. - Set ELAC 2 P/B SW to OFF. - Set ELAC 1 P/B SW to ON. - Do a check of flight control. - Set ELAC 2 P/B SW to ON. - Set pitch trim to takeoff CG. <u>NOTE:</u> Record the ELAC 1 and ELAC 2 resets in the logbook (successful or unsuccessful).
--	--	--	--

SUBTASK 24-00-00-868-067-B

WARNING: MAKE SURE THAT THE TRAVEL RANGES OF THE FLIGHT CONTROLS SURFACES ARE CLEAR. MOVEMENT OF FLIGHT CONTROLS CAN CAUSE INJURY TO PERSONS AND/OR DAMAGE TO EQUIPMENT.

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

GV. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
27	F/CTL SPLR FAULT	SEC or ELAC	CAUTION: - Do not reset SEC in case of dispatch with MMEL item ELAC 1 or SEC 1. - Do not attempt more than one reset. - Set SEC 1 P/B SW to OFF. - Wait for 3 seconds.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			- Set SEC 1 P/B SW to ON. - Set SEC 2 P/B SW to OFF. - Wait for 3 seconds. - Set SEC 2 P/B SW to ON. - Set ELAC 2 P/B SW to OFF. - Wait for 3 seconds. - Set ELAC 2 P/B SW to ON. - Do a check of flight control. <u>NOTE:</u> Record the SEC 1, SEC 2 and ELAC 2 resets in the logbook (successful or unsuccessful).
--	--	--	---

**** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-400, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-709, 712-712, 717-718, 725-725, 729-750, 901-908, 911-951, 953-965, 967-999**

SUBTASK 24-00-00-868-068-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

GW. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
28	FUEL-Loss of quantity indication FUEL-Simultaneous triggering of FUEL L XFR VALVE CLOSED and FUEL R XFR VALVE CLOSED although FUEL SD indicates no anomaly FUEL-Simultaneous triggering of FUEL L OUTER XFR CLOSED and FUEL R OUTER XFR	FQIC	Open the C/B 1QT. Open the C/B 2QT. Open the C/B 8QT. After 5 seconds, close the C/B 1QT. Close the C/B 2QT. Close the C/B 8QT. <u>NOTE:</u> The fuel quantity indication is available after 1 minute.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

	CLOSED although FUEL SD indicates no anomaly		
--	--	--	--

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
49VU	FUEL/FQI/CHAN/1	1QT	A13
121VU	FUEL/FQI/CHANNEL/1 AND 2	8QT	L26
121VU	FUEL/FQI/CHAN/2	2QT	M27

**** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 751-876, 878-878, 880-880, 882-900**

SUBTASK 24-00-00-868-068-B

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

GW. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
28	FUEL-Loss of quantity indication	FQIC	Open the C/B 1QT. Open the C/B 2QT. After 5 seconds, close the C/B 1QT. Close the C/B 2QT. <u>NOTE:</u> The fuel quantity indication is available after 1 minute.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
49VU	FUEL/FQI/CHAN/1	1QT	A13
121VU	FUEL/FQI/CHAN/2	2QT	M27

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-21G-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- GX. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD B ELEC PUMP LO PR	N/A	Not permitted.

SUBTASK 24-00-00-868-21H-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- GY. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD B ELEC PUMP OVHT	N/A	Not permitted.

SUBTASK 24-00-00-868-21I-A

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- HA. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD B RSVR LO AIR PR	N/A	Not permitted.

SUBTASK 24-00-00-868-21J-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- HB. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD B RSVR LO LVL	N/A	Not permitted.

SUBTASK 24-00-00-868-21K-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- HC. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD B RSVR OVHT	N/A	Not permitted.

SUBTASK 24-00-00-868-21L-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- HD. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD B SYS LO PR	N/A	Not permitted.

SUBTASK 24-00-00-868-21M-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

**- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.**

- HE. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD B+Y SYS LO PR	N/A	Not permitted.

SUBTASK 24-00-00-868-21N-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- HF. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD G ENG 1 PUMP LO PR	N/A	Not permitted.

SUBTASK 24-00-00-868-21O-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- HG. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD G RSVR LO AIR PR	N/A	Not permitted.

SUBTASK 24-00-00-868-21P-A

- CAUTION:** DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
 - THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
 - THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
- IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.**

- HH. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD G RSVR LO LVL	N/A	Not permitted.

SUBTASK 24-00-00-868-21Q-A

- CAUTION:** DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
 - THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
 - THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
- IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.**

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- HJ. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD G RSVR OVHT	N/A	Not permitted.

SUBTASK 24-00-00-868-21R-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- HK. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD G SYS LO PR	N/A	Not permitted.

SUBTASK 24-00-00-868-21S-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- HL. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD G+B SYS LO PR	N/A	Not permitted.

SUBTASK 24-00-00-868-21T-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- HM. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD G+Y SYS LO PR	N/A	Not permitted.

SUBTASK 24-00-00-868-21U-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- HN. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD PTU FAULT	N/A	Not permitted.

SUBTASK 24-00-00-868-21V-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- HP. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD RAT FAULT	N/A	Not permitted.

SUBTASK 24-00-00-868-21W-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- HQ. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD Y ELEC PUMP LO PR	N/A	Not permitted.

SUBTASK 24-00-00-868-21X-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- HR. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD Y ELEC PUMP OVHT	N/A	Not permitted.

SUBTASK 24-00-00-868-21Y-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- HS. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD Y ENG 2 PUMP LO PR	N/A	Not permitted.

SUBTASK 24-00-00-868-21Z-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- HT. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD Y RSVR LO AIR PR	N/A	Not permitted.

SUBTASK 24-00-00-868-220-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- HU. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

29	HYD Y RSVR LO LVL	N/A	Not permitted.
----	-------------------	-----	----------------

SUBTASK 24-00-00-868-221-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- HV. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD Y RSVR OVHT	N/A	Not permitted.

SUBTASK 24-00-00-868-222-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- HW. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
29	HYD Y SYS LO PR	N/A	Not permitted.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

SUBTASK 24-00-00-868-069-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

HX. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
30	ANTI ICE L WINDSHIELD ANTI ICE L WINDOW ANTI ICE R WINDSHIELD ANTI ICE R WINDOW	WHC	If the air conditioning packs are OFF with the OAT above 40 deg.C, and/or the windshield is under direct sunlight, a spurious ANTI ICE L(R) WINDSHIELD(WINDOW) may trigger. In that case: - Set both air conditioning packs to ON, - After 5 minutes: * For the WHC 1: ** Open the C/B 5DG1, ** Close the C/B 5DG1. * For the WHC 2: ** Open the C/B 5DG2, ** Close the C/B 5DG2.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
122VU	ANTI ICE/WHC/2	5DG2	W13
122VU	ANTI ICE/WHC/1	5DG1	X13

SUBTASK 24-00-00-868-070-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

**- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A
RESET THAT IS NOT PERMITTED.**

- HY. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
31	FWS FWC 1 FAULT FWS FWC 2 FAULT	FWC	For the FWC 1: - Open the C/B 3WW, - Close the C/B 3WW. For the FWC 2: - Open the C/B 2WW, - Close the C/B 2WW. 50 seconds are necessary after you close the C/Bs.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
49VU	FWS/FWC1/SPLY	3WW	F01
121VU	EIS/FWC2/SPLY	2WW	Q07

**** ON A/C FSN ALL**

EMB SB 32-1346 for A/C 001-009, 011-018, 101-115, 501-501, 503-504, 506-506, 508-508, 561-567, 571-571, 605-608, 610-611, 615-616, 651-651, 701-709, 712-712, 717-718, 725-725, 729-731, 801-803

SUBTASK 24-00-00-868-071-B

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- JA. If it is obvious that this system malfunction or ECAM alert is consecutive to an electrical power up or transient, then the reset may be performed.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If this system malfunction or ECAM alert is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed.
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

AT A	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
32	L/G LGCIU 1 FAULT L/G LGCIU 2 FAULT	LGCIU	<u>WARNING:</u> DO NOT TOUCH THE PROBES DURING OR IMMEDIATELY AFTER THIS PROCEDURE. THE PROBES WILL BE HOT AND CAN BURN YOU. <u>CAUTION:</u> REMOVE THE PROTECTIVE COVERS FROM THE PROBES BEFORE YOU DO THIS PROCEDURE. IF YOU DO NOT REMOVE THEM, THE PROBES AND PROTECTIVE COVERS CAN BECOME DAMAGED OR BURNED. Make sure that the protective covers on the probes are removed Ref. AMM 10-11-00-555-014. Depressurize the Green hydraulic system: - ENG 1 PUMP OFF - PTU OFF. When there is no Green hydraulic pressure: If the ELT-DT is installed, do the deactivation for maintenance Ref. AMM 31-39-00-040-805. To reset LGCIU1, do the steps that follow: - Open C/B 52GA. - Open C/B 1GA. - Open C/B 58GA. - Wait for 15 seconds. - Close C/B 58GA. - Close C/B 1GA. - Close C/B 52GA. To reset LGCIU2, do the steps that follow: - Open C/B 2GA. - Open C/B 59GA. - Wait for 15 seconds. - Close C/B 59GA. - Close C/B 2GA. After the LGCIU reset, pressurize the Green hydraulic system: - ENG 1 PUMP ON - PTU AUTO.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

		If you deactivated the ELT-DT, activate it again after maintenance Ref. AMM 31-39-00-440-805 .
--	--	--

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
-------	-------------	-----	----------

**** ON A/C FSN ALL**

49VU	L/G/LGCIU/SYS1	1GA	C09
------	----------------	-----	-----

**** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-709, 712-712, 717-718, 725-725, 729-750, 801-850, 901-908, 911-951, 953-965, 967-999**

EMB SB 32-1346 for A/C 001-009, 011-018, 101-115, 501-501, 503-504, 506-506, 508-508, 561-567, 571-571, 605-608, 610-611, 615-616, 651-651, 701-709, 712-712, 717-718, 725-725, 729-731, 801-803

121VU	LGCIU/BAT SPLY/SYS2	59GA	R33
121VU	LGCIU/BAT SPLY/SYS1	58GA	R32

**** ON A/C FSN ALL**

121VU	HYDRAULIC/LGCIU/SYS2	2GA	Q35
121VU	HYDRAULIC/LGCIU/SYS1/GRND SPLY	52GA	Q34

**** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900**

121VU	LGCIU/BAT SPLY/SYS2	59GA	R32
121VU	LGCIU/BAT SPLY/SYS1	58GA	R31

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-073-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

JB. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

-

JCP Title: Resets	© AIRBUS S.A.S. ALL RIGHTS RESERVED. CONFIDENTIAL AND PROPRIETARY DOCUMENT.	Page 145 of 206 PRINT DATE: Aug 16/2026
-------------------	--	--

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
32	BRAKES SYS 1 FAULT BRAKES BSCU CH1 FAULT BRAKES SYS 2 FAULT BRAKES BSCU CH2 FAULT BRAKES BSCU CH1 FAULT BRAKES BSCU CH2 FAULT	BSCU	Reset Procedure: - STOP aircraft, - Set PARK BRK handle to ON, - Confirm the towing bar is disconnected, - Set A/SKID & N/W STRG SW to OFF, - Set A/SKID & N/W STRG SW to ON, - If unsuccessful: * Open the C/B 2GG and 1GG * Open the C/B 4GG and 2GG * Close the C/B 2GG, 1GG, 4GG and 2GG. After a successful reset, resume to normal operation. After any BSCU reset: - Do a check of the brake efficiency, - Record the BSCU reset in the logbook.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
121VU	HYDRAULIC/BRAKING AND STEERING/SYS2/SPLY	4GG	M36
121VU	HYDRAULIC/BRAKING AND STEERING/SYS2/CTL	3GG	M35
121VU	HYDRAULIC/BRAKING AND STEERING/SYS1/CTL	1GG	M34
121VU	HYDRAULIC/BRAKING AND STEERING/SYS1/IND AND/SPLY	2GG	M33

SUBTASK 24-00-00-868-072-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
 - THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
 - THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
- IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.**

JC. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
32	WHEEL N.W STEER FAULT WHEEL N/W STRG FAULT	BSCU	Case A: If the three conditions below are fulfilled: - the WHEEL N/W STRG FAULT alert was triggered just after the engine start - the N/W STRG DISC memo was displayed before the start of the pushback (before the aircraft starts moving) - the N/W STRG DISC memo remained displayed even after the pushback is finished (nosewheel steering selector bypass pin is in the steering position). Apply the below reset procedure. If the ECAM alert disappears after the reset, the flight crew may continue the flight without troubleshooting. Case B: In all other cases, including in case of doubt on the above conditions, troubleshooting must be performed before continuing the flight. Reset Procedure: - STOP aircraft, - Set PARK BRK handle to ON, - Confirm the towing bar is disconnected, -

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			Set A/SKID & N/W STRG SW to OFF, - Set A/SKID & N/W STRG SW to ON. After any BSCU reset: - Do a check of brake efficiency, - Do a check of absence of aircraft veering, - Record the BSCU reset in the logbook.
--	--	--	--

SUBTASK 24-00-00-868-084-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- JD. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
34	NAV-STBY-ISIS malfunction	ISIS	In aircraft without movement: - Open circuit breaker 5FN. - After five seconds, close circuit breaker 5FN. - Normal operation is possible after approximately two minutes. - After ISIS reset, approximately two minutes are necessary before you start the normal operation. NOTE: If there is a small aircraft movement during the circuit breaker reset (refueling, cargo loading conditions or

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			other conditions), the ATT red flag comes into view on the ISIS. In this condition, push the RST pushbutton for two seconds and wait for two minutes before you start the normal operation.
--	--	--	---

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
** ON A/C FSN 001-009, 011-014, 101-105, 605-608, 610-610, 701-709, 712-712, 717-718, 731-750			
49VU	NAV/STBY/HORIZON	5FN	F12
** ON A/C FSN 015-050, 106-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 611-611, 615-700, 725-725, 729-730, 751-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999			
49VU	NAV/STBY/INST	5FN	F12

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-086-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- JE. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
34	NAV TCAS FAULT	TCAS or T2CAS or T/TISS	For the applicable C/Bs only shown in the C/B table: - Open the C/B 4SG or 104SG or 1004SG or 2004SG. -

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			After 5 seconds, close the C/B 4SG or 104SG or 1004SG or 2004SG.
--	--	--	--

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
-------	-------------	-----	----------

**** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 381-425, 427-428, 430-433, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-700, 712-712, 717-718, 725-725, 729-750, 801-872, 878-878, 880-880, 901-908, 911-925, 930-951, 953-965, 967-999**

121VU	COM NAV/TCAS	4SG	K10
-------	--------------	-----	-----

**** ON A/C FSN 378-379, 435-450, 751-800, 873-876, 882-900, 926-929**

121VU	T/TISS	2004SG	K07
-------	--------	--------	-----

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-087-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

JF. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
34	NAV GPWS FAULT AND NAV GPWS TERR DET FAULT	GPWC	Open the C/B 3WZ. Set GPWS SYS P/B and GPWS TERR P/B to ON. After 5 seconds, close the C/B 3WZ.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
-------	-------------	-----	----------

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

**** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 381-425, 427-428, 430-433, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-709, 712-712, 717-718, 725-725, 729-750, 801-872, 878-878, 880-880, 901-908, 911-925, 930-951, 953-965, 967-999**

121VU	EIS/GPWS/115VAC	3WZ	P07
-------	-----------------	-----	-----

**** ON A/C FSN 751-800, 873-876, 882-900, 926-929**

SUBTASK 24-00-00-868-112-B

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- JG. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
34	NAV ATC/XPDR 1+2 FAULT	XPDR	- Open C/B 5SH1 and C/B 5SH2. - Wait for 5 seconds. - Close C/B 5SH2 and C/B 5SH1.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
49VU	NAV/ATC/1	5SH1	G11

**** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-650, 701-709, 712-712, 717-718, 725-725, 729-730, 751-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999**

SUBTASK 24-00-00-868-139-A

CAUTION:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

JH. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
34	NAV GLS 1 FAULT NAV GLS 2 FAULT NAV LS 1 FAULT NAV LS 2 FAULT NAV LS 1+2 FAULT	MMR	<u>NOTE:</u> - Do not attempt to reset MMR1 or MMR2 during the approach or RNP AR operations. - If the flight crew suspects interference on GPS, the flight crew should apply the reset of the MMRs after the interference area. If side 1 is affected, in the cockpit, on the overhead panel 49VU: - Open C/B 42RT1. - Wait more than 10 seconds, then close C/B 42RT1. If side 2 is affected, in the cockpit, on the rear maintenance panel 121VU : - Open C/B 42RT2. - Wait more than 10 seconds, then close C/B 42RT2. <u>NOTE:</u> On some aircraft C/B 42RT2 is located in the K09, on the rear maintenance panel 121VU.

Table of the Circuit Breakers Used in This Procedure

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

PANEL	DESIGNATION	FIN	LOCATION
-------	-------------	-----	----------

**** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-650, 701-709, 712-712, 717-718, 725-725, 729-730, 801-850, 878-878, 880-880, 901-908, 911-915, 951-951, 953-965, 967-999**

49VU	NAV/MMR/1	42RT1	G12
------	-----------	-------	-----

**** ON A/C FSN 751-800, 851-876, 882-900, 916-950**

49VU	NAV/MMR/VOR/1	42RT1	G12
------	---------------	-------	-----

**** ON A/C FSN 701-702
PRE SB 92-1093 for A/C 702-702**

121VU	COM NAV/MMR/2	42RT2	K09
-------	---------------	-------	-----

**** ON A/C FSN 751-800**

121VU	MMR/VOR/2	42RT2	K03
-------	-----------	-------	-----

**** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-650, 703-709, 712-712, 717-718, 725-725, 729-730, 801-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999
POST SB 92-1093 for A/C 702-702**

121VU	COM NAV/MMR/2	42RT2	L07
-------	---------------	-------	-----

**** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-709, 712-712, 717-718, 725-725, 729-750, 801-850**

SUBTASK 24-00-00-868-076-B

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

JJ. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE

	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

36	AIR ENG 1 BLEED FAULT	BMC	- Do not try more than one reset. - If the PACK (non-affected side) is operative, and if the wing anti-ice is OFF: - ENG BLEED (affected side).... OFF. - If the ENG BLEED (affected side) pushbutton switch FAULT light is on: - Delay application of the reset until FAULT light goes off. - If the ENG BLEED (affected side) pushbutton switch FAULT light is off: - X BLEED..... AUTO - PACK (affected side)..... ON - ENG BLEED (affected side).. ON - Make sure that the affected engine bleed valve is open on the SD "BLEED" page. - If the AIR ENG (AFFECTED) BLEED FAULT alert occurs again, or if the engine bleed valve (affected side) is not open on the SD "BLEED" page: - ENG BLEED (affected side).... OFF - X BLEED..... OPEN. NOTE: You can record the ENG BLEED reset in the logbook (successful or unsuccessful).
----	-----------------------	-----	--

SUBTASK 24-00-00-868-1GR-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

JK. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

--	--	--	--

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 2 BLEED FAULT	BMC	- Do not try more than one reset. - If the PACK (non-affected side) is operative, and if the wing anti-ice is OFF: - ENG BLEED (affected side).... OFF. - If the ENG BLEED (affected side) pushbutton switch FAULT light is on: - Delay application of the reset until FAULT light goes off. - If the ENG BLEED (affected side) pushbutton switch FAULT light is off: - X BLEED..... AUTO - PACK (affected side)..... ON - ENG BLEED (affected side).. ON - Make sure that the affected engine bleed valve is open on the SD "BLEED" page. - If the AIR ENG (AFFECTED) BLEED FAULT alert occurs again, or if the engine bleed valve (affected side) is not open on the SD "BLEED" page: - ENG BLEED (affected side).... OFF - X BLEED..... OPEN NOTE: You can record the ENG BLEED reset in the logbook (successful or unsuccessful).

**** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999**

SUBTASK 24-00-00-868-076-G

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

JJ. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 1 BLEED FAULT	BMC	- Do not try more than one reset. - If the PACK (non-affected side) is operative, and if the wing anti-ice is OFF: - ENG BLEED (affected side).... OFF. - If the ENG BLEED (affected side) pushbutton switch FAULT light is on: - Delay application of the reset until FAULT light goes off. - If the ENG BLEED (affected side) pushbutton switch FAULT light is off: - X BLEED..... - AUTO - PACK (affected side)..... ON - ENG BLEED (affected side).. ON - Make sure that the affected engine bleed valve is open on the SD "BLEED" page. - If the AIR ENG (AFFECTED) BLEED FAULT alert occurs again, or if the engine bleed valve (affected side) is not open on the SD "BLEED" page: - ENG BLEED (affected side).... OFF - PACK (affected side).....OFF - X BLEED..... OPEN NOTE: You can record the ENG BLEED reset in the logbook (successful or unsuccessful).

SUBTASK 24-00-00-868-1GR-B

CAUTION:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- **THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND**
- **THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR**
- **THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.**

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

JK. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 2 BLEED FAULT	BMC	- Do not try more than one reset. - If the PACK (non-affected side) is operative, and if the wing anti-ice is OFF: - ENG BLEED (affected side).... OFF. - If the ENG BLEED (affected side) pushbutton switch FAULT light is on: - Delay application of the reset until FAULT light goes off. - If the ENG BLEED (affected side) pushbutton switch FAULT light is off: - X BLEED..... - AUTO - PACK (affected side)..... ON - ENG BLEED (affected side).. ON - Make sure that the affected engine bleed valve is open on the SD "BLEED" page. - If the AIR ENG (AFFECTED) BLEED FAULT alert occurs again, or if the engine bleed valve (affected side) is not open on the SD "BLEED" page: - ENG BLEED (affected side).... OFF - PACK (affected side).....OFF - X BLEED..... OPEN <u>NOTE:</u>

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			You can record the ENG BLEED reset in the logbook (successful or unsuccessful).
--	--	--	---

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-154-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

JL. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 1 BLEED FAULT // BLEED NOT CLOSED	BMC	Not permitted.

SUBTASK 24-00-00-868-1GT-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

JM. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 2 BLEED FAULT // BLEED NOT CLOSED	BMC	Not permitted.

SUBTASK 24-00-00-868-155-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
 IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A
 RESET THAT IS NOT PERMITTED.

JN. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 1+2 BLEED FAULT	BMC	Refer to ECAM procedure.

SUBTASK 24-00-00-868-156-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
 - THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
 - THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
 - THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
 IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A
 RESET THAT IS NOT PERMITTED.

JP. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 1+2 BLEED FAULT // LEFT LEAK	BMC	Not permitted.

SUBTASK 24-00-00-868-157-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
 - THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
 - THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
 - THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
 IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A
 RESET THAT IS NOT PERMITTED.

JQ. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
TBD	AIR ENG 1+2 BLEED FAULT // RIGHT LEAK	BMC	Not permitted.

SUBTASK 24-00-00-868-158-A

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

JR. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 1+2 BLEED FAULT // LEFT LEAK // RIGHT LEAK	BMC	Not permitted.

SUBTASK 24-00-00-868-159-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

JS. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 1 BLEED HI TEMP	BMC	Not permitted.

SUBTASK 24-00-00-868-160-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

JT. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 2 BLEED HI TEMP	BMC	Not permitted.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

SUBTASK 24-00-00-868-161-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

JU. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 1 BLEED LO TEMP	BMC	Not permitted.

SUBTASK 24-00-00-868-162-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

JV. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
TBD	AIR ENG 2 BLEED LO TEMP	BMC	Not permitted.

SUBTASK 24-00-00-868-163-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

JW. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
-----	----------------------------------	-------------------	-----------------

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

TBD	AIR ENG1+2 BLEED LO TEMP	BMC	Not permitted.
-----	--------------------------	-----	----------------

SUBTASK 24-00-00-868-1GQ-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

JX. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 1 BLEED ABNORM PR	BMC	- If the PACK (non-affected side) is operative, and if the wing anti-ice is OFF: - ENG BLEED (affected side).... OFF. - If the ENG BLEED (affected side) pushbutton switch FAULT light is on: - Delay application of the reset until FAULT light goes off. - If the ENG BLEED (affected side) pushbutton switch FAULT light is off: - X BLEED..... - AUTO - PACK (affected side)..... - ON - ENG BLEED (affected side).. - ON - Make sure that the affected engine bleed valve is open on the SD "BLEED" page. - If the AIR ENG (AFFECTED) BLEED ABNORM PR alert occurs again, or if the engine bleed valve (affected side) is not open on the SD "BLEED" page: - ENG BLEED (affected side).....OFF - PACK (affected side)..... OFF - X BLEED..... - OPEN.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			<u>NOTE:</u> You can record the ENG BLEED reset in the logbook (successful or unsuccessful).
--	--	--	--

SUBTASK 24-00-00-868-1GS-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

JY. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG2 BLEED ABNORM PR	BMC	- If the PACK (non-affected side) is operative, and if the wing anti-ice is OFF: - ENG BLEED (affected side).... OFF. - If the ENG BLEED (affected side) pushbutton switch FAULT light is on: - Delay application of the reset until FAULT light goes off. - If the ENG BLEED (affected side) pushbutton switch FAULT light is off: - X BLEED..... - AUTO - PACK (affected side)..... ON - ENG BLEED (affected side).. ON - Make sure that the affected engine bleed valve is open on the SD "BLEED" page. - If the AIR ENG (AFFECTED) BLEED ABNORM PR alert occurs again, or if the engine bleed valve (affected side) is not open on the SD "BLEED" page: - ENG BLEED (affected side).....OFF - PACK (affected side)..... OFF

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			- X BLEED..... OPEN. <u>NOTE:</u> You can record the ENG BLEED reset in the logbook (successful or unsuccessful).
--	--	--	---

SUBTASK 24-00-00-868-077-C

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

KA. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 1 BLEED NOT CLSD	BMC	- Do not try more than one reset. - ENG BLEED (affected side).....OFF. - If the ENG BLEED (affected side) pushbutton switch FAULT light is on: - Delay application of the reset until FAULT light goes off. - If the ENG BLEED (affected side) pushbutton switch FAULT light is off: - ENG BLEED (affected side).....ON. - Make sure that the affected engine bleed valve is closed on the SD "BLEED" page. <u>NOTE:</u> You can record the ENG BLEED reset in the logbook (successful or unsuccessful).

SUBTASK 24-00-00-868-1GU-A

CAUTION:

JCP Title: Resets	© AIRBUS S.A.S. ALL RIGHTS RESERVED. CONFIDENTIAL AND PROPRIETARY DOCUMENT.	Page 164 of 206 PRINT DATE: Aug 16/2026
-------------------	--	--

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

KB. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 2 BLEED NOT CLSD	BMC	- Do not try more than one reset. - ENG BLEED (affected side).....OFF. - If the ENG BLEED (affected side) pushbutton switch FAULT light is on: - Delay application of the reset until FAULT light goes off. - If the ENG BLEED (affected side) pushbutton switch FAULT light is off: - ENG BLEED (affected side).....ON. - Make sure that the affected engine bleed valve is closed on the SD "BLEED" page. <u>NOTE:</u> You can record the ENG BLEED reset in the logbook (successful or unsuccessful).

SUBTASK 24-00-00-868-164-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

KC. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

--	--	--	--

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 1 HP VALVE FAULT	BMC	Not permitted.

SUBTASK 24-00-00-868-165-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

KD. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 2 HP VALVE FAULT	BMC	Not permitted.

SUBTASK 24-00-00-868-166-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

KE. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR BLEED 1 OFF	BMC	NOTE: This alert triggers when the ENG 1 BLEED pushbutton switch is abnormally set to OFF. Do not reset if MMEL is applied to the ENG 1 BLEED. Do not try more than one reset. - ENG BLEED 1 ON NOTE: You can record the ENG BLEED reset in the

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			logbook (successful or unsuccessful).
--	--	--	---------------------------------------

SUBTASK 24-00-00-868-167-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

KF. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR BLEED 2 OFF	BMC	NOTE: This alert triggers when the ENG 2 BLEED pushbutton switch is abnormally set to OFF. Do not reset if MMEL is applied to the ENG 2 BLEED. Do not try more than one reset. - ENG BLEED 2 ON NOTE: You can record the ENG BLEED reset in the logbook (successful or unsuccessful).

SUBTASK 24-00-00-868-168-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

KG. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR X BLEED FAULT	BMC	Not permitted.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

SUBTASK 24-00-00-868-169-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

KH. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR APU BLEED FAULT	BMC	Not permitted.

**** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999**

SUBTASK 24-00-00-868-170-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

KJ. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR BLEED LEAK	BMC	Not permitted.

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-171-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

KK. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR L WING LEAK	BMC	Not permitted.

SUBTASK 24-00-00-868-172-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

KL. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR R WING LEAK	BMC	Not permitted.

SUBTASK 24-00-00-868-173-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

KM. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 1 BLEED LEAK	BMC	Not permitted.

SUBTASK 24-00-00-868-174-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

KN. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 2 BLEED LEAK	BMC	Not permitted.

SUBTASK 24-00-00-868-175-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

KP. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR APU BLEED LEAK or AIR APU BLEED LEAK or AIR APU BLEED LEAK	BMC	Not permitted.

SUBTASK 24-00-00-868-177-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

KQ. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR L WNG LEAK DET FAULT	BMC	Not permitted.

SUBTASK 24-00-00-868-178-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

KR. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR R WNG LEAK DET FAULT	BMC	Not permitted.

SUBTASK 24-00-00-868-179-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

KS. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 1 LEAK DET FAULT	BMC	Not permitted.

SUBTASK 24-00-00-868-180-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

KT. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR ENG 2 LEAK DET FAULT	BMC	Not permitted.

SUBTASK 24-00-00-868-181-A

CAUTION:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- KU. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	AIR APU LEAK DET FAULT	BMC	Not permitted.

SUBTASK 24-00-00-868-182-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- KV. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	BLEED MONIT SYS 1 FAULT	BMC	Not permitted.

SUBTASK 24-00-00-868-183-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- KW. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	BLEED MONIT SYS 2 FAULT	BMC	Not permitted.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

SUBTASK 24-00-00-868-184-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

KX. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
36	BLEED MONITORING FAULT	BMC	Not permitted.

SUBTASK 24-00-00-868-111-A
DELETED

**** ON A/C FSN 001-009, 011-014, 101-105, 605-608, 610-610, 651-709, 712-712, 717-718, 731-750**

SUBTASK 24-00-00-868-121-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

KY. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
38	WATER/WASTE-TOILET SYS-Failure messages on CIDS FAP in the cabin (VSC)	VSC	- Open C/B 35MG on 2001VU (aft cabin). - Wait for 30 seconds. - Close C/B 35MG on 2001VU (aft cabin).

Table of the Circuit Breakers Used in This Procedure

--	--	--

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

PANEL	DESIGNATION	FIN	LOCATION
-------	-------------	-----	----------

**** ON A/C FSN 001-009, 011-014, 651-709, 712-712, 717-718**

2001VU	VACU TOIL SYS-VACU-SYS	35MG	A06
--------	------------------------	------	-----

**** ON A/C FSN 101-105, 605-608, 610-610**

2001VU	VACU TOIL SYS-VACUUM-SYS	35MG	A06
--------	--------------------------	------	-----

**** ON A/C FSN 731-750**

2001VU	VACU TOIL SYS-VACU-SYS	35MG	B06
--------	------------------------	------	-----

**** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-709, 712-712, 717-718, 725-725, 729-730, 751-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999**

SUBTASK 24-00-00-868-097-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

LA. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
46	INFO SYS-ATIMS-ATSU malfunction	ATSU	The ATSU reset should be attempted only if: - INVALID DATA is displayed on the DCDU, or - key selection has no effect on the DCDU or any of the MCDU ATSU DATALINK submenus, or - ADS-C, CPDLC or AOC are inoperative. Open the C/B 3TX1.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

		Open the C/B 5TX1. After 5 seconds close the C/B 5TX1. Close the C/B 3TX1.
--	--	--

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-425, 427-428, 430-433, 435-450, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-709, 712-712, 717-718, 725-725, 729-730, 801-850, 901-908, 911-951, 953-965, 967-999			
121VU	ATSU 1	3TX1	L16
121VU	ATSU 1/SWTG	5TX1	L15
** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900			
121VU	ATSU 1	3TX1	K43
121VU	ATSU 1/SWTG	5TX1	K42

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-27J-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LB. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
49	APU AUTO SHUT DOWN	ECB	Not permitted.

SUBTASK 24-00-00-868-27K-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LC. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
49	APU EMER SHUT DOWN	ECB	Not permitted.

SUBTASK 24-00-00-868-23K-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LD. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR AFT AVIONICS	DOOR	- Open C/B 46WV. - Wait for 5 seconds. - Close C/B 46WV.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
121VU	EIS/SDAC1 AND 2/DOOR/DET /AVNCS	46WV	P02

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

SUBTASK 24-00-00-868-23L-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LE. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR AFT CARGO	DOOR	Not permitted.

SUBTASK 24-00-00-868-23M-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LF. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR BULK CARGO	DOOR	- Open C/B 46WV. - Wait for 5 seconds. - Close C/B 46WV.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
-------	-------------	-----	----------

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

121VU	EIS/SDAC1 AND 2/DOOR/DET /AVNCS	46WV	P02
-------	---------------------------------	------	-----

SUBTASK 24-00-00-868-23N-A

- CAUTION:**
DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
 - THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
 - THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
 - THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.
- LG. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR FWD AVIONICS	DOOR	- Open C/B 46WV. - Wait for 5 seconds. - Close C/B 46WV.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
121VU	EIS/SDAC1 AND 2/DOOR/DET /AVNCS	46WV	P02

SUBTASK 24-00-00-868-23O-A

- CAUTION:**
DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
 - THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
 - THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
 - THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.
- LH. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR FWD CARGO	DOOR	Not permitted.

SUBTASK 24-00-00-868-23P-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LJ. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR L AFT CABIN	DOOR	Not permitted.

**** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 751-876, 878-878, 880-880, 882-900**

SUBTASK 24-00-00-868-24F-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LK. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

--	--	--	--

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR L AFT EMER EXIT	DOOR	Not permitted.

**** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900**

SUBTASK 24-00-00-868-24G-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LL. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR L AFT OVERWNG EXIT	DOOR	Not permitted.

SUBTASK 24-00-00-868-23W-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LM. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52		DOOR	Not permitted.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

DOOR L AFT OVERWNG FAULT // FLIGHT LOCK CTL FAULT		
--	--	--

SUBTASK 24-00-00-868-23X-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LN. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR L AFT OVERWNG FAULT // FLIGHT LOCK ENGAGED	DOOR	Not permitted.

SUBTASK 24-00-00-868-23Y-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LP. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR L AFT OVERWNG FAULT // FLIGHT LOCK NOT AVAIL	DOOR	Not permitted.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-23R-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LQ. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR L AVIONICS	DOOR	- Open C/B 46WV. - Wait for 5 seconds. - Close C/B 46WV.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
121VU	EIS/SDAC1 AND 2/DOOR/DET /AVNCS	46WV	P02

**** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-400, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-709, 712-712, 717-718, 725-725, 729-750, 901-908, 911-951, 953-965, 967-999**

SUBTASK 24-00-00-868-24Q-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LR. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:

- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
- If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR L EMER EXIT	DOOR	Not permitted.

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-23S-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LS. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR L FWD CABIN	DOOR	Not permitted.

**** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 751-876, 878-878, 880-880, 882-900**

SUBTASK 24-00-00-868-24H-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LT. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
- If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR L FWD EMER EXIT	DOOR	Not permitted.

**** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900**

SUBTASK 24-00-00-868-24I-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LU. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR L FWD OVERWING EXIT	DOOR	Not permitted.

SUBTASK 24-00-00-868-23Z-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LV. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR L FWD OVERWING FAULT // FLIGHT LOCK CTL FAULT	DOOR	Not permitted.

SUBTASK 24-00-00-868-240-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LW. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR L FWD OVERWING FAULT // FLIGHT LOCK ENGAGED	DOOR	Not permitted.

SUBTASK 24-00-00-868-241-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LX. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

52	DOOR L FWD OVERWNG FAULT // FLIGHT LOCK NOT AVAIL	DOOR	Not permitted.
----	--	------	----------------

SUBTASK 24-00-00-868-24J-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- LY. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR L OVERWNG EXIT	DOOR	Not permitted.

SUBTASK 24-00-00-868-242-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- MA. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR L OVERWNG FAULT // FLIGHT LOCK CTL FAULT	DOOR	Not permitted.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

SUBTASK 24-00-00-868-243-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- MB. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR L OVERWNG FAULT // FLIGHT LOCK ENGAGED	DOOR	Not permitted.

SUBTASK 24-00-00-868-245-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- MC. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR L OVERWNG FAULT // FLIGHT LOCK NOT AVAIL	DOOR	Not permitted.

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-23T-A

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- MD. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR R AFT CABIN	DOOR	Not permitted.

**** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 751-876, 878-878, 880-880, 882-900**

SUBTASK 24-00-00-868-24K-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- ME. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR R AFT EMER EXIT	DOOR	Not permitted.

**** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900**

SUBTASK 24-00-00-868-24L-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- MF. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR R AFT OVERWNG EXIT	DOOR	Not permitted.

SUBTASK 24-00-00-868-246-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- MG. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR R AFT OVERWNG FAULT // FLIGHT LOCK CTL FAULT	DOOR	Not permitted.

SUBTASK 24-00-00-868-247-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- MH. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR R AFT OVERWNG FAULT // FLIGHT LOCK ENGAGED	DOOR	Not permitted.

SUBTASK 24-00-00-868-248-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- MJ. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR R AFT OVERWNG FAULT // FLIGHT LOCK NOT AVAIL	DOOR	Not permitted.

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-23U-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- MK. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR R AVIONICS	DOOR	- Open C/B 46WV. - Wait for 5 seconds. - Close C/B 46WV.

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
121VU	EIS/SDAC1 AND 2/DOOR/DET /AVNCS	46WV	P02

**** ON A/C FSN 001-009, 011-050, 101-150, 154-200, 246-300, 351-352, 356-356, 358-372, 378-379, 381-400, 501-501, 503-504, 506-506, 508-508, 510-512, 517-525, 527-527, 529-529, 531-536, 540-550, 561-567, 571-571, 583-600, 605-608, 610-611, 615-709, 712-712, 717-718, 725-725, 729-750, 901-908, 911-951, 953-965, 967-999**

SUBTASK 24-00-00-868-24R-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- ML. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR R EMER EXIT	DOOR	Not permitted.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

**** ON A/C FSN ALL**

SUBTASK 24-00-00-868-23V-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- MM. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR R FWD CABIN	DOOR	Not permitted.

**** ON A/C FSN 401-425, 427-428, 430-433, 435-450, 751-876, 878-878, 880-880, 882-900**

SUBTASK 24-00-00-868-24M-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- MN. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR R FWD EMER EXIT	DOOR	Not permitted.

**** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900**

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

SUBTASK 24-00-00-868-24N-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- MP. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR R FWD OVERWNG EXIT	DOOR	Not permitted.

SUBTASK 24-00-00-868-249-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- MQ. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR R FWD OVERWNG FAULT // FLIGHT LOCK CTL FAULT	DOOR	Not permitted.

SUBTASK 24-00-00-868-24A-A

CAUTION:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- MR. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR R FWD OVERWNG FAULT // FLIGHT LOCK ENGAGED	DOOR	Not permitted.

SUBTASK 24-00-00-868-24B-A

CAUTION: **DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:**

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- MS. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR R FWD OVERWNG FAULT // FLIGHT LOCK NOT AVAIL	DOOR	Not permitted.

SUBTASK 24-00-00-868-24O-A

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- MT. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR R OVERWNG EXIT	DOOR	Not permitted.

SUBTASK 24-00-00-868-24C-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- MU. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR R OVERWNG FAULT // FLIGHT LOCK CTL FAULT	DOOR	Not permitted.

SUBTASK 24-00-00-868-24D-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

**- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A
RESET THAT IS NOT PERMITTED.**

- MV. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR R OVERWNG FAULT // FLIGHT LOCK ENGAGED	DOOR	Not permitted.

SUBTASK 24-00-00-868-24E-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

**IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A
RESET THAT IS NOT PERMITTED.**

- MW. If there is a "System malfunction or ECAM Alert" because of a change in the electrical power, do the reset of the system.
If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, do a check of the fault history and:
- If the ECAM alert was triggered in the previous flights, do the applicable troubleshooting procedure.
 - If the ECAM alert was not triggered in the previous flights, do the reset of the system.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
52	DOOR R OVERWNG FAULT // FLIGHT LOCK NOT AVAIL	DOOR	Not permitted.

**** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999**

SUBTASK 24-00-00-868-107-A

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

MX. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
77	ENG 1 EIU FAULT ENG 2 EIU FAULT	EIU	This reset procedure is only permitted if the ECAM alert is triggered only on one side (ENG 1 EIU FAULT or ENG 2 EIU FAULT). If this ECAM alert is triggered after engine start, during the selection of the ENG MODE selector from IGN to NORM, do the reset procedure of the ENG MODE selector as follows: - Set the ENG MODE selector from NORM to IGN. - Wait for 1 second. - Set the ENG MODE selector back from IGN to NORM. If the ECAM alert goes out of view after the reset, start the normal operation again.

**** ON A/C FSN 751-800, 851-876, 878-878, 882-900, 908-908, 916-950, 958-959**

POST SB 73-1148 for A/C 880-880, 901-907, 911-915, 951-951, 953-957, 960-965, 967-967

EMB SB 73-1148 for A/C 878-878, 908-908, 958-959

SUBTASK 24-00-00-868-113-D

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

MY. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

JCP Title: Resets	© AIRBUS S.A.S. ALL RIGHTS RESERVED. CONFIDENTIAL AND PROPRIETARY DOCUMENT.	Page 197 of 206 PRINT DATE: Aug 16/2026
-------------------	--	--

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
77	ENG 2 EIU	EIU 2	<u>WARNING:</u> DO NOT TOUCH THE PROBES DURING OR IMMEDIATELY AFTER THIS PROCEDURE. THE PROBES WILL BE HOT AND CAN BURN YOU. <u>CAUTION:</u> REMOVE THE PROTECTIVE COVERS FROM THE PROBES BEFORE YOU DO THIS PROCEDURE. IF YOU DO NOT REMOVE THEM, THE PROBES AND PROTECTIVE COVERS CAN BECOME DAMAGED OR BURNED. This reset procedure is only permitted before pushback and with both engines shutdown. Do not try more than one reset. Spurious MAINTENANCE ENG 2 EIU message can be triggered on STATUS SD page during aircraft power-up. Before pushback and with both engines shutdown, do the reset procedure of the EIU 2 that follows: - Make sure that the protective covers on the probes are removed Ref. AMM 10-11-00-555-014.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			- Set the ENG MODE selector to NORM. - Open the C/B 2KS2. - Open the C/B 4KS2. - Wait for 10 seconds. - Close the C/B 2KS2. - Push the C/B 4KS2. If the MAINTENANCE ENG 2 EIU message goes out of view from the STATUS SD page after the reset, start the normal operation again. If the MAINTENANCE ENG 2 EIU message is triggered again on STATUS SD page, do not try another reset.
--	--	--	---

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999			
49VU	ENGINE/2/FADEC A/AND EIU 2	2KS2	A05
** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900			
121VU	ENGINE/ENG2/FADEC B/AND EIU2	4KS2	R41
** ON A/C FSN 901-908, 911-951, 953-965, 967-999			
121VU	ENGINE/ENG2/FADEC B/AND EIU2	4KS2	Q40

**** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900, 903-908, 911-951, 953-957, 959-959**
POST SB 31-1609 for A/C 902-902, 958-958, 960-965
POST SB 72-1039 for A/C 901-902, 967-967

EMB SB 31-1609 for A/C 878-878, 880-880, 901-901, 903-908, 951-951, 953-957, 959-959, 967-967

SUBTASK 24-00-00-868-109-F

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

NA. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
77	ENG DUAL COOLING // NOT AVAIL	N/A	Several resets may be necessary to start again the engine dual cooling function but do not try to do more than 6 resets. Spurious ENG DUAL COOLING - NOT AVAIL alert can be triggered during automatic engine start, when the flight crew pushes the ENG DUAL COOLING pushbutton-switch to ON. In this case, do the following reset procedure to start again the engine dual cooling function: - If ENG 1+2 MASTER levers are OFF: * Release the ENG DUAL COOLING pushbutton switch. * Wait for 3 seconds. * Push the ENG DUAL COOLING pushbutton switch. * Check dual cooling memo on E/WD: ** If DUAL COOLING memo comes into view on the E/WD: for normal operation, automatic engine start is to be performed with dual cooling function. ** If DUAL COOLING memo and ENG DUAL COOLING – NOT AVAIL alert stay displayed on ECAM after you try to reset, the dual cooling function is inoperative. For normal operation, automatic engine start is to be performed with single cooling on each engine. - If ENG 1(2) MASTER lever is ON: * Reset is not permitted. The dual cooling function is inoperative. For normal operation, automatic engine start is to be performed with single cooling on each engine.

■

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

**** ON A/C FSN 751-800, 851-876, 878-878, 882-908, 911-951, 953-957, 959-962, 964-964, 967-999**

EMB SB 73-1150 for A/C 878-878, 901-908, 911-914, 951-951, 953-957, 959-962, 964-964, 967-967

SUBTASK 24-00-00-868-108-B

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:
- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.
IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

NB. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
 If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
78	ENG 1 FADEC IDENT FAULT ENG 2 FADEC IDENT FAULT	FADEC / EEC	<u>WARNING:</u> DO NOT TOUCH THE PROBES DURING OR IMMEDIATELY AFTER THIS PROCEDURE. THE PROBES WILL BE HOT AND CAN BURN YOU. <u>CAUTION:</u> REMOVE THE PROTECTIVE COVERS FROM THE PROBES BEFORE YOU DO THIS PROCEDURE. IF YOU DO NOT REMOVE THEM, THE PROBES AND PROTECTIVE COVERS CAN BECOME DAMAGED OR BURNED.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

		FADEC/EEC reset is only permitted when the engine is shut down. Spurious ENG 1(2) FADEC IDENT FAULT alert can be triggered during FADEC power-up. If this alert is triggered during FADEC power-up, do the reset procedure of the FADEC that follows: - Make sure that the protective covers on the probes are removed Ref. AMM 10-11-00-555-014. - Open C/B 4KS1 or 4KS2 for ENG 1(2) FADEC channel B. - Wait for 5 seconds. - Close C/B 4KS1 or 4KS2 for ENG 1(2) FADEC channel B. - Wait for 10 seconds. - Open C/B 2KS1 or 2KS2 for ENG 1(2) FADEC channel A. - Wait for 5 seconds. - Close C/B 2KS1 or 2KS2 for ENG 1(2) FADEC channel A. If the ECAM alert goes out of view after the reset, start the normal operation again. If the alert is triggered again, a maintenance action is necessary. Do not try to do another reset. NOTE: After application of this reset procedure, a COOLING indication with a displayed cooling time can comes into view on the E /WD, even if engine cooling is not necessary. Normal operation can be resumed when the displayed cooling time is over.
--	--	--

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
** ON A/C FSN 751-800, 851-876, 878-878, 882-908, 911-951, 953-957, 959-962, 964-964, 967-999			
49VU	ENGINE/2/FADEC A/AND EIU 2	2KS2	A05
49VU	ENGINE/1/FADEC A/AND EIU 1	2KS1	A04

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

**** ON A/C FSN 751-800, 851-876, 878-878, 882-900**

121VU	ENGINE/ENG2/FADEC B/AND EIU2	4KS2	R41
121VU	ENGINE/ENG1/FADEC B/AND EIU 1	4KS1	R40

**** ON A/C FSN 901-908, 911-951, 953-957, 959-962, 964-964, 967-999**

121VU	ENGINE/ENG2/FADEC B/AND EIU2	4KS2	Q40
121VU	ENGINE/ENG1/FADEC B/AND EIU 1	4KS1	R41

**** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999**

EMB SB 73-1144 for A/C 878-878, 880-880, 901-908, 951-951, 953-965, 967-967

SUBTASK 24-00-00-868-110-C

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

NC. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.

If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:

- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
- If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
78	ENG 1 FADEC SYS FAULT ENG 2 FADEC SYS FAULT	FADEC / EEC	<u>WARNING:</u> DO NOT TOUCH THE PROBES DURING OR IMMEDIATELY AFTER THIS PROCEDURE. THE PROBES WILL BE HOT AND CAN BURN YOU. <u>CAUTION:</u> REMOVE THE PROTECTIVE COVERS FROM THE PROBES BEFORE

	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			YOU DO THIS PROCEDURE. IF YOU DO NOT REMOVE THEM, THE PROBES AND PROTECTIVE COVERS CAN BECOME DAMAGED OR BURNED. Do the reset procedure of the EEC only when engine is shut down. - If this alert is triggered after the associated ENG MASTER lever is set to ON, the ENG 1 (2) FADEC SYS FAULT alert is latched. As a result, a maintenance action is necessary. - If this alert is triggered during the FADEC power-up and when the associated ENG MASTER lever is still set to OFF, the alert can be spurious. Then do the following procedure: * Make sure that the protective covers on the probes are removed Ref. AMM 10-11-00-555-014. * Set the ENG MODE selector to NORM. * Make sure that the associated ENG FADEC GND PWR pushbutton-switch is set to OFF. ** For ENG 1(2) FADEC channel A, open the C/B 2KS1 or 2KS2. **For ENG 1(2) FADEC channel B, open the C/B 4KS1 or 4KS2. * Wait for 5 seconds. ** For ENG 1(2) FADEC channel A, close the C/B 2KS1 or 2KS2. - For ENG 1(2) FADEC channel B, close the C/B 4KS1 or 4KS2. * At the next FADEC power-up, make sure that the alert is not triggered. If the alert is triggered again, do not try to do another reset, a maintenance action is necessary.
--	--	--	---

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-908, 911-951, 953-965, 967-999			
49VU	ENGINE/2/FADEC A/AND EIU 2	2KS2	A05
49VU	ENGINE/1/FADEC A/AND EIU 1	2KS1	A04
** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900			
121VU	ENGINE/ENG2/FADEC B/AND EIU2	4KS2	R41
121VU	ENGINE/ENG1/FADEC B/AND EIU 1	4KS1	R40
** ON A/C FSN 901-908, 911-951, 953-965, 967-999			
121VU	ENGINE/ENG2/FADEC B/AND EIU2	4KS2	Q40
121VU	ENGINE/ENG1/FADEC B/AND EIU 1	4KS1	R41
** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900, 908-908, 911-950			

SUBTASK 24-00-00-868-140-B

CAUTION: DO NOT DO THE RESET OF AN EFFECT (ECAM ALERT, LOCAL EFFECT OR CREW /MAINT OBS) IF:

- THERE IS MORE THAN ONE EFFECT FOR THE SAME SYSTEM, AND
- THE RESET IS NOT PERMITTED FOR ONE OR MORE OF THESE EFFECTS, OR
- THE EFFECT IS NOT GIVEN IN THE SYSTEM RESET TABLE.

IF YOU DO NOT OBEY THIS INSTRUCTION, THERE IS A RISK THAT YOU WILL DO A RESET THAT IS NOT PERMITTED.

- ND. If it is obvious that this "System malfunction or ECAM Alert" is consecutive to an electrical power up or transient, then the reset may be performed.
- If this "System malfunction or ECAM Alert" is not consecutive to an electrical power up or transient, then the maintenance operators shall do a check of the fault history and:
- If an ECAM Alert linked with this computer has been triggered on the previous flights then the TSM procedure shall be performed,
 - If no ECAM Alert linked with this computer has been triggered on the previous flights then the reset may be performed.

ATA	ECAM-ALERT OR SYSTEM MALFUNCTION	AFFECTED COMPUTER	RESET PROCEDURE
23	COM-CIDS-Incorrect number of emergency exits on FAP (CIDS)	CIDS	- Open C/Bs in the following order: - 150RH on panel 49VU - 147RH (if installed) on panel 49VU - 151RH on panel 121VU - 157RH on panel 49VU - 146RH (if installed) on panel 49VU - 156RH on panel 121VU.

AIRBUS	TSM - LTM - A318/A319/A320/A321	REV DATE: Aug 01/2026
	Tail Number - MSN - FSN: ALL	
	24-00-00-810-818-A - System Reset Guidelines	

			- Wait for 10 seconds. - Close C/Bs in the following order: - 151RH, 156RH, 147RH (if installed), 146RH (if installed) in order to re-engage the NORM power. - Close C/Bs in the following order: - 150RH and 157RH. - After CIDS reset, wait approximately 4 minutes before recovering normal operation.
--	--	--	--

Table of the Circuit Breakers Used in This Procedure

PANEL	DESIGNATION	FIN	LOCATION
** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900			
49VU	COM NAV/CIDS/DIR2 ESS	157RH	G02
49VU	COM NAV/CIDS/DIR1 ESS	150RH	G01
** ON A/C FSN 908-908, 911-950			
49VU	COM/CIDS/DIR ESS/2	157RH	G02
49VU	COM/CIDS/DIR ESS/1	150RH	G01
** ON A/C FSN 751-800, 851-876, 878-878, 880-880, 882-900			
121VU	COM NAV/CIDS/DIR2 NORM	156RH	M06
121VU	COM NAV/CIDS/DIR1 NORM	151RH	M05
** ON A/C FSN 908-908, 911-950			
121VU	COM NAV/CIDS/DIR NORM/2	156RH	M06
121VU	COM NAV/CIDS/DIR NORM/1	151RH	M05