

ST

3	2	1	SNO.
ST	ST	ST	ABN.TYPE
SIGNAL NO PLATE	SIGNAL ASPECT	SIGNAL ASPECT	SUBHEAD
KUR	KGP	KGP	REPORTSTTN
KGP	KGP	KGP	REPORTDIV
KUR	ULB	ROP	FROM
KGP	ULB	BTS	TO
KUR1729	KGP0025	KGP1388	CREW/CLIID
V SRINIVASA RAO I D	EL H. MURMU	EL KAMAL KANTI NATH	CREW/CLINAME
LPP	Chief Loco Inspector	LPM	DESIG
04-06-2026	01-06-2026	01-06-2026	ABNDATE
09:11	20:28	14:19	ABN.TIME
455		207/14	FROMKM
116		207/12	TO KM
YS	YS	YS	STATUS
APPUSER	APPUSER	CREW	FILLEDBY
39594	30743	37263	LOCO
SGUD	SRCE	TATE	LOCO SHED
15607	22841	22852	TRAIN
06-06-26 21:20	04-06-26 14:10	02-06-26 21:54	SMSTO LP
KGP	KGP	KGP	Div
Y	Y	Y	RemStts
DETAIL:There is no IB Marker plate provided on IB signal at km.no.260/8-10 between SFO and BNBR.A White Circular Board With Black Letters IB to be provided on the iIBH Sigal post.	DETAIL:ULB UP MAIN STARTER SIGNAL GREEN TO DANGER FOR FEW SECONDS THAN GREEN	DETAIL:ROP IB SIGNAL ON APPROACH GREEN TO RED.TRAIN STOPPED IN REAR OF IB SIGNAL BY APPLYING EMERGENCY	
CLOSE_REM:AS PER S&T DEPT As per JE/SIG/SFO- IB Marker provided on 6/6/26 at 10:15 hrs. At km 260/8--10.	CLOSE_REM:as per S&T dept As per through monitoring of data logger report observed that when signal aspect change from double yellow to green of signal no S-1 at BSBP this failure was happened. Resistance and capacitor replaced of both aspect (yellow and double yellow) replaced of signal no S-1 at BSBP and rectified.	CLOSE_REM:AS PER S&T DEPPT As per DL report it has been noticed that DD ACPR drop 14:17 to14:23. For that reason DN IB signal go back to danger and relowered at 14:23hrs when DDACPR clear. Circuit kept under observation. Suspected reason for Dropping of DD ACPR is the working of CNST staff for commissioning of New SSDAC installation.	Closing Remarks
APP_REM:@CNLTRKGP/06-06-2026 14:51-As per JE/SIG/SFO- IB Marker provided on 6/6/26 at 10:15 hrs. At km 260/8--10.	APP_REM:@CNLTRKGP/04-06-2026 12:38-As per through monitoring of data logger report observed that when signal aspect change from double yellow to green of signal no S-1 at BSBP this failure was happened. Resistance and capacitor replaced of both aspect (yellow and double yellow) replaced of signal no S-1 at BSBP and rectified.	APP_REM:@CNLTRKGP/02-06-2026 16:46-As per DL report it has been noticed that DD ACPR drop 14:17 to14:23. For that reason DN IB signal go back to danger and relowered at 14:23hrs when DDACPR clear. Circuit kept under observation. Suspected reason for Dropping of DD ACPR is the working of CNST staff for commissioning of New SSDAC installation.	App Remarks
06-06-2026 14:51	04-06-2026 12:38	02-06-2026 16:46	App Remarks Date
04-06-2026 20:22	01-06-2026 20:31	01-06-2026 16:43	Reporting Date

6	5	4	SNO.
ST	ST	ST	ABN.TYPE
SIGNAL ASPECT	SIGNAL ASPECT	SIGNAL BULB	SUBHEAD
KGP	KGP	KUR	REPORTSTTN
KGP	KGP	KGP	REPORTDIV
ROP	ROP	KGP	FROM
BTS	BTS	KUR	TO
KGP1075	KGP3358	KGP1075	CREW/CLIID
DL SURESH PRASAD PANDEY	EL SUVENDU SUR	DL SURESH PRASAD PANDEY	CREW/CLINAME
LPP	LPP	LPP	DESIG
06-06-2026	06-06-2026	05-06-2026	ABNDATE
10:52	07:06	02:47	ABN.TIME
209/10	209/16		FROMKM
209/08	209/14		TO KM
YS	YS	YS	STATUS
CREW	CREW	SUPConsole	FILLEDBY
	25031	22815	LOCO
	SRCE	SPJD	LOCO SHED
22832	18044	18047	TRAIN
08-06-26 18:52	08-06-26 18:52	05-06-26 22:49	SMSTO LP
KGP	KGP	KGP	Div
Y	Y	Y	RemStts
DETAIL:ROP IB DISTANT SIGNAL SHOWING ONE YELLOW	DETAIL:ROP IB DISTANT FOUND ONE YELLOW	DETAIL:BLS G/S FOUND NO LIGHT IN BLS/STN.	Detail
CLOSE_REM:as per S&T dept Occurred during ROP NI block work. Now the concerned signal is obsolete.	CLOSE_REM:as per S&T dept Occurred during ROP NI block work. Now the concerned signal is obsolete.	CLOSE_REM:as per S&T dept 630mA fuse for S-1 HG blown off. Same replaced, again blown off. Later S-1 HG Cable tested from Relay Room to Gate Home Location via L-5 and found Cable from L-5 to UP Gate Home Location, i.e 4 Core Cable carrying S-1 HG Suspect low insulation. Same Shifted to Spare Core and failure rectified.	Closing Remarks
APP_REM:@CNLTRKGP/08-06- 2026 18:45-Occurred during ROP NI block work. Now the concerned signal is obsolete.	APP_REM:@CNLTRKGP/08-06- 2026 18:44-Occurred during ROP NI block work. Now the concerned signal is obsolete.	APP_REM:@fault/05-06-2026 12:28- Not pertain to KUR Divn.Please forward to KGP Divn.@CNLTRKGP/05-06-2026 18:55-630mA fuse for S-1 HG blown off. Same replaced, again blown off. Later S-1 HG Cable tested from Relay Room to Gate Home Location via L-5 and found Cable from L-5 to UP Gate Home Location, i.e 4 Core Cable carrying S-1 HG Suspect low insulation. Same Shifted to Spare Core and failure rectified	App Remarks
08-06-2026 18:45	08-06-2026 18:44	05-06-2026 18:55	App Remarks Date
06-06-2026 13:06	06-06-2026 11:40	05-06-2026 09:42	Reporting Date

9	8	7	SNO.
ST	ST	ST	ABN.TYPE
SIGNAL ASPECT	SIGNAL ASPECT	SIGNAL ASPECT	SUBHEAD
HWHS	KGP	ADL	REPORTSTTN
KGP	KGP	KGP	REPORTDIV
DSNR	ROP	RGA	FROM
TPKR	BTS	TMZ	TO
TPKR1417	BLS1086	KGP0066	CREW/CLIID
EL RATHINDRANATH BISWAS	EL NITESH KHAITAN	SAMBHUNATH MAITY	CREW/CLNAME
LPG	LPG	Chief Loco Inspector	DESIG
08-06-2026	07-06-2026	06-06-2026	ABNDATE
10:12	05:55	12:10	ABN.TIME
3/28X	209/16		FROMKM
3/26	209/14		TO KM
YS	YS	YS	STATUS
CREW	CREW	APPUSER	FILLED BY
108675	38274	238789	LOCO
	RPDX		LOCO SHED
38103	E/N/B/E	38053	TRAIN
11-06-26 08:36	08-06-26 18:52	07-06-26 21:16	SMSTO LP
KGP	KGP	KGP	Div
Y	Y	Y	RemStts
DETAIL:DN MAIN TPKR HOME SIGNAL SHOW RED AND ONE YELLOW AT A TIME FOR FEW TIME, THEN SHOW ONE YELLOW ONLY	DETAIL:DOUBLE DISTANT SECTION WITH ROP IB DIS ASPECT ONE YELLOW MESSAGE CONVEYED TO ROP BUT NO RESPONSE	DETAIL:GS-1 SUDDEN SUDDEN PUT BACK TO RED FROM YELLOW AND STEADY. RAISED TO YELLOW AGAIN.THEN PUT BACK TO RED AND STEADY	Detail
CLOSE_REM:as per S&T dept As per the Datalogger report, relay 2HR picked up at 10:11:54.921 hrs, followed by the pick-up of relay 2HECR at 10:11:55.546 hrs. Subsequently, relay 2RECR dropped at 10:12:13.031 hrs. Thus, relays 2HECR and 2RECR remained in the picked-up condition simultaneously for approximately 18 seconds. Latter, circuit and operation of signal S2 checked several times but the above situation was not reoccurred. As a precautionary measure, both the Red and Bottom Yellow LED units	CLOSE_REM:as per S&T dept Occurred during ROP NI block work. Now the concerned signal is obsolete.	CLOSE_REM:AS PER S&T DEPT AS PER SSE/TMZ/INCH , UP LINE T/C 108BT FAILED FROM 12:11 TO 12:12HRS. LATER CHECKED THOROUGHLY FOUND NO FAULT. CCT KEPT UNDER OBSERVATION. AS PER D/L- 108BTTPR FAILED FROM 12:10:08:812 TO 12:12:20:109HRS.	Closing Remarks
APP_REM:@CNLTRKGP/11-06-2026 00:23-As per the Datalogger report, relay 2HR picked up at 10:11:54.921 hrs, followed by the pick-up of relay 2HECR at 10:11:55.546 hrs. Subsequently, relay 2RECR dropped at 10:12:13.031 hrs. Thus, relays 2HECR and 2RECR remained in the picked-up condition simultaneously for approximately 18 seconds. Latter, circuit and operation of signal S2 checked several times but the above situation was not reoccurred. As a precautionary measure, both the Red and Bottom Yellow LED units	APP_REM:@CNLTRKGP/08-06-2026 18:45-Occurred during ROP NI block work. Now the concerned signal is obsolete.	APP_REM:@CNLTRKGP/06-06-2026 18:42-Due to T/C-108 failure, rectified at 12:12hrs@kgpuor/06-06-2026 21:21/PLEASE PROVIDE DATA LOGGER REPORTS TIME SLOT.@CNLTRKGP/07-06-2026 15:08-AS PER SSE/TMZ/INCH , UP LINE T/C 108BT FAILED FROM 12:11 TO 12:12HRS. LATER CHECKED THOROUGHLY FOUND NO FAULT. CCT KEPT UNDER OBSERVATION. AS PER D/L- 108BTTPR FAILED FROM 12:10:08:812 TO 12:12:20:109HRS.	App Remarks
11-06-2026 00:23	08-06-2026 18:45	07-06-2026 15:08	App Remarks Date
08-06-2026 11:27	07-06-2026 11:47	06-06-2026 13:36	Reporting Date

13	12	11	10	SNO.
ST	ST	ST	ST	ABN.TYPE
SIGNAL VISIBILITY	SIGNAL ASPECT	SIGNAL ASPECT	SIGNAL NO PLATE	SUBHEAD
KGP	BHC	BHC	NMP	REPORTSTTN
KGP	KGP	KGP	KGP	REPORTDIV
SDAH	BLS	BTS	RNTL	FROM
KGP	NGRD	ROP	BHC	TO
KGP0082	NMP2433	NMP2387	NMP1456	CREW/CLIID
BRIHASPATI DAS	EL INDRAJEET KR VERMA G12	EL K SRINIVAS RAO G12	EL PURNENDU PAL G12	CREW/CLINAME
Chief Loco Inspector	SALP	LPG	LPG	DESIG
08-06-2026	08-06-2026	08-06-2026	08-06-2026	ABNDATE
20:50	17:41	16:27	15:25	ABN.TIME
	238/21	210/29	287/7A	FROMKM
	238/23	210/31	287/9A	TO KM
YS	YS	YS	YS	STATUS
APPUSER	CREW	CREW	APPUSER	FILLED BY
30529	33189	331891	31378	LOCO
SDAD	BIAE		PTRX	LOCO SHED
22201	ME//N/CBSP	ME//N/CBSP	BRN E JSPK	TRAIN
10-06-26 22:30	11-06-26 15:53	11-06-26 11:35	09-06-26 23:45	SMSTO LP
KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	RemStts
DETAIL:Visibility of MRGM starter signal is obstructed by tree branches	DETAIL:TRAIN STOP DUE TO LC84 GATE SIGNAL DANGER.PASS AT ON AS PER RULE.	DETAIL:TRAIN STOP DUE LC 66 GATE SIGNAL DANGER.PASS AT ON AS PER RULE.	DETAIL:Ranital Gate Signal 3rd Line Up Km287/7A G Marker Not Found	Detail
CLOSE_REM:AS PER S&T DEPT AS WELL AS eNGG DEPT SSE/PWAY/SRC/CENTRAL STAFF TRIMMING WORK STARTED , COMPLETED WILL 11/06/26.	CLOSE_REM:AS PER S&T DEPT This is not Signal abnormality. There was no complaint given from BLS or NGRD Station. Also no TRAIN passed LC-84 at given time (at 17:41 HRS) . As per Datalogger report it was revealed that LC-84 closed (84KNLR UP at 17:48:45:750 HRS) , later than Train hit Signal replacement MSDAC TRACK SECTION dropped (GS-5XTPR dropped at 17:48:39:937 HRS).	CLOSE_REM:AS PER S&T DEPT No any signal failure on that day for LC gate no 66.. On duty SM didnt gave any signal for that train as it may block traffic on gate no 66 but LP considered it as signal failure and he moved forward till UP home signal.	CLOSE_REM:AS PER S&T DEPT As per JE SIG SFO G marker provided at 16:00 hrs on 9.6.26	Closing Remarks
APP_REM:@CNLTRKGP/10-06-2026 17:42- SSE/PWAY/SRC/CENTRAL STAFF TRIMMING WORK STARTED , COMPLETED WILL 11/06/26.	APP_REM:@CNLTRKGP/11-06-2026 12:13-This is not Signal abnormality. There was no complaint given from BLS or NGRD Station. Also no TRAIN passed LC-84 at given time (at 17:41 HRS) . As per Datalogger report it was revealed that LC-84 closed (84KNLR UP at 17:48:45:750 HRS) , later than Train hit Signal replacement MSDAC TRACK SECTION dropped (GS-5XTPR dropped at 17:48:39:937 HRS).	APP_REM:@CNLTRKGP/11-06-2026 00:26-No any signal failure on that day for LC gate no 66.. On duty SM didn't gave any signal for that train as it may block traffic on gate no 66 but LP considered it as signal failure and he moved forward till UP home signal...	APP_REM:@fault/08-06-2026 16:56- Not pertains to KUR-division please forwarded to KGP-div.@fault/08-06-2026 16:56-Not pertains to KUR-division please forwarded to KGP-div.@CNLTRKGP/09-06-2026 22:43- As per JE SIG SFO 'G' marker provided at 16:00 hrs on 9.6.26	App Remarks
10-06-2026 17:42	11-06-2026 12:13	11-06-2026 00:26	09-06-2026 22:43	App Remarks Date
09-06-2026 00:09	08-06-2026 22:07	08-06-2026 22:01	08-06-2026 15:59	Reporting Date

18	ST	17	16	15	14	SNO.
SIGNAL ASPECT	ST	SIGNAL ASPECT	SIGNAL VISIBILITY	SIGNAL ASPECT	ST	ABN.TYPE
KGP	KGP	KGP	KGP	KGP	OTHER	SUBHEAD
KGP	KGP	KGP	KGP	KGP	SRC	REPORTSTTN
ULB	BCK	DTE	BZN	BHC	BZN	REPORTDIV
ULB	SMCK	BZN	BZN	KGP	BSBP	FROM
KGP1388	KGP1388	KGP2086	NMP1587	SRC1760		TO
EL KAMAL KANTI NATH	EL KAMAL KANTI NATH	EL SADHAN DAS	EL SHIV SHANKAR KUMAR	EL CROMTON GHOSH C		CREW/CLIID
LPM	LPM	LPG	LPG	LPP		CREW/CLNAME
16-06-2026	15-06-2026	12-06-2026	11-06-2026	09-06-2026		DESIG
01:37	02:12	10:55	06:07	15:26		ABNDATE
32/13X	94/6	46/10	215/10	41/22		ABN.TIME
32/15X	94/8	46/08	215/8	41/20		FROMKM
YS	YS	YS	YS	YS		TO KM
CREW	CREW	APPUSER	CREW	CREW		STATUS
22743	22865	39556	33561	39481		FILLED BY
SRCE	SRCE	NGCD	TKDE	HWHE		LOCO
12278	12278	22808	DNE	18010		LOCO SHED
18-06-26 21:08	15-06-26 15:31	13-06-26 21:03	12-06-26 23:31	09-06-26 23:46		TRAIN
KGP	KGP	KGP	KGP	KGP		SMSTO LP
Y	Y	Y	Y	Y		Div
						RemStts
DETAIL:ULB UP MAIN STARTER SIGNAL ON APPROACH TURNS GREEN TO RED.	DETAIL:AS143 PASSED AT ON AS PER RULE	DETAIL:DN. BZN H/Sig. Not View Properly from LP side due to trees branches	DETAIL:ROP GS 69 NO LIGHT	DETAIL:AS 46 PASS AT ON AS PER RULE.INFORM TO SMR / BSBP THROUGH VHF.		
CLOSE_REM:AS PER S&T DEPT ULB track circuit no 29T failed momentarily(1:36:9:328 To 1:36:38:092),as a result UP STR signal S-9 gone back to danger. Later Signal staff attended and thoroughly checked and found 29T staggering Glued joint at km no 32/21X-23X by Iron flake.	CLOSE_REM:AS PER S&T DEPT Due to Train ahead	CLOSE_REM:AS PER S&T DEPT Obstruction cleared, after tree trimming at km 46/8-10 by staff of SSE/TRD/MCA/INC.	CLOSE_REM:AS PER S&T DEPT ACTION TAKEN - @CNLTRKGP/12-06-2026 17:04- FAILED DUE TO 3*12CORE CABLE CUT BY OUTSIDERS BETWEEN KM 215/6-8. RECTIFIED AT 06:30 HRS ON 11.06.26 AFTER CABLE JOINTING WORK.	CLOSE_REM:AS PER S&T DEPT As per JE BZN C3 to C4 contact of 46AT2PR offering high resistance. Same relay was replaced & rectified .		
APP_REM:@CNLTRKGP/18-06-2026 13:32-ULB track circuit no 29T failed momentarily(1:36:9:328 To 1:36:38:092),as a result UP STR signal S-9 gone back to danger. Later Signal staff attended and thoroughly checked and found 29T staggering Glued joint at km no 32/21X-23X by Iron flake.	APP_REM:@CNLTRKGP/15-06-2026 13:29-Due to Train ahead	APP_REM:@CNLTRKGP/13-06-2026 17:40-Obstruction cleared, after tree trimming at km 46/8-10 by staff of SSE/TRD/MCA/INC,	APP_REM:@CNLTRKGP/12-06-2026 17:04-FAILED DUE TO 3*12CORE CABLE CUT BY OUTSIDERS BETWEEN KM 215/6-8. RECTIFIED AT 06:30 HRS ON 11.06.26 AFTER CABLE JOINTING WORK.	APP_REM:@CNLTRKGP/09-06-2026 22:47-As per JE BZN C3 to C4 contact of 46AT2PR offering high resistance. Same relay was replaced & rectified		
18-06-2026 13:32	15-06-2026 13:29	13-06-2026 17:40	12-06-2026 17:04	09-06-2026 22:47		App Remarks Date
16-06-2026 03:30	15-06-2026 03:04	12-06-2026 20:13	11-06-2026 09:37	09-06-2026 17:26		Reporting Date

22	21	20	19	SNO.
ST	ST	ST	ST	ABN.TYPE
SIGNAL BULB	SIGNAL BULB	SIGNAL ASPECT	SIGNAL ASPECT	SUBHEAD
SRC	NMP	SRC	KGP	REPORTSTTN
KGP	KGP	KGP	KGP	REPORTDIV
KGP	KKQ	SRC	HWH	FROM
BLS	NMP	PDPK	KGP	TO
KGP0028	TATA3119	SRC1501	KGP3819	CREW/CLIID
EL S.C.SUBUDHI	NISHANT PATEL	EL SWAPAN BANERJEE C	EL SUMIT KUMAR II C	CREW/CLINAME
Chief Loco Inspector	LPG	LPP	SALP	DESIG
19-06-2026	19-06-2026	16-06-2026	16-06-2026	ABNDATE
14:34	09:07	15:41	01:37	ABN.TIME
115/11	122/30	PDPK	32/11X	FROMKM
230/23	122/28	7/11	32/11X	TO KM
YS	YS	YS	YS	STATUS
APPUSER	CREW	CREW	CREW	FILLED BY
28623	32142	30706	22743	LOCO
RTMD	LDHE	WATE	SRCE	LOCO SHED
N-CONT(E)/PCP	N/APIG	18046	12278	TRAIN
20-06-26 19:14	20-06-26 19:14	18-06-26 21:08	18-06-26 21:08	SMSTO LP
KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	RemStts
DETAIL:MIDDLE BULB OF TOP LUNAR FOR UP COMMON LOOP LINE AT JER UP MAIN LINE HOME SIGNAL IS NOT GLOWING	DETAIL:NTY FIRST LONNER ONLY FOUR LED GLOWING.	DETAIL:SRC S/S S-114 PUT BACK WITHOUT ANY INTIMATION,AND NOT RESPOND OVER VHF,SIGNAL OFF-15/38,SIGNAL PUT BACK-15/41	DETAIL:WHILE WORKING TRAIN NO-12277 HWH TO KGP AFTER PASSING ULB UP H/S GREEN WE FOUND ULB UP S/S DANGER ASPECT.	
CLOSE_REM:AS PER S&T DEPT AS PER SSE JER 3RD no. ROUTE LED WAS REPLACED ON 20.6.26 AT 10:30 HRS	CLOSE_REM:AS PER S&T DEPT AS PER SSE NMP LED WAS REPLACED ON 20.6.26 AT 6:00 HRS	CLOSE_REM:AS PER S&T DEPT From the Datalogger report, it is observed that the Joint Line-2 slot (SL4YPR) from PDPK failed at 15:40:40.250 hrs. Consequently, 126HR dropped at 15:40:42.031 hrs and 126HECR dropped at 15:40:42.171 hrs. As a result, 114HR dropped at 15:40:46.171 hrs and Signal S114 gone back to the ON position. The SL4YPR circuit was thoroughly checked; however, no abnormality or definite cause for the dropping of SL4YPR could be detected. The circuit has been kept under observa	CLOSE_REM:AS PER S&T DEPT ULB track circuit no 29T failed momentarily(1:36:9:328 To 1:36:38:092),as a result UP STR signal S-9 gone back to danger. Later Signal staff attended and thoroughly checked and found 29T staggering Glued joint at km no 32/21X-23X by Iron flake.	
APP_REM:@CNLTRKGP/20-06-2026 12:02-AS PER SSE JER 3RD NO ROUTE LED WAS REPLACED ON 20.6.26 AT 10:30 HRS	APP_REM:@CNLTRKGP/20-06-2026 10:16-AS PER SSE NMP LED WAS REPLACED ON 20.6.26 AT 6:00 HRS	APP_REM:@CNLTRKGP/18-06-2026 13:31-From the Datalogger report, it is observed that the Joint Line-2 slot (SL4YPR) from PDPK failed at 15:40:40.250 hrs. Consequently, 126HR dropped at 15:40:42.031 hrs and 126HECR dropped at 15:40:42.171 hrs. As a result, 114HR dropped at 15:40:46.171 hrs and Signal S114 gone back to the 'ON' position. The SL4YPR circuit was thoroughly checked; however, no abnormality or definite cause for the dropping of SL4YPR could be detected. The circuit has been kept under observa	APP_REM:@CNLTRKGP/18-06-2026 13:32-ULB track circuit no 29T failed momentarily(1:36:9:328 To 1:36:38:092),as a result UP STR signal S-9 gone back to danger. Later Signal staff attended and thoroughly checked and found 29T staggering Glued joint at km no 32/21X-23X by Iron flake.	
20-06-2026 12:02	20-06-2026 10:16	18-06-2026 13:31	18-06-2026 13:32	App Remarks Date
19-06-2026 22:28	19-06-2026 09:52	16-06-2026 18:22	16-06-2026 03:31	Reporting Date

26	25	24	23	SNO.
ST	ST	ST	ST	ABN.TYPE
SIGNAL ASPECT	OTHER	SIGNAL VISIBILITY	SIGNAL VISIBILITY	SUBHEAD
SRC	SRC	TATA	KGP	REPORTSTIN
KGP	KGP	KGP	KGP	REPORTDIV
ROP	KGP	TATA	TATA	FROM
BTS	GTS	NMP	KGP	TO
SRC1829	KGP0028	CKP0086	KGP4429	CREW/CLIID
DL PRASENJIT BASAK C	EL S.C.SUBUDHI	SARAT KUMAR SAHOO	EL RAHUL KUMAR SINGH G12	CREW/CLINAME
LPP	Chief Loco Inspector	Chief Loco Inspector	SALP	DESIG
20-06-2026	20-06-2026	20-06-2026	20-06-2026	ABNDATE
13:22	11:53	11:44	08:00	ABN.TIME
207/10	115/13	248		FROMKM
207/08	211/21	122		TO KM
YS	YS	YS	YS	STATUS
CREW	APPUSER	APPUSER	CREW	FILLED BY
37010	60090	60383	60383	LOCO
SRCE	SREE	NGPE	NGPE	LOCO SHED
12246	HL/BCNE	BCN/KKH	BCN/NKKH/NMP	TRAIN
21-06-26 10:47	21-06-26 10:47	20-06-26 19:14	21-06-26 10:47	SMSTO LP
KGP	KGP	KGP	KGP	Div
Y	Y	Y	Y	RemStts
DETAIL:ROP IB SIGNAL PASS AT DANGER AS PER RULE AFTER GETTING PRIVET NO AND ID NO FROM TALK BACK TELEPHONE IN IB SIGNAL POST	DETAIL:SIGNAL HEAD OF SIGNAL NO-GSA KT367 AT KM NO-172/10A-172/12A ON UP JOINT LINE BETWEEN GII-CKU SLIGHTLY TURNED TOWARDS RIGHT HAND SIDE CAUSES LESS INTENSITY & VISIBILITY OF SIGNAL ASPECT (TIME - 11.53 HRS)	DETAIL:Signal Visibility Of Gate Signal No GS-18 between GUD-GTS Jointline is Very Poor	DETAIL:GATE SIGNAL G/S 18 OF GATE NO.122 BETWEEN GUD-GTS JOINT LINE RED ASPECT IS NOT VISIBLE PROPERLY AS IT IS VERY DIM	
CLOSE_REM:AS PER S&T DEPT As per SSE JER INCHARGE,Both SSDAC system failed at a time, after passage of 1 Goods train. Both system hanged at IB(NMBR), then attended at IB and both system power made off and on, reset done and and reset accepted. after passage of 12246 train section cleared 14:20 hrs.	CLOSE_REM:AS PER S&T DEPT AS PER SSE GII, TECH GII ATTENDED ON 20.6.26 AT 16:00 HRS, SIGNAL UNIT ADJUSTED. NOW VISIBILITY IS ABOVE 250 MTR	CLOSE_REM:AS PER S&T DEPT Same adjusted and visibility improved on 20-06-2026.	CLOSE_REM:AS PER S&T DEPT AS PER SSE GTS LINE SIGNAL UNIT ADJUSTED ON 20.6.26 AT 17:00 HRS. NOW VISIBILITY IS 600 MTR	Closing Remarks
APP_REM:@CNLTRKGP/21-06-2026 07:42-As per SSE JER INCHARGE,Both SSDAC system failed at a time, after passage of 1 Goods train. Both system hanged at IB(NMBR), then attended at IB and both system power made off and on, reset done and and reset accepted. after passage of 12246 train section cleared 14:20 hrs.	APP_REM:@CNLTRKGP/21-06-2026 07:16-AS PER SSE GII, TECH GII ATTENDED ON 20.6.26 AT 16:00 HRS, SIGNAL UNIT ADJUSTED. NOW VISIBILITY IS ABOVE 250 MTR	APP_REM:@CNLTRKGP/20-06-2026 17:23-Same adjusted and visibility improved.	APP_REM:@CNLTRKGP/21-06-2026 07:17-AS PER SSE GTS LINE SIGNAL UNIT ADJUSTED ON 20.6.26 AT 17:00 HRS. NOW VISIBILITY IS 600 MTR	App Remarks
21-06-2026 07:42	21-06-2026 07:16	20-06-2026 17:23	21-06-2026 07:17	App Remarks Date
20-06-2026 20:01	20-06-2026 16:13	20-06-2026 11:47	20-06-2026 20:15	Reporting Date