(THIS PROCEDURE IS FOR RASPBERRY Pi1 ONLY)

Step for kernel comp	ollation:

1> enable CONFIG_KALLSYMS and CONFIG_DEBUG_INFO in your .config file.

2> set variable KERNEL=kernel

3> make ARCH=arm CROSS_COMPILE=/home/mehul/rpi/tools/arm-bcm2708/arm-bcm2708-linux-gnueabi/bin/arm-bcm2708-linux-gnueabi- bcmrpi_defconfig

4> make ARCH=arm CROSS_COMPILE=/home/mehul/rpi/tools/arm-bcm2708/arm-bcm2708-linux-gnueabi/bin/arm-bcm2708-linux-gnueabi-zImage modules dtbs

Step for U-boot compilation:

____:

*(These commands only if you want to do some changes in U-boot , otherwise placing kernel related images in SDcard will work ,as raspian has its own bootloader)

1> make ARCH=arm CROSS_COMPILE=/home/mehul/rpi/tools/arm-bcm2708/arm-bcm2708-linux-gnueabi/bin/arm-bcm2708-linux-gnueabi-rpi_defconfig

2> make ARCH=arm CROSS_COMPILE=/home/mehul/rpi/tools/arm-bcm2708/arm-bcm2708-linux-gnueabi/bin/arm-bcm2708-linux-gnueabi-

Putting image into SD card:

- 1> First format the SD card.
- 2> Then execute command sudo dd if=2017-06-21-raspbian-jessie.img of=/dev/sdd bs=4M.
- 3> insert the card in the board and boot it once, so that it will create partition.
- 4> now to get the log on minicom write "enable_uart=1" at the end of /boot/config.txt as mentioned in https://elinux.org/RPi_Serial_Connection.

(in board RPi1-1551 Tx/Rx pin is not working, so please take board RPi1-1550)

go to kernel dirrctory where you compile the code and execute below command(below commands are given in raspberry site also.)

mkdir mnt

mkdir mnt/fat32

mkdir mnt/ext4

sudo mount /dev/sdb1 mnt/fat32

sudo mount /dev/sdb2 mnt/ext4

sudo make ARCH=arm INSTALL_MOD_PATH=mnt/ext4 modules_install

sudo cp mnt/fat32/\$KERNEL.img mnt/fat32/\$KERNEL-backup.img

sudo cp arch/arm/boot/zImage mnt/fat32/\$KERNEL.img

sudo cp arch/arm/boot/dts/*.dtb mnt/fat32/

sudo cp arch/arm/boot/dts/overlays/*.dtb* mnt/fat32/overlays/

sudo cp arch/arm/boot/dts/overlays/README mnt/fat32/overlays/

sudo umount mnt/fat32

sudo umount mnt/ext4

JTAG pin configuration	nrogram.
Jirio pin comiguianon	program.

download JtagEnabler.cpp for Rpi1 from internet and crosscompile it and generate a.out and put executable(./a.out)in the SD card partition.

Enabling JTAG pins:

After SD card flashed, put it in the board's SD card slot. Then After when kernel boot and you get the prompt, go to the directory where ./a.out was kept and execute it.

username and password to login into board:

username: pi

password: raspberry

Trace32:

After making connection as shown in the wiki image, launch trace32 and execute below commnad in t32 prompt.

SYSTEM.CPU ARM1176JZF

and then as shown in attched image tronchip.png , untick all the exceptions listed under "set" tab .Then execute below command

SYSTEM.CPUACCESS Enable

SYSTEM.MODE ATTACH

DATA.LOAD.ELF c:\Users\Administrator\Documents\new\linux-rpi-3.10.y\vmlinux /NOCODE Y.SPATH.SRD c:\Users\Administrator\Documents\new\linux-rpi-3.10.y\

Now , you are ready to set the breakpoint and debug ,but this will let you to debug only kernel code in which you have place

breakpoint and if application call that function but you will not able to debug the code which is executing in the start of the kernel

becuase we are enabling JTAG pins after kernel boots; so to debug at kernel booting level, implement the JtagEnable.cpp logic

before kernel boots at uboot level.

USEFUL LINKS:

LINKS:

 $https://wiki.globaledgesoft.com/index.php/JTAG_Debugging_on_Raspberry_Pi\#Preparing_Rasberry_PI_for_JTAG_.26_README$

https://www.raspberrypi.org/documentation/linux/kernel/building.md

http://sysprogs.com/VisualKernel/tutorials/raspberry/jtagsetup/

https://github.com/raspberrypi/linux/tree/rpi-3.10.y

https://elinux.org/RPi_U-Boot

https://github.com/gonzoua/u-boot-pi

https://wiki.globaledgesoft.com/index.php/Raspberry_Pi

https://devsidestory.com/build-a-64-bit-kernel-for-your-raspberry-pi-3/