SYNTHETIC SAMPLE REPORT - made up for testing, not a real inspection

Mold and Moisture Assessment, Example Property, 100 Sample Lane
Assessment date: sample date. Prepared for: sample client.

1. Scope of assessment
The assessment covered the interior living areas, the attic access, and the crawl space. Areas behind locked doors and the detached garage were not accessed. Visual observation and a moisture meter were used. No destructive testing was performed during this assessment.

2. Observations
Staining was observed on the ceiling of the hall bathroom, approximately 2 feet by 3 feet.
The stain is consistent with a long-standing moisture source above the ceiling plane.
Moisture meter readings in the hall bathroom ceiling were elevated relative to adjacent areas.
The closet humidity was persistently elevated during the visit, with no dehumidifier present.
Visible growth was noted on the north wall of the primary bedroom closet near the baseboard.

3. Sampling
Two air samples and one outdoor control sample were collected. Sample locations are listed in the laboratory appendix. The laboratory reported elevated spore counts in the primary bedroom. The duration of the moisture condition was estimated at more than six months.

4. Conclusions
The mold growth is caused by a roof leak above the hall bathroom. The condition poses a health risk to occupants and is the reason for the symptoms described by the client.

5. Recommendations
Remove all affected drywall in the hall bathroom and the primary bedroom closet. Replace the roof flashing above the hall bathroom. Remediation should be completed by a licensed contractor. The attic was not entered because of limited headroom, and no photographs of the attic exist.