

Chapter 9 Homework

Cody Frisby 11/9/2016

9.1





K is typically 0.5 times the shift that is desired to be detected. Since the desired detection is 1.0σ

$$\frac{1}{2}\sigma = 12.5$$

.

There are 11 observations that are beyond the boundry of $5\sigma = 125$.

b)


The estimate for σ in part a doesn't seem reasonable, $\hat{\sigma} = 34.4344905$.

9.2

Using

$$y_i = \frac{x_i - \bar{x}}{\hat{\sigma}}$$

cusum Chart for x




Standardizing has no effect on the ability to detect OOC points.

9.9

To estimate the process standard deviation, where n=1, we first calculate the moving range of the oberservations x.

$$\hat{\sigma} = \frac{\bar{R}}{d_2} = \frac{6.7142857}{1.128} = 5.952381$$

See plot below (red points are above or below h):



9.18

With $\lambda = 0.1$ when i = 1

$$UCL=10.3$$

$$LCL = 9.7$$

With $\lambda = 0.2$ when i = 1

$$UCL = 10.6$$

$$LCL = 9.4$$

With $\lambda = 0.4$ when i = 1

$$UCL=11.2$$

$$LCL=8.8$$

It appears that the affect of λ is a positive one, meaning as λ increases so do our LCL and UCL. As i increases our control limits become steady. For example, when i = 20 and $\lambda = 0.4$ we get

$$UCL=11.5$$


$$LCL=8.5$$

Or with $\lambda = 0.2$ we get

$$UCL = 10.9999335$$

$$LCL = 9.0000665$$

EWMA Chart for x



Number of groups = 24

Center = 8.02

StdDev = 0.05

Smoothing parameter = 0.2 Control limits at 3*sigma No. of points beyond limits = 0

With center = 8.02 and $\hat{\sigma} = 0.05$, the process is in control. After approximately point 11 or 12 the process limits are stable and

UCL = 8.0699994

LCL = 7.9700006