

QDOS Assistance
1st Floor, Barfield House
24-28 alderley Road
Wilmslow
Cheshire
SK9 1PL

Date: 11/06/2026
Our Ref: 00038025/NOELB
Your Ref: 45282/1

To the Court REPAIRABLE REPORT

Dear Sirs,
Client: **Mr Connor Smith**

We refer to your instructions received on **10 June 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: AUDI A3 SE TFSI	Colour: Red	Speedo: 80134	Miles
Reg No: L21CSR	Registered: Jan 2015	Type: 5 Door Hatchback	Trans: Manual
Vin No: WAUZZZ8VXFA093076	MOT Exp: 	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2015		
Brakes: Not Known	Tax Exp: 		
Steering: Not Known	Fuel: Petrol		
Extras: Not Seen	C.C.: 1395		
Air Bags Deployed: Not Known	BHP: 123.	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Light to Moderate Collision/Impact RH Rear Bumper	Incident: 10/05/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £6,825.00		Repair Cost: £4,060.16 inc VAT	(59.49% of PAV)
		Roadworthy: Yes	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the right hand rear bumper.

VEHICLE HISTORY CHECK

According to the Experian database; According to the Experian database; There is a plate change on record. See plate change details.

REPAIR SCHEDULE

New parts required:-Rear Cover Bumper, L/R Bumper Reinf, R/R Bumper Reinf, Rear Bumper Support, Rr Bumper Clamp Kit, L/R Badge, R/R Badge, Rear Badge, L/S Window Bond Kit, R/S Window Bond Kit, Side Window Primer, Cutting Filament, Cleaning Solution, Applicator, Sundry Parts

Repaint only parts:-Rear Cover Bumper New Part Paint K1r, De Nib & Polish.Per Panel, Preparation For Pre-Painting

Specialist/Sundry charges:-Repair Sundries, Car Care Kit, Assesment Fee, Epa Charge, Aries Support, Pas 2060 / Aries

Blend only parts:-Rr Towing Lug Cover Surface Paint Plast., Lower Tailgate Surface Paint, L/R Side Panel Surface Paint, R/R Side Panel Surface Paint

Remove And Refit parts:-Description, Gfs / Guided Function, Rear Wheel (Wheels), Rear Number Plate, Lower Tailgate Trim, Rear Badges, Tailgate Handle, Both Inner Taillamps, Rear Bumper Cover, Renew Rear Bumper

Cover, Rear Impact Support, L/R Wheelhouse Shell, R/R Wheelhouse Shell

Parts to check:-Qc And Road Test, And Valet, Veh Diag Pre, Veh Diag Post, Est Pre Wash

COST OF REPAIRS

No estimate has been obtained for repairing the vehicle but, **subject to further damage found during dismantling**, we have calculated the time involved in such a repair using Audatex and we consider that a reasonable labour charge would be £1,391.31. The cost of the paint and materials would be £834.15, The cost of the replacement parts would be approximately £861.35, The specialist/sundry charges would be £296.66, and the VAT liability on the total would amount to some £676.69 giving a total repair cost of £4,060.16 including VAT **subject to undisclosed damage**. The labour charge is based on 13.5 hours at a rate of £103.06 per hour.

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 16/01/2015. The corresponding CAP Guide (model code: 64696) adjusted retail value for vehicles of this type and age in the May 2026 guide is £6,825.00 at 80134 Miles, trade value is £4,775.00 and mid value is £5,800.00. We place the pre-accident value of this particular vehicle at £6,825.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £4,075.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We confirm that we have not authorised repairs on your behalf and our actions in this matter remain without prejudice.

REPAIR DURATION

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. QDOS Assistance commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Noel Barnes Dip VDA AQP
Exclusive Vehicle Assessors



Imageofclientdamage1jpg-V1.jpg



2_Imageofclientdamage2jpg-V1.jpg



1_Mileage-V1.jpeg



4_VIN-V1.jpeg