

Mrs Jessica Hallford
2 Holly Blue Way
Workshop
S
Workshop
S81 7FW

Date: 04/06/2026
Our Ref: 00037302/JEFFP
Your Ref: EHR102443

To the Court **REPAIRABLE REPORT**

Dear Sirs,

Client: **Mrs Jessica Hallford**

We refer to your instructions received on **30 May 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: AUDI A4 S LINE TFSI	Colour: Grey	Speedo: 62353	Miles
Reg No: NL18XWA	Registered: Apr 2018	Type: 4 Door Saloon	Trans: Manual
Vin No: WAUZZZF44JA159978	MOT Exp:	R/H/F Tyre 5	R/H/R Tyre 5
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manfd: 2018		Spare Tyre
Brakes: Not Known	Tax Exp:		Not Known
Steering: Not Known	Fuel: Petrol		Centre Belt
Extras: Not Seen	C.C.: 1395		Not Tested
Air Bags Deployed: Not Known	BHP: 148	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Light to Moderate Collision/Impact Rear Bumper	Incident: 29/05/2026	L/H/F Tyre 5	L/H/R Tyre 5
Vehicle Value: £12,108.00		Repair Cost: £3,675.80 inc VAT	(30.36% of PAV) Roadworthy: Yes

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the rear bumper.

VEHICLE HISTORY CHECK

04/06/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Sundry Parts

Repairable parts:-Rear Cover Bumper, Rear Bumper Spoiler

Repaint only parts:-Description, Rear Cover Bumper Repair Paint Plastic, R.Lower Spoiler Re-Texture, R.Bumper Ctr Mldg Re-Texture, Preparation For Pre-Painting

Specialist/Sundry charges:-Bs10125 Fee, Methods Research, Aries Fee, Panel Repair Sundry, Adas Methods, Adas Recalibration, E.P.A. Charge, Car Care Kit, Wheel Alignment, Tech Data + Methods

Blend only parts:-Rear Cover Surface Paint Plast., L/R Outer Sensor Surface Paint Plast., R/R Outer Sensor Surface Paint Plast., L/R Inner Sensor Surface Paint Plast., R/R Inner Sensor Surface Paint Plast., Machine Polish Surface Paint

Remove And Refit parts:-Description, Rear Wheel (Wheels), Rear Bumper Cover, Rear Bumper Spoiler, Rear Inner Parking Aid Sensors, Rear Towing Hook Cover, L/R Wheelhouse Shell, R/R Wheelhouse Shell, Rr Bumper Ctr

Cover, L/R Reflector, R/R Reflector

Parts to check:-Rear Bumper Support, Rear Panel, Estimate Pre-Clean, And Clean Car, And Road Test & Qc, Veh Diag Pre, Veh Diag Post, Adas Exploration Fee, Adas Roadtest

COST OF REPAIRS

The repairers, CRS Accident Repair Centre (Tel. 0114 308 1599), have compiled an estimate in the sum of £2,050.89 plus £412.22 for paint and materials plus £600.06 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 19.9 hours at a rate of £103.06 per hour. We have also agreed that the cost of paint and materials will be limited to £412.22. No new parts are required and the specialist/sundry charges will be £600.06, the VAT liability on this repair will amount to some £612.63 giving a total repair cost of £3,675.80 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 20/04/2018. The corresponding Cazana Guide (model code: 894059) adjusted retail value for vehicles of this type and age in the May 2026 guide is £12,108.00 at 62353 Miles, trade value is £10,413.00 and mid value is £11,260.50. We place the pre-accident value of this particular vehicle at £12,108.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £3,700.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 4th June 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 5 to 6 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy.

The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Jeff Parr CAE AMIMI
Exclusive Vehicle Assessors