

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

2/2

Mr A Petherbridge
16 Spindle Road
Haverhill
Suffolk
CB9 9ES

Date: 12/03/2026
Our Ref: 00077510/GC
Your Ref: EHR97455

Engineer Repairable Report - Supplementary Report

Dear Sirs,

Client/Insured: **Mr A Petherbridge**

We refer to your instructions received on **04 March 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: FORD PUMA ST-LINE X MHEV	Colour: BLACK	Speedo: 19158	Miles
Reg No: GX22KUS	Registered: May 2022	Type: 5 Door Hatchback	Trans: Manual
Vin No: WF02XXERK2NY63710	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2022		Spare Tyre
Brakes: Not Known	Tax Exp:		Not Know
Steering: Not Known	Fuel: Petrol		Centre Belt
Extras: Not Seen	C.C.: 999		Not Tested
Air Bags Deployed: Not Known	BHP: 152.	L/H/F Belt Not Tested	L/H/R Belt Not Tested
Damage: Accidental Damage	Incident: 19/02/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno



Vehicle Value: £15,841.00	Repair Cost: £4,504.01 inc VAT	(28.43% of PAV)	Roadworthy: Yes
----------------------------------	---------------------------------------	-----------------	------------------------

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light accidental damage to the rear bumper, and moderate accidental damage to the boot.

ENGINEER'S COMMENTS

13/04/2026 - Supplementary cost: Repair costs have increased due to the Rear Lower Bumper Cover needing to be repaired.

VEHICLE HISTORY CHECK

04/03/2026 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rear Number Plate, Bootlid/Tailgate, Tailgate Handle, Rear Door Lock, Lock Motor, Rear Badge, Badge Model, Badge Motor Typ, Rear Screen Bond Kit, Rear Number Plate

Repairable parts:-Repair Rear Bumper, Repair Rr Bumper Wind Defl

Repaint only parts:-Bootlid/Tailgate New Part Painting, Rear Bumper Repair Paint Plastic, Rr Bumper Wind Defl Repair Paint Plastic, Machine Polish, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Bs10125, Methods Research, Aries Support, Car Care Kit, E.P.A. Charge, Panel

Repair Sundrie, Sundry Part, Anti-Corrosion

Remove And Refit parts:-Rear Parking Aid Sensor/S, Rear Bumper, L/R Reflector, Right Rear Foglamp, Renew Tailgate, Rear No-Plate, Corrosion Prote To 1St Panel

Parts to check:-Check And Clean Car, Check And Quality Control, Check Veh Diag Pre Check, Check Veh Diag Post Check

COST OF REPAIRS

The repairers, Haverhill Steer, CB9 8PB, have compiled an estimate in the sum of £1,299.17 plus parts at manufacturer's list prices plus £738.84 for paint and materials plus £230.13 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be low and we have agreed an amended labour figure of £1,640.62. The labour charge is based on 19.7 hours at a rate of £83.28 per hour. We have also agreed that the cost of paint and materials will be limited to £905.40. The cost of the necessary replacement parts will be approximately £977.19, the specialist/sundry charges will be £230.13, the VAT liability on this repair will amount to some £750.67 giving a total repair cost of £4,504.01 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 30/05/2022. The corresponding Glass's Guide retail value for vehicles of this type and age in the February 2026 guide is £15,841.00 at 19158 Miles, trade value is £13,724.00 and mid value is £14,782.50. We place the pre-accident value of this particular vehicle at £15,841.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £4,525.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 12th March 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 6 to 7 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Exclusive Repair Network commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

Connexus Vehicle Assessors