

Mrs Janet Causer
42 Holme Land
Ingleby Barwick
Stockton-on
TS
Ingleby Barwick
TS17 5FB

Date: 10/04/2026
Our Ref: 00033575/JEFFP
Your Ref: EHR99336

To the Court
REPAIRABLE REPORT

Dear Sirs,
Client: **Mrs Janet Causer**

We refer to your instructions received on **02 April 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle:	SEAT IBIZA XCELLENCE TSI		Colour:	GREY	Speedo:	20190	Miles
Reg No:	NX24UUZ	Registered:	Mar 2024	Type:	5 Door Hatchback	Trans:	Manual
Vin No:	VSSZZZKJ5RR078319	MOT Exp:		R/H/F Tyre	5	R/H/R Tyre	5
Mods:	Not Seen	Cond:	Good	R/H/F Belt	Not Tested	R/H/R Belt	Not Tested
Audio:	Not Seen	Manfd:	2024				Spare Tyre
Brakes:	Not Known	Tax Exp:					Not Know
Steering:	Not Known	Fuel:	Petrol				Centre Belt
Extras:	Not Seen	C.C.:	999				Not Tested
Air Bags Deployed:	Not Known	BHP:	93.9	L/H/F Belt	Not Tested	L/H/R Belt	Not Tested
Damage:	Light to Moderate Collision/Impact RH Rear Bumper		Incident:	30/03/2026	L/H/F Tyre	5	L/H/R Tyre 5
Vehicle Value: £15,784.00		Repair Cost: £2,803.92 inc VAT		(17.76% of PAV)		Roadworthy: Yes	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the right hand rear bumper.

VEHICLE HISTORY CHECK

10/04/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rear Bumper, R/R Bumper Guide, L/R Sensor Bracket, R/R Sensor Bracket, Rr Ctr Sensor Brkt, Primer, Trim Lifting, Sundry Parts

Repaint only parts:-Description, Rear Bumper New Part Paint K1r, X2 Detail Mask Quarters Glass, De Nib & Polish.Per Panel, Preparation For Pre-Painting

Specialist/Sundry charges:-E.P.A. Charge, Car Care Kit, Tech Data + Methods

Blend only parts:-L/R Side Panel Surface Paint, R/R Side Panel Surface Paint

Remove And Refit parts:-Description, Left Rear Wheelhouse Shell, Right Rear Wheelhouse Shell, Both Rear



Lamps, Rear Bumper, Renew Rear Bumper Cover, Rear Bumper Drill, Fuel Flap, Rear Wheel (Wheels), Road Test Quality Control

Parts to check:-Rear Bumper Spoiler, Rear Bumper Support, Rr Ctr Bumper Brkt, Rear Panel, R/R Lamp, R/R Reflector, R/R Wheelhouse Cvr, Pre Rep Diag Scan, Post Rep Diag Scan, Wash And Vacuum, Est Pre Wash

COST OF REPAIRS

The repairers, Preston Farm body and paint (Tel. 01642 673 345), have compiled an estimate in the sum of £1,032.67 plus parts at manufacturer's list prices plus £793.31 for paint and materials plus £86.64 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 12.4 hours at a rate of £83.28 per hour. We have also agreed that the cost of paint and materials will be limited to £793.31. The cost of the necessary replacement parts will be approximately £423.98, the specialist/sundry charges will be £86.64, the VAT liability on this repair will amount to some £467.32 giving a total repair cost of £2,803.92 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 22/03/2024. The corresponding Cazana Guide (model code: 3522217) adjusted retail value for vehicles of this type and age in the March 2026 guide is £15,784.00 at 20190 Miles, trade value is £14,679.00 and mid value is £15,231.50. We place the pre-accident value of this particular vehicle at £15,784.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £2,825.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 10th April 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Jeff Parr CAE AMIMI
Exclusive Vehicle Assessors