

QDOS Assistance
1st Floor, Barfield House
24-28 alderley Road
Wilmslow
Cheshire
SK9 1PL

Date: 30/03/2026
Our Ref: 00033385/MATTG
Your Ref: 44327/1

To the Court REPAIRABLE REPORT

Dear Sirs,
Client: **Mr Zain Qureshi**

We refer to your instructions received on **28 March 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: RENAULT CLIO ESPRIT ALPINE ETECH		Colour: BLACK	Speedo: 10946 Miles	
Reg No: BG25DDL	Registered: Mar 2025	Type: 5 Door Hatchback	Trans: Automatic	
Vin No: VF1RJA00274557987	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Very Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manfd: 2025			
Brakes: Not Known	Tax Exp:			Spare Tyre Not Known
Steering: Not Known	Fuel:			Centre Belt Not Tested
Extras: Not Seen	C.C.: 1598			
Air Bags Deployed: Not Known	BHP: 140.	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Damage: Light Collision/Impact LH Side Mirror	Incident: 25/03/2026	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Vehicle Value: £18,982.00		Repair Cost: £2,329.62 inc VAT (12.27% of PAV)	Roadworthy: No	

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light collision/impact damage to the left hand side mirror.

ENGINEER'S COMMENTS

The engineer has inspected this vehicle from images supplied by the principal only, the repair costs have been based on the images received and therefore may not be accurate if further damage is found, condition details and service records have not been checked in relation to the pre-accident value.

VEHICLE HISTORY CHECK

We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:- L/Door Mirror, L/Door Mirror Cover, L/Lower Mirror Cover, Panel Sundries, Car Care Kit, Glass Lifting Tape, Sundry Parts



Repaint only parts:-L/Door Mirror Cover New Part Paint K1r, De Nib & Polish. Per Panel, Preparation For Pre-Painting

Specialist/Sundry charges:-Bsi Compliance, Adas Methods, Geometry Check, Epa, Corrosion Protection Materials External

Blend only parts:-L/F Lower Door Surface Paint, L/F Door Out Handle Surface Paint Plast.

Remove And Refit parts:-Description, Left Front Door Trim, Outer Handle L/Frt Door, Left Mirror, Renew L/Door Mirror (Removed), Corrosion Prote To 1St Panel

Parts to check:-Adas Exploration, Qc & Road Test, Pre Rep Diag Scan, Post Rep Diag Scan, Wash And Vaccum, Est Pre Wash

COST OF REPAIRS

No estimate has been obtained for repairing the vehicle but, **subject to further damage found during dismantling**, we have calculated the time involved in such a repair using Audatex and we consider that a reasonable labour charge would be £774.50. The cost of the paint and materials would be £346.58, The cost of the replacement parts would be approximately £581.37, The specialist/sundry charges would be £238.90, and the VAT liability on the total would amount to some £388.27 giving a total repair cost of £2,329.62 including VAT **subject to undisclosed damage**. The labour charge is based on 9.3 hours at a rate of £83.28 per hour.

PRE-INCIDENT CONDITION

The vehicle is considered to be in very good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 20/03/2025. The corresponding Percayso Guide (model code: 9752231) adjusted retail value for vehicles of this type and age in the March 2026 guide is £18,982.00 at 10946 Miles, trade value is £16,514.00 and mid value is £17,748.00. We place the pre-accident value of this particular vehicle at £18,982.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £2,350.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We confirm that we have not authorised repairs on your behalf and our actions in this matter remain without prejudice.

REPAIR DURATION

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained due to NSF mirror damaged.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. QDOS Assistance commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Jeff Parr CAE AMIMI
Exclusive Vehicle Assessors



2_Wingmirrordamage-V1.jpg



Mileage-V1.jpg



1_CLVreg-V1.jpg



1_Wingmirror-V1.jpg