

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

Mr M Lacey
27 Walnut Way
Ruislip
Middlesex
HA4 6TA

Date: 08/09/2025
Our Ref: 00072530/PK
Your Ref: EHR87754

Engineer Repairable Report

Dear Sirs,

Client/Insured: **Mr M Lacey**

We refer to your instructions received on **22 August 2025** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle:	PEUGEOT 208 ALLURE PURETECH S/S		Colour:	BLACK	Speedo:	43116	Miles
Reg No:	KR24EGU	Registered:	Mar 2024	Type:	5 Door Hatchback	Trans:	Manual
Vin No:	VR3UPHNE5R5029590	MOT Exp:		R/H/F Tyre		R/H/R Tyre	
Mods:		Cond:	Good	R/H/F Belt		R/H/R Belt	
Audio:		Manf'd:	2024				Spare Tyre
Brakes:	Not testable	Tax Exp:					
Steering:	Not testable	Fuel:	Petrol				Centre Belt
Extras:		C.C.:	1199				
Air Bags Deployed:		BHP:	99.2	L/H/F Belt		L/H/R Belt	
Damage:	Light Accidental Damage RH Front Bumper	Incident:	15/08/2025	L/H/F Tyre		L/H/R Tyre	



Vehicle Value:	£13,260.00	Repair Cost:	£3,142.87 inc VAT	(23.70% of PAV)	Roadworthy:	Yes
----------------	-------------------	--------------	--------------------------	-----------------	-------------	------------

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light accidental damage to the right hand front bumper, and to the wing.

VEHICLE HISTORY CHECK

22/08/2025 - We confirm having checked this vehicle on the Experian Auto Check database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-R/F Bumper Bracket, Frt Bumper Clamp Kit, R/Screw, R/Rivet, R/Screw, R/F Wing Bracket Frt, R/F Tyre, Lift Tape, Panel Sundries

Repairable parts:-Repair Front Bumper, Repair R/F Wing

Repaint only parts:-Front Bumper Repair Paint Plastic, R/F Wing Repair Painting <50%, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Bs10125, Car Care Kit, Diamond Cut Ref, Energy Payment, Methods Research, Post Check, Pre Check, Wheel Align Check, Sundry Part, Epa

Remove And Refit parts:-Right Front Wing, Front Number Plate, Front Bumper Grille, R/F Wing Bracket, Adjust Headlamps, Both Front Daytime Running Lights, R/F Tyre (Wheel Removed), R/Front Wheel Balance, Ice Shutdown, Spare Wheel Swop

Parts to check:-Check Adas Exploration, Check Pre Clean, Check Road Test/Qc, Check Wash And Vac

COST OF REPAIRS

The repairers, Junction Road Motor Company, 6-8 Woodside Grove, London, N12 8QU (Tel. 08084451242), have compiled an estimate in the sum of £1,499.60 plus parts at manufacturer's list prices plus £397.17 for paint and materials plus £627.24 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be high and we have agreed a reduction with the repairers of £101.20 to £1,398.40 in their final account. The labour charge is based on 15.2 hours at a rate of £92.00 per hour. We have also agreed that the cost of paint and materials will be limited to £397.17. The cost of the necessary replacement parts will be approximately £209.17, the specialist/sundry charges will be £614.32, the VAT liability on this repair will amount to some £523.81 giving a total repair cost of £3,142.87 including VAT **subject to any undisclosed damage. We are pleased to confirm that we have achieved total gross savings in this matter of £579.74.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 27/03/2024. The corresponding Glass's Guide (model code: 4P8Y) adjusted retail value for vehicles of this type and age in the August 2025 guide is £13,260.00 at 43116 Miles, trade value is £11,330.00 and mid value is £12,295.00. We place the pre-accident value of this particular vehicle at £13,260.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £3,150.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 8th September 2025, on your behalf.

REPAIR DURATION

We consider that this repair will take some 5 to 6 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it un roadworthy.

The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Exclusive Repair Network commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of