

Tel: 01925 403405
Fax: 0845 077 0806
Email: engineer@connexus.co.uk

2/2

Mrs A Chadwick
38 Dalegarth Avenue
Liverpool
L12 0AJ

Date: 02/04/2026
Our Ref: 00077229/PK
Your Ref: EHR97111

Engineer Repairable Report - Amended Report

Dear Sirs,

Client/Insured: **Mrs A Chadwick**

We refer to your instructions received on **19 February 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: RENAULT CLIO PLAY TCE	Colour: WHITE	Speedo: 71729	Miles
Reg No: H14NGC	Registered: Sep 2018	Type: 5 Door Hatchback	Trans: Manual
Vin No: VF1R9800261128513	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested
Audio: Not Seen	Manf'd: 2018		
Brakes: Not Known	Tax Exp:		
Steering: Not Known	Fuel: Petrol		
Extras: Not Seen	C.C.: 898	Spare Tyre Not Known	
Air Bags Deployed: Not Known	BHP: 75.1	Centre Belt Not Tested	
Damage: Light to Moderate Accidental Damage LH Rear Door	Incident: 19/02/2026	L/H/F Belt Not Tested	L/H/R Belt Not Tested
		L/H/F Tyre Not Kno	L/H/R Tyre Not Kno
Vehicle Value: £5,395.00	Repair Cost: £3,865.07 inc VAT	(71.64% of PAV)	Roadworthy: Yes

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate accidental damage to the left hand rear door, to the quarter panel, and to the bumper

ENGINEER'S COMMENTS

21/05/2026 - Final costs

VEHICLE HISTORY CHECK

19/02/2026 - According to the Experian database; there is a plate change on record

REPAIR SCHEDULE

New parts required:-L/R Door Check, L/R Park Sys Sensor

Repairable parts:-Repair Methods, Repair L/R Door Lower, Repair L/R Side Panel, Repair L/Inner Door Frame

Repaint only parts:-L/R Park Sys Sensor New Part Paint K1r, L/R Door Lower Repair Painting <50%, Rear Bumper

Repair Paint Plastic, L/R Side Panel Repair Painting <50%, L/R Bumper Extension surface Paint Plast., Fuel Filler

Flap Surface Paint Plastic., Left Rear Dr Frame Repair Paint, L/R Door Apperture Detail Mask, L/R Side Pnl Trim

Detail Mask, L/Roof Rail Polish Fade Out, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Aries Charge, Bs10125 Charge, Car Care Kit, E.P.A. Charge, 4 Wheel Alignment,

Sundry Part, Repair Methods, Anti-Corrosion

Remove And Refit parts:-Left Rear Door, Left Rear Door Trim, Left Rear Door Speaker, L/R Outer Door Channel Moulding, L/R Door Protective Mldg, Left Rear Door Check, L/R Door Seal, Rear Bumper, Rear Bumper Skirt, Left Rear Reflector, Right Rear Reflector, L/R Number Plate Lamp, L/R Bumper Extension, Left Rear Wheel, Right Rear Wheel, Wheel/S (Add/Work), Fuel Flap, Rear Parking System Sensor/S, Set Up Flat Liner, Allowance Post Repair Sweep, Inc Sanitise Pre Repair Clean, Allowance Pre Repair Sweep, Allowance R/Test & Final QC , Corrosion Protection 2 Panels

COST OF REPAIRS

The repairers, D Walton, Unit 4 Orion Trade Centre, Tenax Road, Manchester, M17 1JT (Tel. 0161 872 8090), have compiled an estimate in the sum of £1,807.18 plus parts at manufacturer's list prices plus £643.72 for paint and materials plus £317.35 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be low and we have agreed an amended labour figure of £2,181.94. The labour charge is based on 26.2 hours at a rate of £83.28 per hour. We have also agreed that the cost of paint and materials will be limited to £665.67. The cost of the necessary replacement parts will be approximately £80.83, the specialist/sundry charges will be £292.45, the VAT liability on this repair will amount to some £644.18 giving a total repair cost of £3,865.07 including VAT **subject to any undisclosed damage. We are pleased to confirm that we have achieved total gross savings in this matter of £29.88.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 10/09/2018. The corresponding Glass's Guide (model code: 268802001) adjusted retail value for vehicles of this type and age in the February 2026 guide is £5,395.00 at 71729 Miles, trade value is £3,416.00 and mid value is £4,405.50. We place the pre-accident value of this particular vehicle at £5,395.00 bearing in mind the condition described herein.

RESERVE

We consider that a repair reserve of £3,875.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 2nd April 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 8 to 9 working days to complete. This would be subject to the availability of parts and any extra repairs found once the repairs commence.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it un roadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Exclusive Repair Network commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



. AQP CAE AMIMI
Connexus Vehicle Assessors