

Mr Robert Walker
1 Old Oak Gardens
Morton Road
Woking
GU
Morton Road
GU21 4AG

Date: 05/01/2026
Our Ref: 00027703/COHARE
Your Ref: EHR94474

To the Court REPAIRABLE REPORT

Dear Sirs,
Client: **Mr Robert Walker**

We refer to your instructions received on **24 December 2025** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle: FORD S-MAX TITANIUM TDCI		Colour: GREY	Speedo: 77963	Miles
Reg No: LN67XHS	Registered: Sep 2017	Type: M.P.V.	Trans: Manual	
Vin No: WF0JXXWPCJHG65034	MOT Exp:	R/H/F Tyre Not Kno	R/H/R Tyre Not Kno	
Mods: Not Seen	Cond: Good	R/H/F Belt Not Tested	R/H/R Belt Not Tested	
Audio: Not Seen	Manfd: 2017			Spare Tyre
Brakes: Not Known	Tax Exp:			Not Know
Steering: Not Known	Fuel: Diesel			Centre Belt
Extras: Not Seen	C.C.: 1997			Not Tested
Air Bags Deployed: Not Known	BHP: 147.	L/H/F Belt Not Tested	L/H/R Belt Not Tested	
Damage: Moderate Accidental Damage RH Front Complete Vehicle	Incident: 23/12/2025	L/H/F Tyre Not Kno	L/H/R Tyre Not Kno	
Vehicle Value: £10,464.00		Repair Cost: £3,836.82 inc VAT	(36.67% of PAV)	Roadworthy: No

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered moderate accidental damage to the right hand front complete vehicle.

VEHICLE HISTORY CHECK

05/01/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Front Bumper, R/F Out Bumper Brkt, R/F Bumper Grille, Grille Badge, R/F Wing, R/F Wheelhouse Cover

Repaint only parts:-R/F Wing New Part Painting, Front Spoiler Repair Paint Plastic, R/Wing Grille Surface Paint Plast., R/F Door To Window Surface Paint, Side Glass Mask Surface Paint, De Nib, Pre-Painting Sundry Materials, Preparation for Pre-Painting

Specialist/Sundry charges:-Car Care Kit, E.P.A. Charge, Methods Research, Pre And Post Sweeps, Energy Payment, Pas2060, Sundry Part, Anti-Corrosion



Remove And Refit parts:-Add/Time For One Main Position, Alignment Cpl Before Repair, Front Bumper, Renew Front Bumper (Removed), Add/Work For Parking Aid, Right Front Bumper Bracket, Right Headlamp, Adjust Headlamps, Calibrate Adas Attach Parts, Right Front Wing, R/F Door Trim, Right Front Door Handle, R/F Outer Door Channel Moulding, R/Outer Mirror, Simple Road Test, For Repairs Close Down Vehicle, Corrosion Prote Pre Repair Clean, Corrosion Prote To 1St Panel

Parts to check:-Check Wash & Vacuum, Check Adas Exploration

COST OF REPAIRS

The repairers, R&R Autos Bodyshop (Tel. 01256 353736), have compiled an estimate in the sum of £1,200.00 plus parts at manufacturer's list prices plus £583.38 for paint and materials plus £347.33 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 15 hours at a rate of £80.00 per hour. We have also agreed that the cost of paint and materials will be limited to £583.38. The cost of the necessary replacement parts will be approximately £1,066.64, the specialist/sundry charges will be £347.33, the VAT liability on this repair will amount to some £639.47 giving a total repair cost of £3,836.82 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 30/09/2017. The corresponding Glass's Guide (model code: 261228001) adjusted retail value for vehicles of this type and age in the December 2025 guide is £10,464.00 at 77963 Miles, trade value is £7,491.00 and mid value is £8,977.50. We place the pre-accident value of this particular vehicle at £10,464.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £3,850.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 5th January 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 4 to 5 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle was not roadworthy at the time of our inspection as a result of the damage sustained due to Possible Headlamp damaged and geo required. We understand that the vehicle is still being used by the owner.

TEMPORARY REPAIRS

We suggest that it would not be practical to consider cost effective temporary repairs on this occasion to make this vehicle roadworthy.

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions (ACHL) commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of

C O'Hare

Chris O'Hare AMIMI IMI VDA
Exclusive Vehicle Assessors