

Mr Saagar Habib
800 Walsall Road
Great Barr
Birmingham
B
Birmingham
B42 1EU

Date: 29/05/2026
Our Ref: 00034970/JEFFP
Your Ref: EHR100515 \ HMP7012732950

To the Court
REPAIRABLE REPORT - Supplementary Report

Dear Sirs,
Client: **Mr Saagar Habib**

We refer to your instructions received on **23 April 2026** and we confirm that we have attended to this matter and we are pleased to report our findings as follows;

Vehicle:	MERCEDES-BENZ A 200 D AMG LINE E		Colour:	WHITE	Speedo:	75319	Miles
Reg No:	WU17ZKO	Registered:	Mar 2017	Type:	5 Door Hatchback	Trans:	Manual
Vin No:	WDD1760082J592467		MOT Exp:		R/H/F Tyre	Not Kno	R/H/R Tyre Not Kno
Mods:	Not Seen	Cond:	Good	R/H/F Belt	Not Tested	R/H/R Belt	Not Tested
Audio:	Not Seen	Manfd:	2017			Spare Tyre	
Brakes:	Not Known	Tax Exp:				Not Known	
Steering:	Not Known	Fuel:	Diesel			Centre Belt	
Extras:	Not Seen	C.C.:	2143			Not Tested	
Air Bags Deployed:	Not Known	BHP:	134	L/H/F Belt	Not Tested	L/H/R Belt	Not Tested
Damage:	Light to Moderate Collision/Impact Rear Bumper		Incident:	21/04/2026	L/H/F Tyre	Not Kno	L/H/R Tyre Not Kno
Vehicle Value:		£10,107.00		Repair Cost:	£3,620.27 inc VAT		(35.82% of PAV) Roadworthy: Yes

DESKTOP ASSESSMENT

This report has been compiled from a desktop review of the information available relating to this claim.

NATURE OF INCIDENT

The vehicle has suffered light to moderate collision/impact damage to the rear bumper.

ENGINEER'S COMMENTS

29/05/2026 - Supplementary for new Rear Crossmember, Rivets.

VEHICLE HISTORY CHECK

29/04/2026 - We confirm having checked this vehicle on the Experian AutoCheck database and there is no record of any adverse history.

REPAIR SCHEDULE

New parts required:-Rear Bumper Cover, Rear Lower Bumper, Rear Bumper C-Member, Rivets X 20, Sundry Parts

Repaint only parts:-Description, Rear Bumper Cover Painting, Add Colour Sample 1, Additional Work, And Polish De-Nib, Security Measures Before, Preparation Work For Two Coat Painting, Carry Out Colour Shade Determination



Specialist/Sundry charges:-Bs10125 Admin Fee, Adas Methods, Car Care Kit, E.P.A. Charge, Tech Data + Methods, Aries Support

Remove And Refit parts:-Description, Left Rear Wheelhouse Shell, Right Rear Wheelhouse Shell, Rear Bumper, Add To Renew Rear Bumper, Dis + Ass Rear Bumper (Removed), Rear Bumper Carrier, Both Rear Lamps, Pre-Clean Vehicle For Repair, Final Check Road Test And Qc

Parts to check:-Veh Diag Pre, Veh Diag Post, Wash & Vac, Adas Exploration

COST OF REPAIRS

The repairers, XL Motors Ltd (Tel. 02476362181), have compiled an estimate in the sum of £1,267.64 plus parts at manufacturer's list prices plus £499.33 for paint and materials plus £177.66 for specialist/sundry charges. Having calculated the time involved in this repair we consider this to be reasonable. The labour charge is based on 12.3 hours at a rate of £103.06 per hour. We have also agreed that the cost of paint and materials will be limited to £499.33. The cost of the necessary replacement parts will be approximately £1,072.26, the specialist/sundry charges will be £177.66, the VAT liability on this repair will amount to some £603.38 giving a total repair cost of £3,620.27 including VAT **subject to any undisclosed damage.**

PRE-INCIDENT CONDITION

The vehicle is considered to be in good condition for its age and type.

PRE-INCIDENT VALUE

According to the information available to us the vehicle was first registered in 06/03/2017. The corresponding Cazana Guide (model code: 27799) adjusted retail value for vehicles of this type and age in the April 2026 guide is £10,107.00 at 75319 Miles, trade value is £8,490.00 and mid value is £9,298.50. We place the pre-accident value of this particular vehicle at £10,107.00 bearing in mind the condition described herein.

OWNER'S CONTRIBUTION

We do not consider that any betterment contribution is required on this occasion.

RESERVE

We consider that a repair reserve of £3,625.00 would be reasonable on this occasion.

INSTRUCTIONS ISSUED

We are pleased to confirm that we have authorised the repairers to proceed with the work, on the 29th April 2026, on your behalf.

REPAIR DURATION

We consider that this repair will take some 3 to 4 working days to complete. This would be subject to the availability of parts and any other unforeseeable delays.

ROADWORTHY STATE

In our opinion this vehicle has suffered no damage in the incident under review which would render it unroadworthy. **The vehicle is considered currently roadworthy provided it complies with the current Road Traffic Act in terms of Road Tax, MOT standards (if vehicle age/type applies) and Motor Insurance.**

In preparing this report I confirm that I understand my overriding duty to the court and confirm I have complied with that duty. I confirm that I have made clear which facts and matters referred to in this report are within my own knowledge and which are not. Those that are within my own knowledge I confirm to be true. The opinions I have expressed represent my true and complete professional opinions on the matters to which they refer.

This report relates to damage sustained by the above vehicle in an RTC. Connexus Hire Solutions commissioned this report in writing on behalf of the client.

We hope that the foregoing is of assistance and please do not hesitate to contact us should you require anything further in this matter.

For & on behalf of



Our Ref: 00034970
Claim No: EHR100515

Continued

Page 3

Jeff Parr CAE AMIMI
Exclusive Vehicle Assessors