

Glass`s Information Services

Calculation

Client:	
Make / Model / Type:	BMW / 5 Series 4 door Saloon Model 2016.75 / 520 2.0TD (188bhp) xDrive (Plus Pack) Auto 202 [11.2019]
Glass`s national Code	299656001
Vehicle Registration Number:	YL69YFO
VIN:	WBA12DW040WW73171
Date:	12.8.2025
Paint system:	AZT
Hail damage logic:	ETG
Labour time unit:	1 Hour
Currency:	£
Database version:	2025.08.

Body	Repair type	Labour time	Overlap-time	Labour costs	Material costs
5111157 6317260 5113002	Front Bumper Lining Front LED Fog Lamps (Both) Front Grille, Side (Both) Selected criteria: Exterior Equipment M Annotation (time): Time includes adjustment	RP 2.10		168.00	810.67
NN	Front Bumper Side Support (R) Annotation (time): Autovista time net	RP 0.00	0.10		15.10
NN	Front Bumper Side Rear Bracket (R) Annotation (time): Autovista time net	RP 0.00	0.10		7.06
NN	Front Bumper Repair kit	RP 0.00			0.00
NN	Front Bumper Distance-Sensor Glue Kit	RP 0.00			21.50
NN	Front Bumper Lining Clip	RP 0.00			0.47
NN	Front Bumper Lining Screw	RP 0.00			0.67
NN	Front Bumper Lining Nut	RP 0.00			0.49
6312144	LED Headlamp (with indicator) (R) Annotation (time): Time includes adjustment	RP 0.70	1.10	56.00	1,502.07
NN	Front Fog Lamp Bracket (R) Selected criteria: Exterior Equipment M	RP 0.20	1.10	16.00	56.33

	Annotation (time): Autovista opinion time					
4135055	Front Wing (R)	RP	1.40	0.50	112.00	375.83
4135600	Front Wing Lower Bracket (Front) (R)	RP	0.10		8.00	22.47
	Annotation (time): Net times					
NN	Front Wing Repair Kit (R)	RP	0.00			0.00
5114000	Front Wing Emblem (Letters) (R)	RP	0.00	0.20		46.14
	Selected criteria: Exterior Equipment M					
NN	Front Wing Foam (R)	RP	0.00			28.02
NN	Front Wing Panel Screw (R)	RP	0.00			1.23
NN	Front Wing Panel Nut (R)	RP	0.00			0.73
5114000	Bonnet Emblem	RP	0.00	0.20		40.12
Labour costs					360.00	
Material costs						2,928.90
Total Body						£ 3,288.90

Auxiliary work		Repair type	Labour time	Overlap-time	Labour costs	Material costs
5118200EET	Front Wing Strip & Set-Up for Paint (L)	UI	0.30	0.10	24.00	0.00
5113045	Front Wing Cover (L)					
5113045	Front Wing Grille (L)					
	Annotation (time): Autovista opinion time					
5118360	Bonnet Strip & Set-Up for Paint	UI	0.10	0.10	8.00	0.00
5114000	Bonnet Emblem					
5118250	Front Door Strip & Set-Up for Paint (R)	UI	0.40	0.20	32.00	0.00
5121300	Front Door Window Outer Channel Strip (R)					
5121170	Front Door Outer Handle (R)					
5116001	Front Door Ext Mirror (Elect/Htd) (R)					
NN	ADAS methods Research Fee	EC	0.00			38.00 F
NN	Alloy Wheel Refurbish	EC	0.00			106.00 F
NN	Assessment Damage Appraisal Charge	EC	0.00			70.00 F
NN	Electric / hybrid risk assessment	EC	0.50		40.00	0.00 F
NN	Electric / hybrid shutdown and power up	EC	3.00		240.00	0.00 F
NN	Energy cost supplement	EC	0.00			25.00 F
NN	Environmental Charge	EC	0.00			30.00 F
NN	Identify the presence of ADAS	EC	0.50		40.00	0.00 F
NN	Load / Unload vehicle to ramp	EC	0.40		32.00	0.00 F
NN	OSF tyre	EC	0.00			175.00 F

NN	Pre repair cleaning charge (including sa	EC	0.70	56.00	0.00 F
NN	QC & Road Test	EC	1.00	80.00	0.00 F
NN	Repair method research charge	EC	0.00		100.00 F
NN	Sundries	EC	0.00		102.51 F
NN	System Diagnostic Check (Post Repair)	EC	0.00		80.00 F
NN	System Diagnostic Check (Pre Repair)	EC	0.00		80.00 F
NN	Vehicle Care Kit	EC	0.00		10.00 F
NN	Wash/Clean	EC	1.00	80.00	0.00 F
NN	Wheel Alignment (4 wheel)	EC	0.00		108.00 F
Labour costs				632.00	
Material costs					924.51
Total Auxiliary work				£ 1,556.51	

Paint	Paint type	Paint level	Labour time	Labour costs	Material costs
Front Bumper k	200	K1R	1.20	96.00	389.40
Front Wing, Complete (L)	200	B	0.60	48.00	86.20
Annotation (price) Part made from aluminium					
Front Wing, Complete (R)	200	I	1.10	88.00	184.10
Annotation (price) Part made from aluminium					
Bonnet	200	B	1.50	120.00	410.60
Annotation (price) Part made from aluminium					
A-Post, Upper (R)	200	B	0.40	32.00	18.30
Front Door, Complete K (R)	200	B	0.80	64.00	161.30
Annotation (price) Part made from aluminium					
Roof Moulding (R)	200	B	0.40	32.00	22.90
Prep. metal (on vehicle without pre-painting)	200		1.70	136.00	114.68
Prep. synthetics (combined-operation work)	200		0.50	40.00	44.68
Colour mixing (1)			0.30	24.00	0.00
Sample colour creation (1)			0.30	24.00	11.06
Labour costs				704.00	
Material costs					1,443.22
Total Paint				£ 2,147.22	

Summary	Labour rate	Labour time	Labour costs	Material costs
Body	80.00	4.50	360.00	2,928.90
Auxiliary work	80.00	7.90	632.00	924.51
Paint	80.00	8.80	704.00	1,443.22
Total Labour		21.20	1,696.00	
Total Material				5,296.63
Repair costs excl. VAT				6,992.63

VAT (20.00 %)

1,398.53

Repair costs incl. VAT

£ 8,391.16

Part name	Part no.	Previous part no.	Material costs
Front Bumper Lining	51118069072		810.67
Front Bumper Side Support	51117385348		15.10
Front Bumper Side Rear Bracket	51117385350		7.06
Front Bumper Repair kit	KET		0.00
Front Bumper Distance-Sensor Glue Kit	83195B683D3		21.50
Front Bumper Lining Clip	51471911992		0.47
Front Bumper Lining Screw	07149213164		0.67
Front Bumper Lining Nut	07147311312		0.49
LED Headlamp (with indicator)	63117214954		1,502.07
Front Fog Lamp Bracket	51118064968		56.33
Front Wing	41007443688		375.83
Front Wing Lower Bracket (Front)	41007440424		22.47
Front Wing Repair Kit	KET		0.00
Front Wing Emblem (Letters)	51148070804		46.14
Front Wing Foam	51486996304		28.02
Front Wing Panel Screw	07147147513		1.23
Front Wing Panel Nut	07147133884		0.73
Bonnet Emblem	51147463684		40.12
Total Parts			£ 2,928.90

Attention: Listed part numbers are for information only and CANNOT be used for ordering purposes.

Part name	Position no.
Front Bumper Lining	5111157+6620610
Front Bumper Side Support	
Front Bumper Side Rear Bracket	
Front Bumper Repair kit	
Front Bumper Distance-Sensor Glue Kit	
Front Bumper Lining Clip	
Front Bumper Lining Screw	
Front Bumper Lining Nut	
LED Headlamp (with indicator)	6312144+6620610
Front Fog Lamp Bracket	
Front Wing	4135055
Front Wing Lower Bracket (Front)	4135600
Front Wing Repair Kit	

Front Wing Emblem (Letters)	5114000
Front Wing Foam	
Front Wing Panel Screw	
Front Wing Panel Nut	
Bonnet Emblem	5114000
Front Wing Strip & Set-Up for Paint	5118200EET
Bonnet Strip & Set-Up for Paint	5118360
Front Door Strip & Set-Up for Paint	5118250
ADAS methods Research Fee	
Alloy Wheel Refurbish	
Assessment Damage	
Appraisal Charge	
Electric / hybrid risk assessment	
Electric / hybrid shutdown and power up	
Energy cost supplement	
Environmental Charge	
Identify the presence of ADAS	
Load / Unload vehicle to ramp	
OSF tyre	
Pre repair cleaning charge (including sa	
QC & Road Test	
Repair method research charge	
Sundries	
System Diagnostic Check (Post Repair)	
System Diagnostic Check (Pre Repair)	
Vehicle Care Kit	
Wash/Clean	
Wheel Alignment (4 wheel)	

Abbreviations

Description

F	User defined operations
R	RIGHT
L	LEFT
RP	Replace
UI	Uninstall and install
EC	Surcharge
NN	No part number

Paint type

Paint level, Procedure, Method

K1R	Part priming/part raw
200	2 Coat
B	Adjacent Panel Blend

I

New part

Selected criteria

Automatic Parking System
Exterior Equipment M

Additional Fields

Paint material index	100.000 %
Part index	100.000 %

Glass`s does not take responsibility for accuracy and completeness of data originating from vehicle manufacturers.