12. Time / Date of boiler light up and sync

: Light Up: 11:52 Hrs on 06/03/2018 Sync'd: 17:50 Hrs on 06/03/2018.

13. Delay for light up

: Other pending works were attended.

14. Recommendation / Action plan

Time line Responsibility Recommendations/Action plan SI.No.

Sl.No.	Recommendations/Action plan	Responsibility	
1)	After WB operation ensure complete closing of all poppet valves. Physically ensure @ local that steam passing noise dies out after closure of valves.	Operation	Immediate
2)	Periodically check ASLD for its healthiness.	Operation/C&I	Immediate
3)	Periodically conduct make-up tests for checking increase in system losses. Make up flow variations to be closely monitored.	Operation	Immediate
4)	Periodically carry out local visits around boiler furnace area for any abnormalities.	Operation/BM	Immediate

15. Any specific learning / feedback

: WB steam leak leads to tube erosion and has a cascading effect leading to further tube failures. Monitor make-up flow for early detection of leaks. Maintain ASLD healthiness for an early alarm. Frequent local visits around furnace is emphasized.

16. Signatures / Date

CM / OS

DGM / C&I

the BTL Committee (Cm (Bmi), \$96m(ch)
report
GM/08M

July

Tol3/14

Committee

Dam (Bmi)

Shoot

B lhe

Tol3/14

Committee

Copy submitted to CEO / NTPL