DI7OU-04

CIRCUIT INSPECTION

1. Black screen (Nothing displayed)

INSPECTION PROCEDURE

1 Check the ECU-IG fuse.

NG

Replace the fuse.

OK

2 Check multi display.

PREPARATION:

Disconnect the multi display connector.

CHECK:

Check voltage terminals +B.

<u>OK:</u>

+B: 10 - 14 V

CHECK:

Check voltage terminal ACC when turn ignition switch ACC or ON position.

OK:

ACC: 10 - 14 V

CHECK:

Check continuity terminal GND1.

<u>OK:</u>

GND1: Continuity

NG

Replace or repair wire harness or connector.

OK

Replace the multi display.