DI1AM-21

DIAGNOSTIC TROUBLE CODE CHART

DTC No. (See page)	Detection Item	Trouble Area
B2795 (DI-593)	Unmatched key code	Key Unregistered key inserted before
B2796 (DI-594)	No communication in immobiliser system	Key Transponder key coil Amplifier Wirehaness Engine and ECT ECU
B2797 (DI-596)	Communication malfunction No.1	Communication contents Unregistered key inserted before
B2798 (DI-598)	Communication malfunction No.2	Key Transponder key coil Amplifier Wire haness Engine and ECT ECU

HINT:

To reduce the unnecessary exchange of engine and ECT ECU, check that a trouble occurs with the original engine and ECT ECU at the time of exchanging engine and ECT ECU and the trouble will disappear with a new engine and ECT ECU.