

Service Hub - 2018 Alfa Romeo Stelvio 2.0T

VIN ZASFAKPN5J7B88115 | about 142,290 km | Q4 AWD, ZF 8HP | cuore, 2026-10-07

Section	Key specs (confidence)	Last known service	Open items	cuore page
Engine oil & service	0W-30 full synthetic, FCA MS-13340 (CORROB.). 5.5 qt / 5.2 L with filter (SINGLE). Filter Mopar 4892339 (not 68191349 = V6). Drain plug 20 Nm, filter cap 25 Nm (SINGLE). Shop interval 8,000 mi / 12 mo (CORROB.); FCA max 10,000 mi / 1 yr, severe duty 4,000 mi (CONFIRM.).	Oil change reset logged in MES 2026-09-15 (no odometer). Turbo replaced 2025-10-14 (overboost counter reset).	Record the oil change details in cuore (brand, filter, torques applied, condition).	/v/<VIN>/oil-change
Routine maintenance	Owner's manual (CONFIRM.): air filter and spark plugs due every 30k mi; car is near 88,400 mi (142,290 km), approaching the 90k mi mark for both. Spark plug NGK 90219 / Mopar 68292346AA (CORROB.), 19.5 Nm. Cabin filter 20k mi / 2 yr. Coolant OAT MS.90032, 8.8 L engine circuit + separate intercooler circuit, 150k mi / 15 yr. Brake fluid DOT 4 MS.90039 every 2 yr (CONFIRM.). Drive belt 36k mi / 4 yr (18k mi / 2 yr severe duty). A/C R-1234yf, annual. PCV, throttle body, boost hoses: UNKNOWN.	Oil-change reset only (MES 2026-09-15). No maintenance items recorded yet.	Record a baseline visit (what is known, with odometer) so due dates can be calculated, unless records show these were already done. Air filter, spark plugs and drive belt are likely due soon.	/v/<VIN>/maintenance
Brakes, wheels & tyres	Front rotor 330 x 28 mm new, 25.5 mm min (SINGLE); rear min UNKNOWN (read cast MIN TH). DOT 4, MS.90039, change every 2 yr (CONFIRM.). 235/60R18 or 235/55R19 (CORROB.). Lugs 121 Nm / 89 lb-ft (CORROB.). Pressures: read the door placard.	No brake/tyre record yet.	Rear pads: put the electric park brake in service mode first (MES or wiTECH).	/v/<VIN>/brakes-tires
Transmission (ZF 8HP)	ZF LifeguardFluid 8 / Mopar 68218925AA, NOT ATF+4. Level check only at 30-50 C (CONFIRM.). Pan/filter bolts 10 Nm (CONFIRM.). Drain/fill plug torques UNKNOWN. Relearn adaptations after service.	No transmission service on record.	TSB 21-035-20 TCM flash applies to this VIN: check on wiTECH.	/v/<VIN>/drivetrain/transmission
Transfer case (Q4)	Tutela, FIAT 9.55550-DA11 (CORROB.). Capacity ~0.7 L, sources conflict. Plug torques UNKNOWN. Replace oil at 80k mi / 128k km / 8 yr (CONFIRM., owner's manual).	No record.	DUE: car is past 128,000 km. Replace transfer case oil unless records show it was done.	/v/<VIN>/drivetrain/transfer_case
Differentials	Front 75W-80 GL-5 DA10, 0.5 L; rear 75W-85 DA9, 0.9-1.1 L by unit (SINGLE). Rear plugs 26 Nm (SINGLE); front plugs UNKNOWN. Which rear unit (open/LSD/eLSD) this VIN has: UNKNOWN.	No record.	-	/v/<VIN>/drivetrain/differentials
Driveline	Hub nut 52 lb-ft + 47 deg, SINGLE-USE (SINGLE). Hub mount bolts 74 lb-ft (SINGLE). Propshaft flange UNKNOWN (online 72-101 lb-ft figure is from a 1970s Alfa: do not use).	No record.	-	/v/<VIN>/drivetrain/driveline
Mounts	Engine mount bolts 22-27 Nm; dogbone 25-31 Nm, single-use (SINGLE). Strut-to-lower-arm and upper-arm torques UNKNOWN (fabricated values withdrawn in fact-check).	No record.	-	/v/<VIN>/drivetrain/mounts
EVAP & emissions	P0455, P0456, P0440 chronic since 2025-09. System sealed (3 smoke tests); canister, ESIM, cap, filter, purge valve all new. ECM software 52170619 / P235QB39. P0455 / P0440 freeze frames: fuel 94% / 92% (EVAP monitor needs 15-85%).	P0440 recurred in the 2026-09-28 and 09-29 scans after earlier clears; cleared again 2026-09-29 10:46 (SCAN_2609291046). The 2026-10-04 clean session/scan came after that clear, before any monitor could re-run: repair is UNVERIFIED, not confirmed.	wiTECH flash check (TSB 18-030-17), then Test A (ESIM switch). Check recalls 25V586000 (fuel pump) and 18V636000 (ECM software). Do not clear codes again; verify with a readiness read after drives with fuel 15-85%.	/tree, /dashboard
Network / body / ADAS	Network: U0100 (ECM comms), U1713 (BCM), B1040 (RFHUB), C141B (DASM camera) -- chronic since 2026-06/08-27. Separate: B1176 (rear left window riser, BCM), chronic since 2026-08-27.	Network codes present in the 2026-09-28 scan, gone by 2026-09-29: one power/bus event, not per-module faults. B1176 persisted through 2026-09-29 -- a separate, unresolved body fault.	Confirm network codes stay clear next scan. B1176: grey-cable read of ABS/HALF, then the window-riser fault tree (separate from the network-cascade steps).	/v/<VIN>/tree

Confidence: CONFIRM. = manufacturer document; CORROB. = two independent sources; SINGLE = one source; UNKNOWN = use the FCA service manual (TechAuthority). Torque data fact-checked 2026-09-26. Full torque tables: 'Stelvio Torque Settings' and 'Stelvio Drivetrain Torque Settings' PDFs, and the cuore torque page.