

Recalls and Campaigns

2018 Alfa Romeo Stelvio 2.0T (GU) | VIN ZASFAKPN5J7B88115

Read this first

- This list is every NHTSA recall for the **2018 Stelvio model year** (11 recalls), with each one's scope judged for a 2.0T that is not a Quadrifoglio. Whether each recall includes **this VIN**, and whether it has already been done, is not public data.
- **Check open status by VIN** at nhtsa.gov/recalls or alfaromeousa.com (owners, recalls), or in wiTECH/DealerCONNECT VIP. Recall work is free at any Alfa Romeo dealer. FCA US customer service: 1-800-853-1403.
- Two items matter for the EVAP fault now: **25V586000** (fuel pump) and **18V636000** (ECM software). Book them together with the ECM flash check.

NHTSA recalls, 2018 Stelvio

Campaign	Year / component	Issue (NHTSA summary, shortened)	Remedy	Applies to this car?	Priority / relevance
25V586000	2025 Fuel System, Gasoline:Delivery:Fuel Pump	Chrysler (FCA US, LLC) is recalling certain 2017-2019 Alfa Romeo Giulia and 2018-2019 Alfa Romeo Stelvio vehicles. The fuel pump may fail, which can result in a loss of fuel flow and loss of drive power.	Dealers will replace the fuel delivery module, free of charge. Interim notification letters, notifying owners of the safety risk, were mailed October 7, 2025. Additional ...	Yes: 2018-2019 Stelvio	HIGH - loss of drive power risk; also replaces the fuel delivery module, where the EVAP internal vapour line connects (TSB 9100471)
18V636000	2018 Electrical System:Wiring	Chrysler (FCA US LLC) is recalling certain 2017-2018 Alfa Romeo Giulia and 2018 Alfa Romeo Stelvio vehicles, equipped with 2.0L engines. These engines may misfire causing the catalytic converter to overheat, possibly resulting in damage to the nearby wiring a...	Chrysler will notify owners, and dealers will inspect the vehicles for diagnostic codes, and update the engine control module software, free of charge. The recall began ...	Yes: 2018 Stelvio with 2.0L	HIGH for this diagnosis - remedy is an ECM software update; do with the ECM flash check
19V551000	2019 Electrical System: Instrument Cluster/Panel	Alfa Romeo (FCA US LLC) is recalling certain 2018-2019 Giulia and Stelvio vehicles. The Body Control Module (BCM) may indicate an inaccurate fuel level that displays higher than the actual amount.	Alfa Romeo will notify owners, and dealers will update the BCM software, free of charge. The recall began August 12, 2019. Owners may contact Alfa Romeo customer servic...	Yes: 2018-2019 Stelvio	Relevant to EVAP: BCM fuel-level reading; EVAP tests depend on fuel level

Campaign	Year / component	Issue (NHTSA summary, shortened)	Remedy	Applies to this car?	Priority / relevance
18V205000	2018 Equipment:Electrical	Chrysler (FCA US LLC) is recalling certain 2018 Alfa Romeo Stelvio vehicles. Water may leak into the body control module and its connectors, causing corrosion. This corrosion can cause illumination of one or more malfunction indicator lamps, a loss of windsh...	Chrysler will notify owners, and dealers will install additional sealing protection to prevent water from entering the body control module and its connectors. The recall...	Yes: 2018 Stelvio	Relevant to network codes: water into BCM connectors
18V203000	2018 Structure:Body :Hatchback/Lift gate	Chrysler (FCA US LLC) is recalling certain 2018 Alfa Romeo Stelvio vehicles. Water may Leak into the wiring connectors for the rear liftgate and the liftgate-opening switch, causing corrosion.	Chrysler will notify owners, and dealers will install additional protection against water leaking into the liftgate wiring connectors and switch, free of charge. The rec...	Yes: 2018 Stelvio	Liftgate connector water protection
24V510000	2024 Air Bags:Frontal	Chrysler (FCA US, LLC) is recalling certain 2017-2024 Alfa Romeo Giulia, 2018-2025 Alfa Romeo Stelvio, 2019-2023 Fiat 500X, Jeep Renegade, and 2024 Fiat 500E vehicles. A seat belt buckle switch sensor may be improperly connected, preventing the front seat air...	Dealers will repair the connection, free of charge. Owner notification letters were mailed beginning August 27, 2024. Owners may contact FCA US, LLC customer service at...	Yes: 2018-2025 Stelvio	Seat belt buckle sensor connection (airbag)
19V148000	2019 Forward Collision Avoidance: Adaptive Cruise Control	FCA US LLC (Alfa Romeo) is recalling certain 2018-2019 Alfa Romeo Stelvio and 2017-2019 Giulia vehicles. The Brake System Module (BSM) software may prevent the driver from disabling the Adaptive Cruise Control (ACC) after the traction control system detects a...	Alfa Romeo has notified owners, and dealers will update the BSM software, free of charge. The recall began March 25, 2019. Owners may contact Alfa Romeo customer servic...	If fitted with adaptive cruise	BSM software, ACC disable
18V147000	2018 Visibility:Windshield Wiper/Washer:Motor	Chrysler (FCA US LLC) is recalling certain 2018 Alfa Romeo Stelvio vehicles. The software for the wiper motor may incorrectly interpret the wiper motor as overheating, limiting the windshield wipers to operating only at the low-speed setting. As such, these v...	Chrysler will notify owners, and dealers will replace the wiper motor, free of charge. The recall began on April 25, 2018. Owners may contact Chrysler customer service ...	Yes: 2018 Stelvio (certain)	Wiper motor replacement
17V823000	2017 Service Brakes, Hydraulic	Chrysler (FCA US LLC) is recalling certain 2018 Alfa Romeo Giulia and Stelvio vehicles. The braking system on these vehicles may have been filled with contaminated brake fluid, possibly damaging the system and affecting its performance.	Alfa Romeo will notify owners, and dealers will inspect the braking system, replacing it as necessary, free of charge. The recall began February 1, 2018. Owners may con...	Only early-build 2018 cars	Brake fluid contamination inspection

Campaign	Year / component	Issue (NHTSA summary, shortened)	Remedy	Applies to this car?	Priority / relevance
23V382000	2023 Service Brakes, Hydraulic	Chrysler (FCA US, LLC) is recalling certain 2017-2020 Alfa Romeo Giulia and 2018-2020 Alfa Romeo Stelvio vehicles equipped with carbon ceramic matrix brakes. During certain driving maneuvers, the brake system may exert an excessive clamp force that may fractu...	Dealers will update the brake system module (BSM) software, free of charge. Owner notification letters were mailed July 20, 2023. Owners may contact FCA US, LLC custome...	Only with carbon ceramic brakes	Almost certainly not this car
18V635000	2018 Engine And Engine Cooling :Cooling System:Hoses/Lines /Piping/Fittings	Chrysler (FCA US LLC) is recalling certain 2018-2019 Alfa Romeo Stelvio Quadrifoglio vehicles. The engine cooling hose may have inadequate webbing material allowing a coolant leak.	Chrysler will notify owners, and dealers will replace the coolant hose, free of charge. The recall began October 10, 2018. Owners may contact Chrysler customer service ...	No: Quadrifoglio only	Not applicable to the 2.0T

Service campaigns and bulletins (not recalls)

Item	What it is	Applies	Relevance
CSN W05 (Mar 2020)	Customer Satisfaction Notification: reprogram PCM, PROXI Alignment, Phonic Wheel Replacement. PCM software may not allow enough turbo oil-feed cooling time.	2018-2019 Stelvio 2.0L GME-T4 (EC2)	An ECM reflash; may already be done. Check in wiTECH.
TSB 18-026-20 (Mar 2020)	Flash: PCM updates. Fix list includes P1CEA (boost-side EVAP purge) and P24D6 (EVAP pressure switch circuit).	2018 Stelvio 2.0L EC2, North America	EVAP-related ECM calibration
TSB 18-030-17 REV. B and the 18-0xx flash family	PCM flash family whose fixed-DTC lists include P0440 / P0441 / P0455 / P0456.	Giulia / Stelvio	Why the ECM flash check is on the EVAP fault tree (step E8)
TSB 18-048-23	wiTECH Small Leak Verification Test (SLVT); a road test cannot confirm a small-leak repair.	All FCA gasoline	Verifies an EVAP fix

Suggested dealer visit

- Ask for a VIN recall check and complete every open item.
- Priority: **25V586000** fuel delivery module and **18V636000** ECM software.
- While it is connected: ECM Flash tab, compare Current vs New ECU Part Number (see the 'Stelvio ECM Flash Procedure (wiTECH)' PDF), and confirm CSN W05 status.
- After a fuel delivery module replacement, have the technician confirm the internal vapour line is connected at the FDM port (TSB 9100471).

Source: NHTSA recalls API, [api.nhtsa.gov/recalls/recallsByVehicle?make=ALFA ROMEO&model;=STELVIO&modelYear;=2018](https://api.nhtsa.gov/recalls/recallsByVehicle?make=ALFA%20ROMEO&model;=STELVIO&modelYear;=2018), retrieved 2026-09-26. CSN W05 and TSB 18-026-20 from static.nhtsa.gov. Applicability column is judged from each recall's stated scope; VIN inclusion must be confirmed by VIN lookup.