

# wiTECH ECM Flash Check

2018 Stelvio 2.0T | VIN ZASFAKPN5J7B88115 | Installed: ECU software **52170619**, supplier software **P235QB39** ver 0000, HW MM10JAHW232

- **Charger on:** hold **13.2-13.5 V** (stand-alone voltmeter); timer to continuous. Too high: switch on lights or blower.
- **Only wiTECH on the OBD port** (MES and cuore disconnected). Laptop on mains, sleep off, stable internet.
- **Never interrupt a flash.** If it aborts, restart it.

## Check

- Connect the wiTECH interface; ignition **RUN**, engine off.
- Sign in to wiTECH 2; select the vehicle; confirm the VIN.
- **Topology > ECM > Flash** tab.
- Compare **Current ECU Part Number** with **New ECU Part Number** and write both below.

| If the numbers are... | Then                                                                                                            |
|-----------------------|-----------------------------------------------------------------------------------------------------------------|
| <b>The same</b>       | ECM is on the latest calibration. <b>Do not flash.</b> Software lead closed: go to wiTECH Test A (ESIM switch). |
| <b>Different</b>      | A newer calibration exists: continue below.                                                                     |

## Flash (only if different)

- Tick the flash agreement, select **Flash ECU**, follow the screen (about 8 minutes). Watch the volts.
- **BCM > Misc. Functions > PROXI Alignment.**
- **View DTCs;** Topology > Action Items > **All DTCs > Clear All DTCs.**
- **ECM > Misc. Functions > Phonic Wheel Replacement;** follow prompts. (If skipped or done wrong, **P1300** stays active.)
- Clear All DTCs again. Re-open ECM Flash tab: Current now equals New.
- **BCM Flash tab:** compare and update the BCM too if different (TSB 18-026-20).
- Ignition OFF, disconnect, charger off.

## Record

| Item                                     | Result |
|------------------------------------------|--------|
| Date / odometer                          |        |
| ECM Current ECU Part Number              |        |
| ECM New ECU Part Number                  |        |
| Flashed? / part number after             |        |
| PROXI + Phonic Wheel done / BCM current? |        |

After a flash: drive several days (fuel 15-85 %, cold starts), then cuore **verify\_repair** for P0455/P0456/P0440; 'passed since clear' on all three confirms it. The check-engine light cannot confirm it on this car. Enter the result on cuore's dealer-results page.