

wiTECH Test A: ESIM Switch

Does the engine computer see the ESIM switch close under vacuum? | 2018 Alfa Romeo Stelvio 2.0T | VIN ZASFAKPN5J7B88115

What this decides. The EVAP system is sealed (three clean smoke tests) and every EVAP part is new, yet the codes keep setting: P0440 came back within a day of the 2026-09-28 and 09-29 clears. The ECU calls a fault when it does not see the ESIM switch close. A hand pump closes the switch while you watch the ECU's own reading, testing switch, connector, wiring and ECU input at once, without unplugging anything.

Note. wiTECH tab and parameter names are as commonly shown in wiTECH 2 and may differ by release; the exact switch parameter name for this ECU is not known, so search for it (step 6). Apply vacuum gently; never use shop air.

You need: wiTECH 2 account, laptop and interface; hand vacuum pump with a short hose that fits the ESIM's canister-side port; flat trim tool and torch for the wheel liner; optionally a phone to video the wiTECH screen.

Steps

1	Prepare	Parked, engine off and cool, park brake on. MultiEcuScan and cuore disconnected: only wiTECH on the OBD port. Battery maintainer if the session is long.
2	Reach the ESIM	Open the driver-side rear wheel liner; the ESIM sits on the vent side of the EVAP canister. Leave it plugged in . Identify its canister-side hose and its fresh-air side.
3	Connect wiTECH	Interface on the OBD port. Ignition RUN , engine off .
4	Select the car	Sign in to wiTECH 2, select the vehicle, confirm VIN ZASFAKPN5J7B88115.
5	Open the ECM	From Topology , select the ECM .
6	Find the switch	In the ECM's live data, search for the ESIM switch or EVAP pressure / leak-detection switch (words: ESIM, EVAP, leak, pressure switch, NVLD). Add it and fuel level . None listed: note it, and use the meter test (Test B, ESIM Wiring Test sheet).
7	Baseline	Nothing on the ESIM hose: record the switch state (expected open / not sealed).
8	Apply vacuum	Remove the ESIM's canister-side hose, fit the hand pump to that port (fresh-air side open). Pump slowly and note when wiTECH shows closed . Hold about 30 s: it should stay closed. Release: it should return to open . Do it three times; note any delay.
9	Wiggle test	Hold it closed with vacuum and gently flex the ESIM connector and harness along the wheel well. Any flicker to open is an intermittent connection.
10	Finish	Release vacuum, refit the hose firmly and the wheel liner, ignition OFF, disconnect wiTECH. Do not clear codes .

Reading the result

What wiTECH shows	Meaning	Next step
Closes with vacuum, opens on release, every time, no flicker	The whole signal path works: switch, connector, wiring, ECU input.	Fault is ECU calibration or test logic. Do the Flash check; if already current, this plus three clean smoke tests is the dealer case.
Never changes	The ECU does not see the switch.	ESIM Wiring Test (Test B): connector, signal voltage, ground, resistance, jumper.
Changes, but flickers when wiggled	Intermittent connection at connector or harness.	Repair the connector or wiring; wiring tests B1 and B5 find the spot.
Changes only after a long delay or at hard vacuum	Sluggish switch.	Bench-test the ESIM against a new unit (ESIM Bench Test sheet).

Record sheet

Item	Result	Item	Result
Date / odometer / fuel level		Run 2	
wiTECH parameter name		Run 3	
Baseline (no vacuum)		Held closed 30 s?	
Run 1: closed? opened on release?		Wiggle: any flicker?	
Conclusion			

Enter the result in cuore (dealer results or the evidence gate). A clean pass clears the ESIM wiring; a failure localises the fault.