SERVICE BULLETIN

NUMBER: 08-029-20

GROUP: 08 - Electrical

DATE: March 5, 2020

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This bulletin supersedes Service Bulletin 08-012-19, dated February 15, 2019, which should be removed from your files. All revisions are highlighted with **asterisks and include new Entertainment Telematics Module (ETM) software, additional symptoms, repair steps and LOPs.**

SUBJECT:
RAN RAP RAJ RAG and RSD Radio Software Enhancements

OVERVIEW:
This bulletin involves inspecting and if required, updating the radio to software level **MV-002.010.041.**

NOTE: The customer should be informed that after the reprogram, the radio will need to have the phones paired to the Entertainment Telematics Module (ETM). The operative details for pairing telephones and settings are shown in the Owner Handbook of the infotainment module.

MODELS:

2018	(GU)	Alfa Romeo Stelvio

NOTE: This bulletin applies to vehicles within the following markets/countries: North America.

NOTE: This bulletin applies to vehicles built on or before January 11, 2018 (MDH 0111XX) equipped with one of the following radios:

- **AM/FM/HD Bluetooth W/Nav 8.8 Radio (Sales Code RAN).**
- **AM/FM/HD W/Bluetooth 8.8 Radio (Sales Code RAP).**
- **W/WO Sirius XM Satellite Radio (Sales Code RSD).**
- **AM/FM With Bluetooth 6.5 Radio (Sales Code RAG).**
- **AM/FM Bluetooth W/NAV 6.5 Radio (Sales Code RAJ).**

SYMPTOM/CONDITION:
Some customers may experience one or more of the following:

- **Voice commands not recognized, especially in SiriusXM®.
- Can’t select certain character in navigation, character grayed out.**
- Radio may reboot while driving.
- Tweeter noise during audio streaming.
- Ipod Nano® not recognized.
- Voice recognition does not work when setting an address in Spanish.

In addition, the following improvements are included:

- **Stability improvements, to help prevent the radios from rebooting and freezing.
- Preset management improvements, for better usability.
- Additional phone compatibility improvements on phones not tested in the past.**

DIAGNOSIS:

Using a Scan Tool (wiTECH) with the appropriate Diagnostic Procedures available in DealerCONNECT/Service Library, verify all related systems are functioning as designed. If Diagnostic Trouble Codes (DTCs) or symptom conditions, other than the ones listed above are present, record the issues on the repair order and repair as necessary before proceeding further with this bulletin.

If the customer describes any of the symptom/condition listed above, perform the Inspection Procedure

INSPECTION PROCEDURE:

NOTE: **If the radio has been replaced with an updated 2.5 radio, this software will not work. Refer to all applicable published service bulletins for detailed repair procedures and labor times regarding updating the 2.5 radio software.**

1. Check the ETM software version.
2. Start the vehicle and turn on the radio.
3. Press the “MENU” button that is next to the Rotary Pad, to activate the main menu.
4. Turn and press the Rotary Pad to select and activate “SETTINGS” mode.
5. Turn and press the Rotary Pad to access the “SYSTEM” function.
6. Turn and press the Rotary Pad to access the “SOFTWARE UPDATE” function.
7. Turn and press the Rotary Pad to access the “CURRENT SOFTWARE” function.
8. What is the ETM software version?
    - MV-002.008.041, MV-002.009.043, MV-002.009.053, MV-002.009.055 or MV-002.009.059, update the ETM. Proceed to Step 1 of the repair procedure.
    - **MV-002.010.041 ETM has the latest available software. Normal diagnostic should be performed.
    - MV072.001.002 or higher, this bulletin’s 2.0 radio software will not work on a 2.5 radio. Refer to all applicable published service bulletins for detailed repair procedures and labor times regarding updating the 2.5 radio software.**

REPAIR PROCEDURE:

1. Has the a USB flash drives been created?
   - Yes>>> Proceed to Step 5 of the Repair Procedure.
   - No >>> Proceed to Step 2.

NOTE: If you cannot download the software, make sure you have proper security access. If not, have the Service Manager or Shop Foreman download the software update.

2. Go to DealerCONNECT> Service> UCONNECT Command Center> Uconnect> Dealer software downloads, to download the files.
3. If a security message appears “Do you want to view only the web page content that was delivered securely?” (Fig. 1) . Press ”No” to continue.

Fig. 1
Security Warning Pop-up

NOTE: The software acquisition requires the deletion of all the files on the USB flash drive before copying the contents of the folder necessary for the update. Copy only the files contained in the folder onto the flash drives, NOT the folder itself.

4. To download the software files to USB flash drives, follow the on-screen instructions and perform the following:
   - Acquire a blank USB flash drive with at least 4GB.
   - A blank USB flash drive will be needed for each software update (one for each software update). Additional updates can not be on the same USB flash drive.
   - Once the file is saved to the USB flash drive, it is recommended to label the USB flash drive with the bulletin number.
   - The USB flash drives must be formatted as New Technology File System (NTFS) structure.
   - Download the software update files to your local PC’s desktop.
5. Check that there is nothing inserted (USB flash drive or other devices) in the vehicle’s USB ports. If there is, they must be removed before starting the update procedure.

NOTE: Start the engine and leave it running in a secure location for the duration of the update.

6. Turn on the radio with a long press of the volume control knob if it does not turn on automatically.

NOTE: The technician should record and reprogram the radio presets and user settings that may be reset with the radio update.

7. Press the “MENU” button to activate the main menu.
8. Turn and press the Rotary Pad to select and activate “SETTINGS” mode.
9. Turn and press the Rotary Pad to access the “SYSTEM” function.

10. Turn and press the Rotary Pad to access the “SOFTWARE UPDATE” function.
11. Insert the USB flash drive with the ETM update software into either USB port.

NOTE: If an error message ″Insert a compatible USB device″ is displayed, make sure the correct software is being used. 2018 GU vehicles have two different software versions.

12. Turn and press the Rotary Pad to select OK, to start the update.

NOTE: Once started, the procedure does not require any intervention by the operator.

CAUTION! DO NOT remove the USB flash drive. DO NOT turn off the ignition, leave the engine running.

13. When the software update procedure has completed, remove the USB flash drive. The radio will reboot and restart.

NOTE: The customer should be informed that after the reprogram, the radio will need to have the phones paired to the Entertainment Telematics Module (ETM). The operative details for pairing telephones and settings are shown in the Owner Handbook of the infotainment module.

TIME ALLOWANCE:

Labor Operation No:	Description	Skill Category	Amount
**18-60-02-HE	Radio, Software - Create USB Jump Drive For ETM using Uconnect Website (One Time Only) (0 - Introduction)	6 - Electrical and Body Systems	0.2 Hrs.
18-60-02-HA	Check Software Level and Perform Software Update (ETM) (0 - Introduction)	6 - Electrical and Body Systems	0.5 Hrs.**

NOTE: The “One Time Only” LOPS are used one time per dealer when downloading the software onto a USB flash drive. The technician can only use the download LOP one time for each of the radios listed.

FAILURE CODE:

The dealer must use failure code CC with this Service Bulletin.

- If the customer’s concern matches the SYMPTOM/CONDITION identified in the Service Bulletin, failure code CC is to be used.
- When utilizing this failure code, the 3C’s (customer’s concern, cause and correction) must be provided for processing Service Bulletin flash/reprogramming conditions.

CC	Customer Concern