

Pending Items - 2018 Alfa Romeo Stelvio 2.0T

VIN ZASFAKPN5J7B88115 | about 142,290 km / 88,415 mi | as of 2026-10-01 | newest MES logs: all-systems scans 2026-09-28 and 2026-09-29 (none since)

Latest MES scans

Module	Code	28 Sep scan	29 Sep scan
Engine (ECM)	P0440 evaporation control valve	present, cleared	back after the clear
Body (BCM)	B1176 rear left window riser obstructed	present, cleared	back after the clear
Body (BCM)	U1713 engine message erratic	present, cleared	gone
Transfer case (DTCM)	U0100 no communication with engine module	present, cleared	gone
Key fob hub (RFHUB)	B1040 message from BCM implausible	present, cleared	gone
Driver assist radar (DASM)	C141B camera blocked	present, cleared	gone

Reading the scans: P0440 came back within a day of being cleared, so the engine module's EVAP self-test is still failing. The system passed three smoke tests and every EVAP part is new, so the suspects are the ESIM switch signal path or the engine-module software. B1176 is real but unrelated. The four network codes on 28 Sep were gone the next day: one power or bus event.

Pending items (priority 1 = do first)

Pri.	Item	What to do	Who
1	EVAP: check engine-module software	wiTECH Flash tab: compare P235QB39 with the latest calibration; recall 18V636000 is a 2.0L engine-software update.	You, wiTECH
1	EVAP: run Test A (ESIM switch)	Vacuum on the ESIM while watching its switch reading in wiTECH. Decides ESIM signal path versus engine software.	You, wiTECH
1	Stop clearing codes	Each clear resets the EVAP self-test. Let P0440 (and any P0455 / P0456) set and keep the evidence until Test A is done.	You
1	Recalls and bulletins	25V586000 (fuel pump), 18V636000 (2.0L engine software), TSB 21-035-20 (transmission software): check open status by VIN.	You, wiTECH / dealer
2	Transfer case oil	Due at 80,000 mi / 128,000 km / 8 yr (owner's manual). Car is past it: replace unless records show it was done.	Shop
2	Drive belt	Due every 36,000 mi / 4 yr. Overdue unless replaced.	Shop
2	Air filter and spark plugs	Next mark 90,000 mi: about 1,585 mi away. Plugs NGK 90219 / Mopar 68292346AA, 19.5 Nm.	Shop
2	Brake fluid	Every 2 years regardless of mileage (DOT 4, MS.90039). Overdue unless changed since 2024-09.	Shop
2	Rear left window (B1176)	Window riser reports obstructed, back after the clear. Separate from EVAP.	You / shop
3	Enter records in cuore	A baseline maintenance visit with odometer, and the 2026-09-15 oil change (brand, filter, odometer) so due dates can be tracked.	You, cuore
3	Label print check	Print the sample sheet and test grids; report offsets for the 6576 / 6578 plastic ID labels (margins not published).	You
3	Chassis bus read	Grey cable (A6) read of ABS, steering and other chassis modules; follow the network fault tree if codes appear.	You, cuore
3	Unsourced values	EVAP purge and vapour-pressure limits, peak boost: need the service manual (TechAuthority). Tyre pressures: read the door placard.	You

Priority 1: diagnosis and safety recalls. Priority 2: overdue or due-soon maintenance from the 2018 owner's manual schedule (no maintenance records exist in cuore yet, so these assume the work was not done). Priority 3: records and open checks.