

**17-1. Car Error Code**

P 129

CODE	DEFINITION
1695	Occurrence of forced stop due to wrong in a speed of a CAR at highest floor → Alteration to "1702"
1696	Occurrence of forced stop due to wrong in a speed of a CAR at lowest floor → Alteration to "1703".
1701	Detection of overspeed (Cancellation of TFR)
1854	LU/LD stuck Error (1110)
2005	Detection of break down of ARD system

P 130

CODE	DEFINITION
2006	It did not be implanted in 6 minutes after ARD driving.(permanent break down)
2007	Power of battery does not be turn off in 4 seconds after den of ARD driving. (Permanent break down)
2008	Occurrence of break down of CPI DRIVE (when SAF2 is 'true' and SAF3I is 'false'). If break down being caused by CPI, it is cut off safety line. → It is established to make a point of contact of SAF3 in a safety line open with hardware and to be managed in software. ※ It is applied to a model without a contact for SAF3 in drive like as CPI50R and CPI100R.
2009	An error of an examination about rationality of i/o in Car door Lock(CDL) error(delaying time: 2sec)
2010	An error of an examination about rationality of i/o in DZP contactor.(delaying time: 1.5sec, critical – Automatic operation after stop at near floor.)
2011	An error of an examination about rationality of i/o in CDXF/CDXR contactor.(delaying time: 1.5sec, non-critical)
2012	A break down of wrong in door-open detected by Hoistway Interlock. (delaying time: 2sec, critical – Permanent break down)
2013	If fault code is occurred in CPI, TAC50K records information taken through CAN communication. Message: "Drive fault via CAN"
2014	An occurrence of wrong in control of Door zone bypass, although it is made DZC be in active, DZECM sign is input continuously.
2015	An occurrence of wrong in DZC contactor (or relay), DZECM sign does not be input outside of Door zone. (RUN MONITOR)
2016	Detection of opening of rescue hole on upper part of a Car. (MLS1) - RUN MONITOR



2017	One of the HDFC1, HDFC2, HDRC1 and HDRC2 relay IO is not operated properly.
2019	AC power detection relay is not operated properly.
2020	Retire-cam device IO is not operated properly.
2021	DLT or DLB of Direction Limit Switch and Landing Switch (LVU or LVD) signals are active together. Must not active together DLT and LVU. Must not active together DLB and LVD.

Added 2017, 2019, 2020 and 2021 error code on Jan 14, 2010.