

Car Error Codes

Codes	DEFINITION
100	The input of position sensor seems to be escaped from the sequency during the hoistway setup.
110	Load Sensor Communication Error
1001	OS could not create the timer required for a client – Internal software error.
1002	OS could not create the memory required for a client - Internal software error.
1003	FScheduler overran a single OS tick a higher % of the time - Internal software error.
1004	Gate and Locks opened during a run – A Car or Hoistway interlock opened while the car was running. • Car doors clipping interlocks • Defective I/O • Defective gate switch contact • Defective wiring
1005	DOL detected while HW closed. • Defective DOL input • Defective H/W input
1006	Contact problem of hoistway interlock switch. • Defective I/O • Defective Hoistway door contact • Blocked Hoistway door
1007	Safety String opened during run. The safety string opened during a run causing an emergency stop. • Open device in safety string • Defective I/O
1008	Motor contact is already conductive (MCD/MCE). Before run initiation was issued, MCD was already disabled or MCE was already enabled. (Only in UP Run attempt). • Defective I/O • Software activation error • Defective Relays
1010	Motor Contact error (MCD Open). After run, MCD was not enabled or MCE was not disabled. • Defective MCD input • Defective MCE input • Defective MC contact • Defective Relays

CODE	DEFINITION
1011	Motor Contact failed power supply (MCD/MCE). After run, MCD was enabled or MCE was disabled. - Defective MCD input - Defective MCE input - Defective MC contact - Defective Relays.
1012	Serial I/O timeout error.
1013	NV Hardware failure. Software issued a command to modify Non Volatile memory that was not completed, or completed with invalid results. 186C Board fault
1014	NV Checksum error. Data in Non volatile memory was lost. 186C Board fault
1015	Software Error making invalid NV request- producing wrong NV request
1016	Software error - NV Full, cannot hold another client structure. No more room for data in Non Volatile memory.
1017	Software error – Change of Run Type during run. Car doesn't perform Emergency stop and the software has changed the run type (leveling, stop after run, normal speed run).
1018	Normal Limit Signal Error – Signals of both Top & Bottom limit switches (DLT/DLB) work simultaneously. - Defective wiring - Defective I/O
1019	Normal Limit Switches(DLB and DLT) don't correspond to the car position. - Defective wiring. - Defective I/O
1020	Software error – IO database has been corrupted. Checksum for I/O has changed.
1021	Inspection indicates an Invalid I/O condition. Status of I/O indicates combination of active and inactive inputs that are not allowed. - Wire error. - Defective I/O (INCN, INCT)
1022	Run Monitor- Anti-run timer exceeds the fixed value.

CODE	DEFINITION
1023	Run Monitor – Wrong direction run. For example, software issued the command to run in UP direction, but the car actually ran in DOWN direction. • Defective wiring • Defective I/O
1024	Not applicable to TKDE. Excessive number of re-levels – Fault issued if elevator re-levels more than 25 times in a 5 minute interval.
1025	Not applicable to TKDE. BP parity error.
1026	Door Zone Sequence Error – Door zone input doesn't work in normal order.
1027	Door Zone Monitor Error – Door zone monitor signal is not entered on time. DZM should not work if both DZ1 & DZ2 work and DZE works. Otherwise, DZM should work. Also, when DZE doesn't work, DAM should work.
1028	LVU/LVD means that the car landed out of the door zone. These inputs indicate that the car is in the floor level but escaped from the door zone. LVU and LVD are fixed to the operating status and are not transferred to non-operation while running.
1029	LVU and LVD active at same time. - LU(Level Up) and LD(Level Down) inputs work simultaneously.
1030	Leveling sequence error – Leveling inputs activated in an invalid sequence.
1031	Selected set-up – Selector not setup properly. • Leveling vanes of wrong number are installed. • Bad floor position setup. • Selector setup incomplete • Scanning hatch to fast.
1032	Slow Down Interrupt Failure – Slow down interrupt occurred when the slow down signal input is not enabled.
1033	Selector position error – Selector position out of step with encoder, slowdown or BP position.
1034	Expansion Board Error – Incorrect expansion board type returned. • Expansion board of wrong type is installed. • Defective expansion board or cable. • Extension cable is installed reversely. • Incorrect expansion board type is applied.(See E10 Adjustment part.)
1035	Improper Target Run Req. – NOT IMPLEMENTED AT PRESENT

CODE	DEFINITION
1036	Improper controlled run dir. Change - NOT IMPLEMENTED AT PRESENT
1037	Improper controlled run - NOT IMPLEMENTED AT PRESENT
1038	Improper Find Floor run - NOT IMPLEMENTED AT PRESENT.
1039	Target Run Direction Error – NOT IMPLEMENTED AT PRESENT
1040	Door WatchDog closing failure – DCL input did not activate in expected time interval.
1041	Door WatchDog opening failure – DOL input did not activate in expected time interval.
1042	Stoppage by over-heat.
1043	The car doesn't finish the movement between floors during the low oil timer interval.
1044	Software error – Fire Service Signal Error.
1045	Software error – Primary & secondary Fire Service Signal Error.
1046	Failed to add I/O to hardware assignments list. Invalid I/O name found.
1049	Open door protection failure. Doors failed to open in the allotted time. • Defective I/O • Defective door operation
1050	Close door protection failure. Doors failed to close in the allotted time. • Defective I/O • Defective door operation
1051	Stuck open device error. I/O (SE, EE, DOB) has been stuck in the active state. • Defective I/O • Defective device
1052	Stuck DCB error. DCB I/O has been stuck in the active state. • Defective I/O • Defective device
1053	Not applicable to TKDE.

CODE	DEFINITION
1054	Not applicable to TKDE. Down run time exceeds 5 minutes. Down run time is longer than the down run time of whole hoistway. Defective I/O
1055	Not applicable to TKDE.
1056	In Auto mode, the floor table of encoder counts is not set up. In other mode than Inspection mode, the reference value of pulse on the floor in non-volatile memory is wrong. - Defective Hoistway scan. - Defective CPU. - Poor battery contact.
1057	Encoder is beyond the allowable error on the floor level. It occurs when the car is at the floor level, and the difference of Encoder position count from the concerned floor's position count (pulse) is bigger than P20 parameter.
1058	The position of selector is wrong at the top or bottom floor.
1059	Bad Encoder zeroing. Two consecutive encoder zeroing were out of range. The position counts of two consecutive floors and the encoder counts of these floors are bigger than the value of P20 parameter. Defective Encoder
1060	Selector scan is not completed normally. Selector setup has been failed, or cancelled before completion. - Setup procedure error 186c error - Selector error
1061	Not applicable to TKDE
1062	Not applicable to TKDE (related to NTSD). Encoder interrupt failure. The car passes the slow down point when the encoder didn't receive the confirming signal. - Encoder error - Wrong encoder wiring - Check P17 and P18.
1064	LON Resync Fail Channel A Error – Communication with LON channel A is impossible.
1066	LON Resync Fail Channel B Error - Communication with LON channel B is impossible.
1067	Enabling of both low-temperature sensor and high-temperature sensor has been detected. - One or both sensors are adjusted wrong. - One or both sensors are defective. - Input wire error - CPU card error.

CODE	DEFINITION
1068	Jack cylinder cannot synchronize so it doesn't work. In case of this error, the elevator stops. - Oil is leaked from the component of hydraulic system, and jack adjustment is wrong. - Wrong wiring. - Jack position sensor error. - CPU card error.
1069	False power supply error. Board 186 receives false NMI interrupt input which means power supply error although the power supply is not disconnected. • Defective Power Supply • Board 186 error • Electric noise gives an effect on the signal sensing the power supply failure or on the power supply device (Check the ground and noise attenuation).
1070	LVU/LVD Off in Door Zone. • Defective leveling sensors • Defective wiring • Defective 186 Board.
1071	Lower limit switch override circuit controlled by BLO output finds an error by the monitoring input BLOM. When this error occurs, the elevator stops. • BLO Relay and/or Output error • BLOM Input error • Wrong wiring • CPU card error.
1072	It's not applicable to TKDE (applicable only in case of using the door controller of TKE US). Door contact error. GLM which is the monitoring input signal (or double monitoring signals GL1M and GL2M) detects the error of circuit which configures this gate switch and interlock. • Defective gate contact or hoistway interlock. • Defective wiring. • Defective HDIF or HDIR relay. • Defective 186 Board
1073	Car Gate-Door Open Limit Error. Error occurs because DOL and the gate switch contact of the car work simultaneously. • One or both of defective gate contact and door open limit. • Defective CDCF or DOL input • Detective wiring. • Communication error between 186 Board and door controller. • Either or both of defective 186 Board and door controller.
1074	Jack low-pressure sensor is enabled. Down run is impossible.
1075	Stop switch override circuit controlled by CSTO output has error by CSTOM (CSTO's feedback signal) by input sensing signal. In case of having this error, the elevator is disabled of operation. • Non-standard wire • Defective 186 Board.

CODE	DEFINITION
1076	Freight Door Interlock Stuck Error. The freight door interlock has failed to close at the start of a run, or failed to open at the end of a run. - Defective interlock. - Error by Defective Cam. - Defective wiring - Defective 186 Board.
1077	Encoder Pulse Error. The elevator is hut down at the final landing floor when this error occurs. - Defective encoder. - Defective wiring. - Defective 186 Board.
1078	Low Battery Error. 3-volt battery in the CPU is either low or dead. If this voltage is short, the field-set values (job configuration) cannot be guaranteed. If the job configuration and adjusted values are lost, then the job configuration must be uploaded through IMS. The values of parameters including the hoistway scan should be reentered, to learn the position of the floor. In Gearless case, ETSD should be reset. - Battery replacement needed. (check the battery voltage.) - Battery missing, or installed backwards. - Defective 186 Board.
1079	Down Run attempted but velocity stayed zero. The mentioned position sensor determined the speed of car and attempted the down run, but the speed entered at the position sensor is 0 and it is considered that the car has a fault. - Position sensor (Encoder) error - Run trouble by mechanic problem - Wrong adjustment of position sensor.
1080	Bad Group Job Data – Group software can't run. Stored Non-volatile data has invalid parameters in the group portion. This error is generally generated by the following information in the group memory: - Number of floors = 0 or greater than the allowed maximum number of floors. - Number of cars in the group = 0 or greater than the allowed maximum number of cars. - Number of I/O = 0 or greater than the allowed maximum number of I/O. - Rear Operation is specified but there is no rear opening specified. - Invalid configuration or adjustment - Corrupted memory. Install previously downloaded backup copy of non-volatile memory. This file was generated previously by doing a Service, Transfer, Download from IMS - Bad 186 Board
1081	Bad initialization of non-volatile memory. This can occur if a new section of non-volatile memory is assigned by software but the memory was not accessible at that time. This could happen when updating software or performing the Init or Init all command. Remote FAST displays a message indicating which section of non-volatile memory was failed. - Memory was temporarily unavailable. Reset 186 Board. - Software error. - Corrupted memory. Install previously downloaded backup copy of non-volatile memory. This file was generated previously by doing a Service, Transfer, Download from IMS.

CODE	DEFINITION
1082	Bad Save to non-volatile memory. When saving into non-volatile memory is attempted by software, if it is impossible to save into the memory, this error occurs. If Remote FAST window is opened, it indicates that non-volatile memory has an error. Memory was temporarily unavailable in case that CPU is reset. • Software error. • Corrupted memory. • Bad CPU card.
1083	Bad Recall to non-volatile memory. This can occur if a recall to non-volatile memory is attempted by software but the memory was not available at that time. The Remote FAST (if open) will display a message indicating which section of non-volatile memory failed. • Memory was temporarily unavailable. Reset CPU. • Software error. • Corrupted memory. Install previously downloaded backup copy of non-volatile memory. This file was generated previously by doing a Service, Transfer, Download from IMS. • Bad CPU card.
1084	Car is too far to attempt releveleving • Invalid configuration or adjustment. • Corrupted memory. Install previously downloaded backup copy of non-volatile memory. This file was generated previously by doing a Service, Transfer, Download from IMS. • Bad CPU card.
1085	SPI error was detected at HN or CN node.
1086	Not applicable to TAC50K.
1087	Car has no run request, but MCD input indicates that run circuit contacts were active. • Stuck Motor Contactor Auxiliary Contact (MC1) • Bad CPU card.
1088	Motor Contactor OFF. Car has no run request, but MCE input indicates that the motor contactor was still enabled. • Stuck Motor Contactor Auxiliary Contact (MC1). • Bad CPU card.
1089	Although the gate switch of car door and the interlock switch of hall door are enabled, DCL doesn't work • Faulty Gate Switch or Interlock • Jumpered to Gate Switch or Interlock. • DCL defective or misadjusted.
1090	LON Channel A doesn't work normally. LON Channel A doesn't receive messages from other LON devices on the network.

CODE	DEFINITION
1092	LON Host A cannot communicate with 188/186 processors through parallel port on CPU board.
1093	LON Host B cannot communicate with 188/186 processors through parallel port on CPU board.
1094	Hoistway access monitor failed.
1095	The car is positioned at the top floor, but the dynamic sensor is not enabled.
1096	CDCF ver CDCFM conflict, CDCF and CDCFM in the same state.
1097	CDCF ver CDCFM conflict, CDCF and CDCFM in the same state.
1098	CDCR ver CDCRM conflict, CDCR and CDCRM in the same state.
1099	CDCR ver CDCRM conflict, CDCR and CDCRM in the same state.
1100	Not applicable to TAC50K.
1101	Gate Switch of front door is enabled, but DCL doesn't work.
1102	Gate Switch of rear door is enabled, but DCLR doesn't work.
1103	Door communication fault detected.
1104	Hoistway Interlock Error during Run.
1105	CDCF or CDCR interlock has fault while running.
1106	Running stops. This error is usually connected with other errors.
1107	Levelling time exceeds the reaction delay time set at P22 parameter.
1108	Departure failure. The controller stops working in case of repeating the attempt for departure 6 times.
1109	Input/output status of FSCDB relay is same.

CODE	DEFINITION
1110	Fault that requires checkup occurred. Latched error is initialized only in case of manual resetting. • B44=related error code occurred. • LVU/LVD/DZ1/DZ2 signal error • Causes of 1110 error (B44) 1) 1072: Hall/Car door interlock switch rationality 2) 1075: COP CSTO relay rationality 3) 1101: DCL input error while the front car door is closed 3) 1096: Front car door relay rationality 4) 1098: Front hall door relay rationality 5) 1100; BYPASS SWITCH 6) 1657: BRK contactor A contact/B contact rationality 7) 1109: FSCDB relay rationality 8) 1669: EOBP not used. 9) 1005: DOL is detected while the hall door is closed. 10) 1073: DOL is detected while HW is closed. 11) 1005: DOL is detected while HW is closed. 12) 1089: No DCL with HW and DR mismatch 13) 1027: Door Zone Monitor error (Door zone relay) 14) 1070: Both LVU and LVD off in door zone (Level signal rationality) 15) 1028: Encoder data indicates that the car is within the door zone, and the actual door sensor doesn't work.
1500	Inverter failed to make the exciting current. Run sequence started and is waiting for input of MCE. MCE input is not enabled with the start of run.
1501	MCD contact (B contact) open failure. The running procedures started and the car waits for input of MCD contact, but the contact input is not received until the starting time for running. • Permanent shutdown
1502	MCE contact (A contact) failure during run – At the start of run, MCE contact was attached, but during run, detachment of MCE contact was detected. • Permanent shutdown
1503	Brake open failed by Brake Contactor error— When starting run, check the brake. If BRKC output and BRKE(A contact) input are entered, a run is initiated. Otherwise, brake fault is detected. • Check the brake wiring. • Check the Brake Contactor and Brake Regulator.
1504	Brake operation during run by Brake Contactor error – If BRKC output and BRKE input are normal, a run is initiated. Otherwise, brake fault is detected. • Check the brake wiring.. • Check the Brake Contactor and Brake Regulator. • Permanent shutdown
1505	Not applicable to TKDE.

CODE	DEFINITION
1506	The safety string was opened by the drive (SAF3)
1507	Not applicable to TKDE.
1508	Not applicable to TKDE.
1509	Inverter failed echo to the command of Inverter in CAN communication. During every run, 186 disconnects DRVE signal entering the Inverter for a short moment. Inverter echoes the input signal of DRVE entering 186 together with CAN serial signal. If 186 detects that CAN data doesn't correspond with the status of DRVE, the error occurs. This test is performed as a safety monitoring check to ensure that the drive enable signal is operating properly.
1510	Not applicable to TKDE.
1511	load weigher load line slope negative.
1512	Current line slope negative of PTQ
1513	The car moves even after braking because the value of PTQ is too big.
1514	The value of load weigher device sensor exceeded tolerance.
1515	ESTD failed to echo over CAN. The 186 to ETSD DSP CAN communications is faulty. This error is difficult to determine the cause because this CAN communication line is shared with the Inverter.
1516	ESTD system fault, the ETSD DSP has an internal fault. Refer to ETSF command for further details. • ESTD tables may not be setup. • A TBS setup command was issued and the programming jumper for the DSP is in the non programming position.
1517	Overheat of Motor sensed at the Inverter; Overhead of Brake and Choke sensed at Gearless (option).
1518	Digitizer error.
1519	Running monitoring – Defective Brake Lift Switch
1520	CAN Bus Channel is switched off.
1521	Communication trouble of No. 1 channel of CAN (Initialization failure of CAN controller)

CODE	DEFINITION
1522	Communication trouble of No. 2 channel of CAN (Initialization failure of CAN controller)
1523	Communication trouble of No. 3 channel of CAN (Initialization failure of CAN controller)
1524	CAN controller trouble
1525	Fuse of HN board is disconnected. Check which HN board has a problem, by entering the command DHNF (front door) or DHNR (rear door) on the Remote Fast screen.
1526	CAN channel 1 line (Local) does not respond for 60 secs..
1527	CAN channel 2 line (Local) does not respond for 60 secs.
1528	CAN channel 3 line (Local) does not respond for 60 secs.
1529	CAN didn't transmit the data within the requested time.
1608	Motor Speed too slow vs. Demans. Feedback signal of Motor Encoder is checked by comparison with the speed pattern of 186c Board. The fault is generated if the Motor Encoder is less than the Speed Pattern by more than 125fpm (38m/min)
1609	The deviation of Encoder speed is bigger than the value of M61. The deviation of Motor and Position Encoder is bigger than the value of TKR. In case of this error, the safety line is opened.
1610	The value of Motor Encoder violates the value of speed window. Speed error value (M63) is used to set the upper error margin of speed pattern. The consecutively allowed number of times exceeding this error margin is set with M64. In other words, unless the number of times exceeding the error margin consecutively exceeds the set value of M64, the system will not occur any error. This error opens the Safety String via removal of the SAFC output. Reset via Tach Fault Reset TFR command.
1611	Wiring is made in reverse way from the Motor Encoder to 186c Board. The direction of Motor during express run is compared with the commanded value. The direction of motor is needed for detecting the roll-back phenomenon necessary for automatic zeroing of pre-torque system.
1612	This occurs when the motor moved above 6 inches(152mm) but the car(selector) moved less 1 inch(25mm). It can be checked by DCD command on R-Fast screen.
1620	Position Encoder Loss error -- The car is in Auto by receiving the speed command, the Position Encoder is checked during sampling. If the value of Encoder does not change, this error occurs.

CODE	DEFINITION
1652	Car speed is within 10 fpm of set value of speed window. This is just a warning to indicate a potential problem prior to issuing a Tach Fault 1610.
1653	Contact error (SAFCD, MCCD, BRKCD, MCPD) Whenever the car arrives at the destination floor during every high-speed run, 186c removes the DRVE signal coming from the Inverter, and monitors the operation status of safety line relays. Inverter includes the status of DRVE in the CAN message and echoes it to 186c. If the Inverter does not include the correct status of DRVE in CAN message and send it within the specified time, the error occurs. • Wrong DRVE output wiring going into the Inverter from 186c. • Defective DRVE output. • Defective DRVE input into the Inverter. • DRVE cannot be input into the Inverter due to opening of safety line by other device. While DRVE is low, check the status of safety relays of total lower system including SAFDRV, ETSX and 186c (SAFC, MCC, BRK, MCPD), and check if they work by opening them for a while.
1654	Movement of uncontrolled car is detected.
1655	RGOK input error.
1656	Rope Gripper monitoring error
1657	BRKC fault
1658	CAN Buffer over-run
1659	Motor Encoder sensed the movement of above 6 inches, but Position Encoder sensed the movement of less than 1 inch. In this case, DEM has error. Check the actual encoder value of every error case, by entering DEM command on Remote Fast.
1660	DEM sensed CAN communication error. The error could be deleted but DEM records the error.
1661	CAN communication error from 186c to DEM board • Wrong wiring • Power supply failure of DEM
1662	186c sensed the movement, but DEM didn't. • Wrong wiring between the Encoder and the DEM board
1663	DEM sensed the SPI loop trouble. • DEM board fault

CODE	DEFINITION
1664	Position Encoder sensed the movement of above 12 inches but Motor Encoder sensed the movement of less than 3 inches. In this case, DEM has error. . In this case, DEM has error. Check the actual encoder value of every error case, by entering DEM command on Remote Fast.
1665	DEM Encoder detected that the deviation between Motor Encoder and Position Encoder is above 5% or 100rpm. • Check if the resolution of Motor Encoder and Position Encoder equals to the value of each name plate. • Check if the times of rotation per minute of Motor Encoder is set properly according to the spec.
1666	DEM SPI warning. It indicates the problem that SPI loop may have fault.
1667	RO1 Relay fault of DEM board • Replace the RO1 Relay.
1668	RO2 Relay fault of DEM board • Replace the RO2 Relay.
1669	Rescue Operation – When EOBP is enabled, EOBPM is disabled.
1670	Rescue Operation –When INEO is enabled, INEOM is disabled.
1671	Rescue Operation – UPS battery trouble
1672	Rescue Operation – Car doesn't move when the Brake is released.
1673	No-run 2. Speed pattern lost the running signal while the car runs. Check the inputs of safety line including MCD, BRKE, MCD and BRKD.
1674	Pre-torque cannot work by input of invalid load value. Load sensor calculated the load too small or above 150% of rated load. Pre-torque and maximum speed are disabled.
1675	MCE Contactor was opened while running (MCE was opened in the final running section).
1676	MCE Contactor was opened while running (MCE was opened while waiting for releasing of brake).
1677	MCE Contactor was opened while running (MCE was opened while running).
1678	MCE Contactor was opened while running (MCE was opened in the final stopping section).

CODE	DEFINITION
1679	MMCE drops during operation
1681	Run disabled ("fMoving" signal is lost while running.)
1682	Run disabled (invalid run type is executed after start delay)
1683	Run disabled (inverter enable signal input error when starting)
1684	Run disabled (inverter run signal input error when starting)
1685	Upgrades invalid CN version - CN software.
1686	Upgrades invalid HN version – HN software. Software of CN/HN is not compatible with the generic software of the concerned car. Upgrades the software of CN/HN to the latest version.
1687	No poll response of CN – Input is cleared.
1688	No poll response of HN – Input is cleared. CN/HN have important input/output related to safety, but there is no response to the request of these signals at the control panel. All inputs and outputs of concerned node are cleared.
1689	Exceeding of maximum node number of safety line – Car is prohibited to operate. Job configuration has CN/HN with too many input/output signals of safety line. In case of having an error, contact the factory.
1690	Configuration of invalid CN. Job configuration has invalid CN. Contact the factory.
1691	Invalid message ID on No. 1 channel
1692	Invalid message ID on No. 2 channel
1693	Invalid message ID on No. 3 channel
1694	Length of invalid CAN message. Control panel senses invalid CAN message. Checks CAN bus.
1702	Compulsory stop occurred at the top floor at the speed above the slow down speed of car. (6LS)
1703	Compulsory stop occurred at the bottom floor at the speed above the slow down speed of car. (5LS)

CODE	DEFINITION
2000	Passenger confined (Jugong spec.)
2001	SDB is not detected when the car is at the bottom floor.
2002	SDT is not detected when the car is at the top floor
2003	Operation started but the car doesn't move. (mechanic defect or encoder trouble)
2004	Inverter senses overheat of the heat sink
9999	During slow down, the speed pattern bypasses the destination floor.