## Symptom:
### *"NO BUS" IN VF DISPLAY

| POSSIBLE CAUSES |
|---|
| PCI BUS MESSAGES NOT REC'D BY MIC |
| INSTRUMENT CLUSTER |

| TEST | ACTION | APPLICABILITY |
|---|---|---|
| 1 | Turn the ignition on.<br>With the DRBIII®, select J1850 Module Scan.<br>Does the DRBIII® display MIC in the J1850 Module Scan?<br><br>Yes → Replace the Instrument Cluster in accordance with the Service Information.<br>Perform BODY VERIFICATION TEST - VER 1.<br><br>No → Refer to the COMMUNICATION category and perform the appropriate symptom.<br>Perform BODY VERIFICATION TEST - VER 1. | All |