## Symptom:

## *NO RESPONSE FROM PCM (PCM SCI ONLY) - NGC

| POSSIBLE CAUSES |
|---|
| CHECK PCM POWERS AND GROUNDS |
| CONTROLLER ANTILOCK BRAKE |
| SCI TRANSMIT CIRCUIT SHORTED TO VOLTAGE |
| SCI RECEIVE CIRCUIT SHORTED TO VOLTAGE |
| SCI CIRCUITS SHORTED TOGETHER |
| SCI TRANSMIT CIRCUIT SHORTED TO GROUND |
| SCI RECEIVE CIRCUIT SHORTED TO GROUND |
| SCI RECEIVE CIRCUIT OPEN |
| SCI TRANSMIT CIRCUIT OPEN |
| POWERTRAIN CONTROL MODULE |

| TEST | ACTION | APPLICABILITY |
|---|---|---|
| 1 | Perform the symptom Checking PCM Power and Ground Circuits in the Driveability category.<br>**NOTE: With the DRBIII® in the generic scan tool mode, attempt to communicate with the PCM.**<br>**NOTE: If the DRBIII® can communicate with the PCM in the generic scan tool mode, it may not be necessary to perform this step.**<br>Did the vehicle pass this test?<br>Yes → Go To 2<br>No → Repair as necessary.<br>Perform POWERTRAIN VERIFICATION TEST VER - 1. | All |
| 2 | Turn the ignition off.<br>Disconnect the PCM harness connectors.<br>Disconnect the DRB from the DLC.<br>Measure the resistance between ground and the SCI Transmit circuit at the DLC (cav 7).<br>Is the resistance below 5.0 ohms?<br>Yes → Go To 3<br>No → Go To 4 | All |