## P0068-MANIFOLD PRESSURE/THROTTLE POSITION CORRELATION - VACUUM LEAK DETECTED — Continued

| TEST | ACTION | APPLICABILITY |
|---|---|---|
| 9 | Measure the resistance between ground and the (K22) TP Sensor No.1 Signal circuit at the TP Sensor harness connector.<br>Is the resistance above 100k ohms?<br>Yes → Go To 10<br>No → Repair the short to ground in the (K22) TP Sensor No.1 Signal circuit.<br>Perform POWERTRAIN VERIFICATION TEST VER - 5. | All |
| 10 | **CAUTION: DO NOT PROBE THE PCM HARNESS CONNECTORS. PROBING THE PCM HARNESS CONNECTORS WILL DAMAGE THE PCM TERMINALS RESULTING IN POOR TERMINAL TO PIN CONNECTION. INSTALL MILLER SPECIAL TOOL #8815 TO PERFORM DIAGNOSIS.**<br>Measure the resistance of the (K900) Sensor ground circuit from the TP Sensor harness connector to the appropriate terminal of special tool #8815.<br>Is the resistance below 5.0 ohms?<br>Yes → Go To 17<br>No → Repair the excessive resistance in the (K900) Sensor Ground circuit.<br>Perform POWERTRAIN VERIFICATION TEST VER - 5. | All |
| 11 | Turn the ignition off.<br>Disconnect the MAP Sensor harness connector.<br>Disconnect the C1 and C2 PCM harness connectors.<br>**CAUTION: DO NOT PROBE THE PCM HARNESS CONNECTORS. PROBING THE PCM HARNESS CONNECTORS WILL DAMAGE THE PCM TERMINALS RESULTING IN POOR TERMINAL TO PIN CONNECTION. INSTALL MILLER SPECIAL TOOL #8815 TO PERFORM DIAGNOSIS.**<br>Measure the resistance of the (F856) 5-volt Supply circuit from the MAP Sensor harness connector to the appropriate terminal of special tool #8815.<br>Is the resistance below 5.0 ohms?<br>Yes → Go To 12<br>No → Repair the excessive resistance in the (F856) 5-volt Supply circuit.<br>Perform POWERTRAIN VERIFICATION TEST VER - 5. | All |
| 12 | Measure the resistance between ground and the (F856) 5-volt Supply circuit at the MAP Sensor harness connector.<br>Is the resistance above 100k ohms?<br>Yes → Go To 13<br>No → Repair the short to ground in the (F856) 5-volt Supply circuit.<br>Perform POWERTRAIN VERIFICATION TEST VER - 5. | All |