## Symptom:

## P0108-MAP SENSOR CIRCUIT HIGH

**When Monitored and Set Condition:**

**P0108-MAP SENSOR CIRCUIT HIGH**

When Monitored: Engine RPM greater than 260. Battery voltage greater than 10.3 volts

Set Condition: The MAP sensor signal voltage is greater than 4.93 volts.

| POSSIBLE CAUSES |
|---|
| MAP SENSOR VOLTAGE ABOVE 4.93 VOLTS |
| MAP SENSOR |
| (K1) MAP SIGNAL CIRCUIT SHORTED TO BATTERY VOLTAGE |
| (K1) MAP SIGNAL CIRCUIT OPEN |
| (K1) MAP SIGNAL CIRCUIT SHORTED TO THE (F856) 5-VOLT SUPPLY CIRCUIT |
| (K900) SENSOR GROUND CIRCUIT OPEN |
| PCM |

| TEST | ACTION | APPLICABILITY |
|---|---|---|
| 1 | Start the engine.<br>With the DRBIII®, read DTCs and record the related Freeze Frame data.<br>With the DRBIII®, read the MAP Sensor voltage.<br>Is the voltage above 4.93 volts?<br>Yes → Go To 2<br>No → Refer to the INTERMITTENT CONDITION Symptom (Diagnostic Procedure).<br>Perform POWERTRAIN VERIFICATION TEST VER - 5. | All |
| 2 | Turn the ignition off.<br>Disconnect the MAP Sensor harness connector.<br>Connect a jumper wire between the (K1) MAP Signal circuit and the (K900) Sensor ground circuit in the harness connector.<br>Ignition on, engine not running.<br>With the DRBIII®, monitor the MAP Sensor voltage.<br>Is the voltage below 1.0 volt?<br>Yes → Replace the MAP Sensor.<br>Perform POWERTRAIN VERIFICATION TEST VER - 5.<br>No → Go To 3<br>**NOTE: Remove the jumper wire before continuing.** | All |