## P0344-CAMSHAFT POSITION SENSOR INTERMITTENT — Continued

| TEST | ACTION | APPLICABILITY |
|---|---|---|
| 7 | If there are no possible causes remaining, view repair.<br><br>Repair<br>Replace the Camshaft Position Sensor.<br>Perform POWERTRAIN VERIFICATION TEST VER - 5. | All |
| 8 | Turn the ignition off.<br>Disconnect the C1 and C2 PCM harness connectors.<br>Ignition on, engine not running.<br>Measure the voltage on the (K44) CMP Signal circuit.<br>Wiggle the related wire harness while taking this measurement.<br>Does the voltage ever increase above 5.5 volts?<br><br>Yes → Repair the short to voltage in the (K44) CMP Signal circuit.<br>Perform POWERTRAIN VERIFICATION TEST VER - 5.<br><br>No → Go To 9 | All |
| 9 | Turn the ignition off.<br>**CAUTION: DO NOT PROBE THE PCM HARNESS CONNECTORS. PROBING THE PCM HARNESS CONNECTORS WILL DAMAGE THE PCM TERMINALS RESULTING IN POOR TERMINAL TO PIN CONNECTION. INSTALL MILLER SPECIAL TOOL #8815 TO PERFORM DIAGNOSIS.**<br>Measure the resistance in the (K44) CMP Signal circuit from the CMP harness connector to the appropriate terminal of special tool #8815.<br>Wiggle the related wire harness while taking this measurement.<br>Is the resistance below 5.0 ohms?<br><br>Yes → Go To 10<br><br>No → Repair the excessive resistance in the (K44) CMP Signal circuit.<br>Perform POWERTRAIN VERIFICATION TEST VER - 5. | All |
| 10 | Measure the resistance between ground and the (K44) CMP Signal circuit in the CMP Sensor harness connector.<br>Wiggle the related wire harness while monitoring the resistance value.<br>Does the resistance ever go below 100 ohms?<br><br>Yes → Repair the short to ground in the (K44) CMP Signal circuit.<br>Perform POWERTRAIN VERIFICATION TEST VER - 5.<br><br>No → Go To 11 | All |
| 11 | Measure the resistance between the (F856) 5-volt Supply circuit and the (K44) CMP Signal circuit in the CMP harness connector.<br>Wiggle the related wire harness while taking this measurement.<br>Does the resistance ever go below 5.0 ohms?<br><br>Yes → Repair the short between the (F856) 5-volt Supply circuit and the (K44) CMP Signal circuit.<br>Perform POWERTRAIN VERIFICATION TEST VER - 5.<br><br>No → Go To 12 | All |