Symptom:

P0481-COOLING FAN NO.2 CONTROL CIRCUIT

When Monitored and Set Condition:

P0481-COOLING FAN NO.2 CONTROL CIRCUIT

When Monitored: With the ignition on. Battery voltage greater than 10 volts.

Set Condition: An open or shorted circuit is detected in the high speed radiator fan relay control circuit. One Trip Fault.

POSSIBLE CAUSES
HIGH SPEED RADIATOR FAN RELAY OPERATION
HIGH SPEED RADIATOR FAN RELAY
(F20) FUSED IGNITION SWITCH OUTPUT CIRCUIT
(A16) FUSED B+ CIRCUIT
(N112) HIGH SPEED RAD FAN RELAY CONTROL CIRCUIT OPEN
(N112) HIGH SPEED RAD FAN RELAY CONTROL CIRCUIT SHORT TO GROUND
PCM

TEST	ACTION	APPLICABILITY
1	Ignition on, engine not running. With the DRBIII®, actuate the High Speed Radiator Fan Relay. Is the High Speed Radiator Fan Relay operating? Yes → Refer to the INTERMITTENT CONDITION Symptom (Diagnostic Procedure). Perform POWERTRAIN VERIFICATION TEST VER - 5. No → Go To 2	All
2	Turn the ignition off. Remove the High Speed Radiator Fan Relay from the PDC. Measure the resistance of the High Speed Radiator Fan Relay between the (F20) Fused Ignition Switch Output terminal and the (N112) High Speed Rad Fan Relay Control terminal. Is the resistance between 60 to 85 ohms? Yes → Go To 3 No → Replace the High Speed Radiator Fan Relay. Perform POWERTRAIN VERIFICATION TEST VER - 5.	All