P0506-IDLE SPEED PERFORMANCE LOWER THAN EXPECTED — Continued

TEST	ACTION	APPLICABILITY
3	Inspect the throttle plate for carbon build up or other restrictions. Verify that the throttle cable between the Accelerator Pedal and the Throttle body is not binding. Make sure the throttle plate is in the idle position. Remove the IAC Motor and actuate the IAC Motor with the DRBIII® to verify proper operation. Install the IAC Motor. **WARNING: WHEN THE ENGINE IS OPERATING, DO NOT STAND IN A DIRECT LINE WITH THE FAN. DO NOT PUT YOUR HANDS NEAR THE PULLEYS, BELTS OR FAN. DO NOT WEAR LOOSE CLOTHING.** With the vehicle is running, lightly tap on IAC Motor, with your hand, and listen for idle to raise. Were any problems found? Yes → Repair or replace as necessary. Perform POWERTRAIN VERIFICATION TEST VER - 5. No → Go To 4	All
4	**NOTE: Before continuing, check the PCM harness connector terminals for corrosion, damage, or terminal push out. Repair as necessary.** Using the schematics as a guide, inspect the wire harness and connectors. Pay particular attention to all Power and Ground circuits. If there are no possible causes remaining, view repair. Repair Replace and program the Powertrain Control Module per Service Information. Perform POWERTRAIN VERIFICATION TEST VER - 5.	All