## P0513-INVALID SKIM KEY — Continued

| TEST | ACTION | APPLICABILITY |
|---|---|---|
| 5 | With the DRBIII®, display the VIN that is programmed in the PCM.<br>Was the correct VIN programmed into the PCM?<br><br>Yes → Go To 6<br><br>No → Replace and program the Powertrain Control Module per Service Information.<br>Perform SKIS VERIFICATION. | All |
| 6 | Turn the ignition off.<br>Replace and program the Sentry Key Immobilizer Module per Service Information.<br>Ignition on, engine not running.<br>With the DRBIII®, erase all SKIM and PCM DTCs.<br>Attempt to start and idle the engine.<br>With the DRBIII®, read the PCM DTCs.<br>Does the DRBIII® display this code?<br><br>Yes → NOTE: Before continuing, check the PCM harness connector termnals for corrosion, damage, or terminal push out. Repair as necessary. Replace and program the Powertrain Control Module per Service Information.<br>Perform SKIS VERIFICATION.<br><br>No → Test Complete. | All |
| 7 | **NOTE: You must obtain the SKIM pin number.**<br>**NOTE: This DTC could have been set if the SKIM harness connector was disconnected, or if the SKIM was replaced recently.**<br>**NOTE: All keys that the customer uses for this vehicle must be tested to verify they are operating properly.**<br>Verify the correct VIN is programmed into the PCM and SKIM.<br>Turn the ignition off.<br>With the next customer key turn the ignition key on and crank the engine to start.<br>With the DRBIII®, read the PCM DTCs. Look for P0513.<br>Is the Good Trip Counter for DTC P0513 displayed and equal to 0?<br><br>Yes → Replace the Ignition Key.<br>Perform SKIS VERIFICATION.<br><br>No → Test Complete.<br><br>**NOTE: If this DTC cannot be reset, it could have been an actual theft attempt.** | All |