P0897-WORN OUT/BURNT TRANSAXLE FLUID — Continued

TEST	ACTION	APPLICABILITY
2	Turn the ignition off. Remove the Transmission Oil Pan and Oil Filter per the Service Information. Install a new Transmission Oil Filter per Service Information. Reinstall Transmission Oil Pan, and refill with new Transmission Fluid per the Service Information. **Note: The Transmission Cooler must be flushed before prodceeding.** Start the engine, check and adjust the Transmission Fluid Level per Service Information. Allow the engine to idle for 10 minutes, in Park. Flush the Transmission Oil Cooler per the Service Information. Turn the ignition off. Drain and refill the Transmission Fluid. Flush the Transmission Oil Cooler again. Start the engine, check and adjust the Transmission Fluid Level per Service Information. With the DRBIII®, perform a Battery Disconnect. **Note: This must be done to re enable EMCC during an A/C Clutch engagement.** The vehicle may exhibit intermittent shudder during the first few hundred miles. **Note: The oil will gradually penetrate the TCC friction material and the shudder should disappear.** Erase the DTC and return the vehicle to the customer. Did the Code reset or does the vehicle still shudder after a few thousand miles? Yes → Replace the Torque Convertor per the Service Information. Perform 42RLE TRANSMISSION VERIFICATION TEST - VER 1. No → Test Complete.	All