ANTENNA FAILURE — Continued

POSSIBLE CAUSES
SKIM INTERNAL DTC FAILURE

TEST	ACTION	APPLICABILITY
1	**Note: This trouble code indicates an internal SKIM fault.** With the DRBIII®, read and record the SKIM DTCs and then erase the SKIM DTCs Perform 5 ignition key cycles, leaving the ignition key on for a minimum of 90 seconds per cycle. With the DRBIII® , read the SKIM DTCs. Did the same SKIM DTC return? Yes → Replace and program the Sentry Key Immobilizer Module in accordance with the Service Information. Perform SKIS VERIFICATION. No → Test Complete.	All