Symptom:

P0072-AMBIENT TEMP SENSOR CIRCUIT LOW

When Monitored and Set Condition:

P0072-AMBIENT TEMP SENSOR CIRCUIT LOW

When Monitored: The ignition key on.

Set Condition: Ambient Temperature Sensor is less than 0.039 of a volt at the PCM for 4.8 seconds. Three good trips to clear the MIL.

POSSIBLE CAUSES
AAT SENSOR VOLTAGE BELOW 0.3 OF A VOLT
AAT SENSOR
(G31) AAT SIGNAL CIRCUIT SHORTED TO GROUND
(G31) ATT SIGNAL CIRCUIT SHORTED TO THE (K900) SENSOR GROUND
PCM

TEST	ACTION	APPLICABILITY
1	Ignition on, engine not running. With the DRBIII®, read the Ambient Temperature Sensor voltage. Is the voltage below 0.3 of a volt? Yes → Go To 2 No → Refer to the INTERMITTENT CONDITION Symptom (Diagnostic Procedure). Perform POWERTRAIN VERIFICATION TEST VER - 5.	All
2	Turn the ignition off. Disconnect the Ambient Temperature Sensor harness connector. Ignition on, engine not running. With the DRBIII®, read AAT Sensor voltage. Is the voltage above 4.6 volts? Yes → Replace the Ambient Temperature Sensor. Perform POWERTRAIN VERIFICATION TEST VER - 5. No → Go To 3	All
3	Turn the ignition off. Disconnect the C1 and C2 PCM harness connectors. Measure the resistance between ground and the (G31) AAT Signal circuit at the AAT Sensor harness connector. Is the resistance below 100 ohms? Yes → Repair the short to ground in the (G31) AAT Signal circuit. Perform POWERTRAIN VERIFICATION TEST VER - 5. No → Go To 4	All