Symptom:

P0108-MAP SENSOR CIRCUIT HIGH

When Monitored and Set Condition:

P0108-MAP SENSOR CIRCUIT HIGH

When Monitored: Engine RPM greater than 260. Battery voltage greater than 10.3 volts

Set Condition: The MAP sensor signal voltage is greater than 4.93 volts.

POSSIBLE CAUSES
MAP SENSOR VOLTAGE ABOVE 4.93 VOLTS
MAP SENSOR
(K1) MAP SIGNAL CIRCUIT SHORTED TO BATTERY VOLTAGE
(K1) MAP SIGNAL CIRCUIT OPEN
(K1) MAP SIGNAL CIRCUIT SHORTED TO THE (F856) 5-VOLT SUPPLY CIRCUIT
(K900) SENSOR GROUND CIRCUIT OPEN
PCM

TEST	ACTION	APPLICABILITY
1	Start the engine. With the DRBIII®, read DTCs and record the related Freeze Frame data. With the DRBIII®, read the MAP Sensor voltage. Is the voltage above 4.93 volts? Yes → Go To 2 No → Refer to the INTERMITTENT CONDITION Symptom (Diagnostic Procedure). Perform POWERTRAIN VERIFICATION TEST VER - 5.	All
2	Turn the ignition off. Disconnect the MAP Sensor harness connector. Connect a jumper wire between the (K1) MAP Signal circuit and the (K900) Sensor ground circuit in the harness connector. Ignition on, engine not running. With the DRBIII®, monitor the MAP Sensor voltage. Is the voltage below 1.0 volt? Yes → Replace the MAP Sensor. Perform POWERTRAIN VERIFICATION TEST VER - 5. No → Go To 3 **NOTE: Remove the jumper wire before continuing.**	All