Symptom:

P0125-INSUFFICIENT COOLANT TEMP FOR CLOSED-LOOP FUEL CONTROL

When Monitored and Set Condition:

P0125-INSUFFICIENT COOLANT TEMP FOR CLOSED-LOOP FUEL CONTROL

When Monitored: With battery voltage greater than 10.4 volts and after engine is started.

Set Condition: The engine temperature does not go above -10°C (15°F). Failure time depends on start-up coolant temperature and ambient temperature. (i.e. 2 minutes for a start temp of -10°C (15°F) or up to 10 mintues for a vehicle with a start-up temp of -28°C (5°F). Two Trip Fault.

POSSIBLE CAUSES
LOW COOLANT LEVEL
THERMOSTAT OPERATION
ECT SENSOR

TEST	ACTION	APPLICABILITY
1	**NOTE: If a Engine Coolant Temperature (ECT) DTC is set along with this code, diagnose the ECT DTC first.** **NOTE: Inspect the ECT terminals and related PCM terminals. Ensure the terminals are free from corrosion and damage.** **NOTE: The best way to diagnose this DTC is to allow the vehicle to sit overnight outside in order to have a totally cold soaked engine.** **NOTE: Extremely cold outside ambient temperatures may have caused this DTC to set.** **WARNING: Never open the cooling system when the engine is hot. The system is under pressure. Extreme burns or scalding may result. Allow the engine to cool before opening the cooling system.** Inspect the coolant system for proper level and condition. Is the coolant level and condition OK? Yes → Go To 2 No → Inspect the vehicle for a coolant leak and add the necessary amount of coolant. Perform POWERTRAIN VERIFICATION TEST VER - 5.	All