P0201-FUEL INJECTOR NO.1 CIRCUIT — Continued

P0206-FUEL INJECTOR NO.6 CIRCUIT

When Monitored: With battery voltage greater than 11.9981 volts. Auto Shutdown Relay energized. Engine speed less than 3008 rpm.

Set Condition: No inductive spike is detected after injector turn off.

POSSIBLE CAUSES
GOOD TRIP EQUAL TO ZERO
(F142), (K334) ASD RELAY OUTPUT CIRCUIT
FUEL INJECTOR
INJECTOR CONTROL CIRCUIT OPEN
INJECTOR CONTROL CIRCUIT SHORTED TO GROUND
PCM

TEST	ACTION	APPLICABILITY
1	Ignition on, engine not running. With the DRBIII®, read DTCs and record the related Freeze Frame data. Is the Good Trip Counter displayed and equal to zero? Yes → Go To 2 No → Refer to the INTERMITTENT CONDITION Symptom (Diagnostic Procedure). Perform POWERTRAIN VERIFICATION TEST VER - 5.	All
2	**NOTE: (F142) is the ASD Relay Output circuit on the 2.4L and (K334) is the ASD Relay Output on the 4.0L.** Turn the ignition off. Disconnect the Fuel Injector harness connector. Ignition on, engine not running. With the DRBIII®, actuate the ASD Relay. Using a 12-volt test light connected to ground, backprobe the (F142), (K334) ASD Relay Output circuit at the Fuel Injector harness connector. Does the test light illuminate brightly? Yes → Go To 3 No → Repair the open or short to ground in the (F142), (K334) ASD Relay Output circuit. Perform POWERTRAIN VERIFICATION TEST VER - 5.	All