P0455-EVAP SYSTEM LARGE LEAK — Continued

TEST	ACTION	APPLICABILITY
2	Check for any related TSBs before continuing. **NOTE: Since a hot vehicle can conceal a leak, it is best to perform this test at room temperature.** **NOTE: A loose gas cap could have caused this DTC to set. Make sure gas cap is tight and in good condition. Make sure the gas cap meets OEM specifications.** Ignition on, engine not running. With the DRBIII®, read DTCs and record the related Freeze Frame data. Is the Good Trip Counter displayed and equal to zero? Yes → Go To 3 No → Refer to the INTERMITTENT CONDITION Symptom (Diagnostic Procedure). Perform POWERTRAIN VERIFICATION TEST VER - 6.	All
3	Perform a visual and physical inspection of the entire Evaporative Emission system. Check for the follow conditions: - Holes or cracks - Loose seal points - Evidence of damaged components - Incorrect routing of hoses and tubes - Fuel Cap gasket seal Were any of the above conditions found? Yes → Repair as necessary. Perform POWERTRAIN VERIFICATION TEST VER - 6. No → Go To 4	All