## Symptom:

## P0481-COOLING FAN NO.2 CONTROL CIRCUIT

**When Monitored and Set Condition:**

**P0481-COOLING FAN NO.2 CONTROL CIRCUIT**

When Monitored: With the ignition on. Battery voltage greater than 10 volts.

Set Condition: An open or shorted circuit is detected in the high speed radiator fan relay control circuit. One Trip Fault.

| POSSIBLE CAUSES |
|---|
| HIGH SPEED RADIATOR FAN RELAY OPERATION |
| HIGH SPEED RADIATOR FAN RELAY |
| (F20) FUSED IGNITION SWITCH OUTPUT CIRCUIT |
| (A16) FUSED B+ CIRCUIT |
| (N112) HIGH SPEED RAD FAN RELAY CONTROL CIRCUIT OPEN |
| (N112) HIGH SPEED RAD FAN RELAY CONTROL CIRCUIT SHORT TO GROUND |
| PCM |

| TEST | ACTION | APPLICABILITY |
|---|---|---|
| 1 | Ignition on, engine not running.<br>With the DRBIII®, actuate the High Speed Radiator Fan Relay.<br>Is the High Speed Radiator Fan Relay operating?<br><br>Yes → Refer to the INTERMITTENT CONDITION Symptom (Diagnostic Procedure).<br>Perform POWERTRAIN VERIFICATION TEST VER - 5.<br><br>No → Go To 2 | All |
| 2 | Turn the ignition off.<br>Remove the High Speed Radiator Fan Relay from the PDC.<br>Measure the resistance of the High Speed Radiator Fan Relay between the (F20) Fused Ignition Switch Output terminal and the (N112) High Speed Rad Fan Relay Control terminal.<br>Is the resistance between 60 to 85 ohms?<br><br>Yes → Go To 3<br><br>No → Replace the High Speed Radiator Fan Relay.<br>Perform POWERTRAIN VERIFICATION TEST VER - 5. | All |