Symptom:
P0501-VEHICLE SPEED SIGNAL PERFORMANCE

When Monitored and Set Condition:

P0501-VEHICLE SPEED SIGNAL PERFORMANCE

When Monitored: With the engine running, transmission not in park or neutral, brakes not applied, and engine rpm greater than 1500.

Set Condition: This code will set if no vehicle speed signal is received from the Body Control Module for more than 11 seconds for 2 consecutive trips.

POSSIBLE CAUSES
GOOD TRIP EQUAL TO ZERO
(K75) VSS CIRCUIT SHORTED TO BATTERY VOLTAGE
RESISTANCE IN THE (F856) 5-VOLT SUPPLY
RESISTANCE BETWEEN GROUND AND THE (F856) 5-VOLT SUPPLY CIRCUIT
VEHICLE SPEED SENSOR
RESISTANCE BETWEEN GROUND AND THE (K75) VSS SIGNAL CIRCUIT
(K75) VSS SIGNAL CIRCUIT SHORTED TO THE (K900) SENSOR GROUND CIRCUIT
PCM

TEST	ACTION	APPLICABILITY
1	Ignition on, engine not running. With the DRBIII®, read DTCs and record the related Freeze Frame data. Is the Good Trip Counter displayed and equal to zero? Yes → Go To 2 No → Refer to the INTERMITTENT CONDITION Symptom (Diagnostic Procedure). Perform POWERTRAIN VERIFICATION TEST VER - 5.	All
2	Disconnect the Vehicle Speed Sensor harness connector. Disconnect the C1 PCM harness connector. Ignition on, engine not running. Measure the voltage on the (K75) Vehicle Speed Sensor Signal circuit in the Vehicle Speed Sensor harness connector. Is the voltage above 5.2 volts? Yes → Repair the short to voltage in the (K75) VSS Signal circuit. Perform POWERTRAIN VERIFICATION TEST VER - 5. No → Go To 3	All