Symptom:

P0516-BATTERY TEMPERATURE SENSOR LOW

When Monitored and Set Condition:

P0516-BATTERY TEMPERATURE SENSOR LOW

When Monitored: Ignition on.

Set Condition: Battery temperature sensor voltage below 0.0392 of a volt for 4.8 seconds. Three good trips to clear the MIL.

POSSIBLE CAUSES
BATTERY TEMP VOLTS BELOW 0.0392 OF A VOLT
BATTERY TEMPERATURE SENSOR
(K25) BATT TEMP SIGNAL CIRCUIT SHORTED TO GROUND
(K25) BATT TEMP SIGNAL CIRCUIT SHORTED TO THE (K900) SENSOR GROUND CIRCUIT
PCM

TEST	ACTION	APPLICABILITY
1	Ignition on, engine not running. With the DRBIII® record all DTCs and the related Freeze Frame data. With DRBIII®, monitor the Battery Temperature Sensor voltage. Is the voltage below 0.0392 of a volt? Yes → Go To 2 No → Refer to the INTERMITTENT CONDITION Symptom (Diagnostic Procedure). Perform POWERTRAIN VERIFICATION TEST VER - 2.	All
2	With the DRBIII® in sensors, read the Battery Temp Sensor Voltage value. Disconnect the Battery Temperature Sensor harness connector. Did the Batt Temp Sensor voltage change from below 1.0 volt to above 4.5 volts? Yes → Replace the Battery Temperature Sensor. Perform POWERTRAIN VERIFICATION TEST VER - 2. No → Go To 3	All
3	Turn the ignition off. Disconnect the C3 PCM harness connector. Measure the resistance between ground and the (K25) Batt Temp Signal circuit at the Battery Temp Sensor harness connector. Is the resistance below 100 ohms? Yes → Repair the short to ground in the (K25) Batt Temp Signal circuit. Perform POWERTRAIN VERIFICATION TEST VER - 2. No → Go To 4	All