## P0580-SPEED CONTROL SWITCH NO.1 LOW — Continued

| TEST | ACTION | APPLICABILITY |
|---|---|---|
| 4 | Turn the ignition off.<br>Disconnect the clockspring 6-way harness connector (instrument panel wiring side) per Service Information.<br>Ignition on, engine not running.<br>With the DRBIII® in Sensors, read the S/C Switch voltage.<br>Did the S/C Switch volts change to 5.0 volts?<br><br>Yes → Replace the Clockspring.<br>Perform POWERTRAIN VERIFICATION TEST VER - 4.<br><br>No → Go To 5 | All |
| 5 | Turn the ignition off.<br>Connect the Clockspring harness connector per Service Information.<br>Disconnect the C3 PCM harness connector.<br>**CAUTION: DO NOT PROBE THE PCM HARNESS CONNECTORS. PROBING THE PCM HARNESS CONNECTORS WILL DAMAGE THE PCM TERMINALS RESULTING IN POOR TERMINAL TO PIN CONNECTION. INSTALL MILLER SPECIAL TOOL #8815 TO PERFORM DIAGNOSIS.**<br>Measure the resistance between the (K900) Sensor ground circuit and the (V37) S/C Signal circuit at the Speed Control Switch.<br>Is the resistance below 5.0 ohms?<br><br>Yes → Repair the (V37) S/C Signal circuit shorted to the (K900) Sensor ground circuit.<br>Perform POWERTRAIN VERIFICATION TEST VER - 4.<br><br>No → Go To 6 | All |
| 6 | **CAUTION: DO NOT PROBE THE PCM HARNESS CONNECTORS. PROBING THE PCM HARNESS CONNECTORS WILL DAMAGE THE PCM TERMINALS RESULTING IN POOR TERMINAL TO PIN CONNECTION. INSTALL MILLER SPECIAL TOOL #8815 TO PERFORM DIAGNOSIS.**<br>Measure the resistance between ground and the (V37) S/C Signal circuit at the appropriate terminal of special tool #8815.<br>Is the resistance below 5.0 ohms?<br><br>Yes → Repair the short to ground in the (V37) S/C Signal circuit.<br>Perform POWERTRAIN VERIFICATION TEST VER - 4.<br><br>No → Go To 7 | All |
| 7 | **NOTE: Before continuing, disconnect the PCM harness connector and check the related wiring terminals for corrosion, damage or terminal push out. Repair as necessary.**<br>Using the schematics as a guide, inspect the wire harness and connectors. Pay particular attention to all Power and Ground circuits.<br>If there are no possible causes remaining, view repair.<br><br>Repair<br>Replace and program the Powertrain Control Module per Service Information.<br>Perform POWERTRAIN VERIFICATION TEST VER - 4. | All |