P2096-DOWN STREAM FUEL TRIM LEAN BANK 1 — Continued

POSSIBLE CAUSES
GOOD TRIP EQUAL TO ZERO
EXHAUST LEAK
ENGINE MECHANICAL PROBLEM
O2 SENSOR
O2 SIGNAL CIRCUIT
O2 RETURN CIRCUIT
FUEL CONTAMINATION

TEST	ACTION	APPLICABILITY
1	**NOTE: Check the vehicle repair history. If the O2 has been replace ensure that the O2 sensor was properly installed and meets OEM specification.** **NOTE: Check for contaminants that may have damaged the O2 Sensor: contaminated fuel, unapproved silicone, oil and coolant.** Ignition on, engine not running. With the DRBIII®, read DTCs and record the related Freeze Frame data. Is the Good Trip Counter displayed and equal to zero? Yes → Go To 2 No → Refer to the INTERMITTENT CONDITION symptom in the Driveability category. Perform POWERTRAIN VERIFICATION TEST VER - 5.	All
2	Turn the ignition off. **WARNING: To avoid personal injury from the exhaust system being hot, allow the exhaust to cool down to a safe temperature before performing a physical inspection.** Visually and Physically inspect the for holes, cracks and blockage in the exhaust system. Is the exhaust system is good condition? Yes → Go To 3 No → Repair or Replace as necessary. Perform POWERTRAIN VERIFICATION TEST VER - 5.	All