## P0897-WORN OUT/BURNT TRANSAXLE FLUID — Continued

| TEST | ACTION | APPLICABILITY |
|---|---|---|
| 2 | Turn the ignition off.<br>Remove the Transmission Oil Pan and Oil Filter per the Service Information.<br>Install a new Transmission Oil Filter per Service Information.<br>Reinstall Transmission Oil Pan, and refill with new Transmission Fluid per the Service Information.<br>**Note: The Transmission Cooler must be flushed before prodceeding.**<br>Start the engine, check and adjust the Transmission Fluid Level per Service Information.<br>Allow the engine to idle for 10 minutes, in Park.<br>Flush the Transmission Oil Cooler per the Service Information.<br>Turn the ignition off.<br>Drain and refill the Transmission Fluid.<br>Flush the Transmission Oil Cooler again.<br>Start the engine, check and adjust the Transmission Fluid Level per Service Information.<br>With the DRBIII®, perform a Battery Disconnect.<br>**Note: This must be done to re enable EMCC during an A/C Clutch engagement.**<br>The vehicle may exhibit intermittent shudder during the first few hundred miles.<br>**Note: The oil will gradually penetrate the TCC friction material and the shudder should disappear.**<br>Erase the DTC and return the vehicle to the customer.<br>Did the Code reset or does the vehicle still shudder after a few thousand miles?<br>Yes → Replace the Torque Convertor per the Service Information. Perform 42RLE TRANSMISSION VERIFICATION TEST - VER 1.<br>No → Test Complete. | All |