P1776-SOLENOID SWITCH VALVE LATCHED IN LR POSITION — Continued

TEST	ACTION	APPLICABILITY
2	With the scan tool, check for other transmission DTC's Is the DTC P0841 present also? Yes → Refer to the Transmission category and perform the appropriate symptom. Perform 42RLE (NGC) TRANSMISSION VERIFICATION TEST - VER 1. No → Go To 3	All
3	With the scan tool, check the DTC EVENT DATA for P1776. Does the DTC EVENT DATA show a TRS Code of TR2? Yes → This indicates the shift lever and the manual control valve were in an invalid position between Neutral and OD. Check the shifter cable for: proper adjustment, binding, friction, improper routing, or the shifter was moved in transit. Repair as necessary. Perform 42RLE (NGC) TRANSMISSION VERIFICATION TEST - VER 1. No → Go To 4	All
4	With the scan tool, check the STARTS SINCE SET counter for P1776. **NOTE: This counter only applies to the last DTC set.** Is the STARTS SINCE SET counter 2 or less? Yes → Go To 5 No → Go To 11	All
5	Turn the ignition off to the lock position. **CAUTION: Removal of the Starter Relay is to prevent a Transmission, NO RESPONSE, condition and disable the starter.** Install the Transmission Simulator, Miller tool #8333 and the Electronic Transmission Adapter kit 8333-1A. Ignition on, engine not running. With the Transmission Simulator, turn the Pressure Switch selector switch to L/R. With the DRBIII® monitor the L/R Pressure Switch state while pressing the Pressure Switch Test button on the Transmission Simulator. Did the Pressure Switch state change from open to closed when the test button was pressed? Yes → Go To 6 No → Go To 7	All